124-5

FIRE SERVICE INCORPORATED 27006

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR	AREA'S		CABLE	XDUCER	SENS TEST	S/D
21	PASS ELEV.		1	020	2.8	BLK
	COMM A		1	204	3.0	BLK
	ELECT A		1	204	3.0	BLK
	TELEPH A		1	204	3.0	BLK
	FREIGHT ELEV.		1	020	3.0	BLK
	ELECT B		1	204	2.8	BLK
	COMM B		1	204	3.0	BLK
	TELEPH B		1	204	3.0	BLK
21	ELECT C		1	205	3.0	BLK
	COMM C		1	205	3.2	BLK
	TELEPH C		1	205	3.0	BLK
	TELEPH D		1	205	3.0	BLK
	COMM D		1	205	3.2	BLK
	ELECT D		1	205	3.0	BLK
21	CORE HER D/D		1	008	3.2	Hochiki
(C)	CORE HER D/D		1	008	8.2	Hochiki
	-TO BE REPLACE	(UNIT DEFECTIVE)				
21	RETURN D/D SOUTH		1	007	3.0	Hochiki
	RETURN D/D NORTH		1	007	3.2	Hochiki
13	STROBE PANEL AFC 101 (B COMM)					
	(2) BATTERIES REPLACED - (LOW)					
	TROUBLE / BATTERIES					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	FS-1.
	DATE SCHEDULED 8-22-01
CONTRACT # S/C00818	TYPE OF SYSTEM LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VOLTS BATTERIES	69.95

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING S/CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTOR CHECKS - SENSITIVITY TEST AS (SHOWN ABOVE) — LOCATIONS ON 21ST FL. — ALSO TROUBLE SHOOTER 21ST FL. DUCT DETECTOR CORE HER (1) FIRST TO BE REPLACED (SENSITIVITY OUT RANGE). — UNIT SIF24 HOCHIKI TYPE. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

:27007

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	AREA'S		CABLE	XTNDR	TST SENS	S/D
20	COMM A		1	203	2.8	BLK
	ELECT A		1	203	3.0	BLK
	TELEPH A		1	203	3.0	BLK
	ELEC B		1	203	3.0	BLK
	COMM B		1	203	3.0	BLK
	TELEPH B		1	203	3.2	BLK
	ELEV. PASS		1	019	3.0	BLK
	ELEV. FREIGHT		1	019	2.8	BLK
	—		—			
	COMM C		1	202	3.0	BLK
	ELEC C		1	202	2.8	BLK
	TELEPH C		1	202	3.0	BLK
	ELEC D		1	202	3.0	BLK
	COMM D		1	202	3.2	BLK
	TELEPH D		1	202	3.0	BLK
	CORE HEL D/D		1	006	3.2	HOLLOW
	CORE HEL D/D		1	006	3.2	HOLLOW
	RETURN D/D		1	005	3.2	HOLLOW
20	RETURN D/D		1	005	3.0	HOLLOW
	RETURN D/D EAST		3	045	3.2	D13
46	STROBE PNL 'B' COMM. Trouble					STATUS
	Repairing A CIRCUIT — AS F.S.D.					—
	PANEL RESTORED to NORMAL —					

INVOICE TO: 7W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 8-28-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LJN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean OKeeffe.

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT. — S/DETECTORS Check. Also Testing Sensitivity / Cleaning Semiannual Service. — Also Repaired on 46 Floor STROBE PNL AFC100 — 'A' Loop Circuit Corrected. — SYSTEM OK / RESETTED. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED 27064

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Area		CABLE	XMDR	S/D	TST SENS
23	PASS ELEV.		2	000	BLK	2.8
	COMM B		2	169	BLK	3.0
	ELECT B		2	169	BLK	3.0
	TELEPH B		2	169	BLK	3.0
	ELECT A		2	169	BLK	3.2
	COMM A		2	169	BLK	3.0
	TELEPH A		2	169	BLK	2.8
	FREIGHT ELEV		2	000	BLK.	3.0
	CORE HER D/D		2	228	Hochiki	3.2
23	CORE HER D/D		2	228	Hochiki	3.2
	ELECT C		2	168	BLK	3.0
	COMM C		2	168	BLK	3.0
	TELEPH C		2	168	BLK	3.2
	COMM D		2	168	BLK	3.0
	ELECT D		2	168	BLK	3.0
	TELEPH D		2	168	BLK	3.0
	RETURN D/D	LADIES	2	227	Hochiki	3.4
	RETURN D/D	NORTH	N/A - AS PREVIOUS			
23	RETURN D/D	SOUTH	N/A - AS PREVIOUS			
13	STROBE PNL TROUBLE CONDITION 101 Model CLEARED. - STATUS -					
14	SUB SYSTEM PNL TROUBLE - (UNIT IN TROUBLE / EXECUTIVE AREA - 14th FL) ZONE WIRES LIFTED TTB (15th FL) - (TB6 7-8)					
	TO RESTORE, SUPV. WIRES TTB WHEN SS(U) IS RESTORED TO NORMAL CONDITION					

INVOICE TO: WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torre / F. Rosario	F.S.D.
	DATE SCHEDULED 8-29-01
CONTRACT # 5/000818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME / DATE / NAME

SERVICE PERFORMED & REMAINING Sensitivity Test / Maintenance as per Contract on 23rd Fl (Silverstein Area BLD) - as listed above - Repairs on 13th / 14th Fl. Sub Systems — as per F.S.D.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

27065

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	CORRIDORS.		CABLE	XTNDR	S/D	TST SENS.
19	ELECT A		1	201	BLK	3.0
	COMM A		1	201	BLK	3.0
	TELEPH "A"		1	201	BLK	2.8
	ELECT B		1	201	BLK	2.8
	COMM B		1	201	BLK	3.0
	TELEPH B		1	201	BLK	3.0
				—		
	ELEV LBBY PASS		1	018	BLK	3.0
19	FREIGHT ELEV.		1	018	BLK	3.2
	ELECT C		1	200	BLK	3.0
	COMM C		1	200	BLK	2.8
	TELEPH C		1	200	BLK	2.8
	CORE HEL D/D		1	004	Hochiki	3.4
19	CORE HEL D/D		1	004	Hochiki	3.2
	PLENUM RETURN D/D		1	003	Hochiki	3.2
	PLENUM RETURN D/D		1	003	Hochiki	3.2
	ELECT D		1	200	BLK	3.0
	COMM D		1	200	BLK	3.0
	TELEPH D		1	200	BLK	3.0

(*) 47 WATERFLOW S/W 2 OHZ ALARM - CHECK / TROUBLESHOOTING DEVICE / TTB INPUT - DEVICE ISOLATED FROM TTB - TO BE MONITORED - (POSSIBLE DEFECTIVE S/W DEVICE)

(*) 14th SMOKE DAMPER SUBSYSTEM TROUBLE ... TRACED / CHECK - INTO A SUBSYSTEM CODE 042 IN TROUBLE STATUS / PANEL DISABLED FOUND SEVERAL ZONES DISMANTLED BY TENANT - (MOVE-OUT.) -

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torre; F. Rosario	F.S.D
	DATE SCHEDULED: 9-4-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): D. GIACOMAZZA
CUSTOMER SIGNATURE: [signature] 9/5/01
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

DATE	TIME	NAME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE / SMOKE DETECTOR UNITS SENSITIVITY CHECK ON 19th FL AS PER SCHEDULE AS LISTED AREAS
(*) ALSO CHECK / TROUBLESHOOTING FLOOR 47 W/FLOW (112) ALARM DEVICE ISOLATED FROM SYSTEM - TO BE MONITORED CLASS 'E' SYSTEM - TO BE FOLLOW UP. AND 14th FL SUBSYSTEM - TO BE RESTORE TO NORMAL BY TENANT (SOLOMON BROS.)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER
(INPUTS LIFTED ON TTB SYSTEM / UNTIL S.SYSTEM - RESTORE NORMAL STATUS

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

27066

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREAS			CABLE	XTNDR	S/D	TEST SENS
18	COMM	A		1	199	BLK	3.2
	ELECT	A		1	199	BLK	3.0
	TELEPH	A		1	199	BLK	3.0
	PASS	ELEV.		1	017	BLK	3.0
18	FREIGHT ELEV.			1	017	BLK	3.0
	ELECT	B		1	199	BLK	3.0
	COMM	B		1	199		2.8
	TELEPH	B		1	199		3.0
	ELECT	C		1	198	BLK	3.0
	TELEPH	C		1	198		3.2
	COMM	C		1	198		3.0
	ELECT	D		1	198	BLK	2.8
	COMM	D		1	198		2.8
18	TELEPH	D		1	198		3.0
	PLENUM	RETURN D/D-N		1	001	Hochiki	3.2
	PLENUM	RET. D/D	SOUTH	1	001	Hochiki	3.2
	CORE	HEL D/D		1	002	Hochiki	3.2
	CORE	HEL D/D		1	002	Hochiki	3.4
17	PASS	ELEV.		1	016	BLK	3.0
	FREIGHT	ELEV.		1	016	BLK	3.0
	ELECT	A-B	(2)	1	197	BLK	3.0/3.2
	COMM	A-B	(2)	1	197	BLK	3.0
	TELEPH	A-B	(2)	1	197	BLK	3.0/2.8
	CORE	HEL D/D		1	000	Hochiki	3.4
	CORE	HEL D/D		1	000	Hochiki	3.4
	ELECT	C		1	196		
	COMM	C		1	196		
	TELEPH	C		1	196		
	TELEP	D		1	196		
	COMM	D		1	196		
	ELECT	D		1	196		
17 FL (*)	RETURN D/D	NOT AVAILABLE AS					
	PREVIOUS	REPORTED					

INVOICE TO: 2 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED: J. Torres, F. Rosario
SEE AT JOB SITE: F.S.D
DATE SCHEDULED: 9-05-01
CONTRACT #: S/C 818
TYPE OF SYSTEM: LSN 2000 I
FEE SERVICE #: -
P.O. #
CALL AUHTORIZED BY | PHONE | EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): D GIACOMAZZI
CUSTOMER SIGNATURE: [signature] FSD 9/5/01
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: PREVENTIVE MAINTENANCE - CLASS E FIRE SYSTEM - SMOKE DETECTOR AREA ABOVE LISTED 18th/17th FLOOR'S SENSITIVITY TESTED. —

(*) NOTE RETURN D/DETECTOR NOT AVAILABLE - NO ACCESS PROVIDED CEILING SOLID - 17th FLOOR

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SEPVICE INCORPORAT=D   102313

SUBSIDIARY OF FIRE ... M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7 WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		09-05-01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

SERVICE DATE: 09-05-01

WILL RETURN ON:

I & T COMPLETE ☐   CALL COMPLETE ☐

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED

Service Maintenance

SERVICE PERFORMED

Assisting Jimmy T. on the performing of the Service Maintenance.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name [signature] 9/5/01   Date

FCI 155

FIRE SERVICE INCORPORATED

102312

SUBSIDIARY OF FIRE... INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 WTC
New York 1024.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	3C00818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		09-04-01	A.M.	Frank R

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 A.M.	9:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE 09-04-01

WILL RETURN ON

CUSTOMER SIGNATURE [signature] 9/5/01

SERVICEMAN SIGNATURE [signature]

PROBLEM—AS DESCRIBED

Service Maintenance

SERVICE PERFORMED

Assisting Jimmy T. on the performing of the service maintenance.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97685

SUBSIDIARY OF FIRE ALARM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		08/15/01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 08/15/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Soxette

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Tessa on the performing of AD Service Contract. Inspection, Test, Clean and Sensitivity of the Smoke Detectors on 24th Floor, etc.

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

X

FIRE SERVICE INCORPORATED

97687

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
710 T G
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	Sc00818				F.D.

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		08/22/01	AM.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 08/22/01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Attending [illegible] per the Agreement of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED 97688

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		08/21/01	AM.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE	CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 08/21/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Miguel Rivera

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting [illegible] in the [illegible] of the Service Contract!

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____________ Date ____________

FIRE SERVICE INCORPORATED

97689

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00818				F.S.I.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		8/29/01	A.M.			

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8/29/01

CUSTOMER SIGNATURE: Sean O'Keeffe

WILL RETURN ON:

SERVICEMAN SIGNATURE: [illegible]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy T. on the performing of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SEP'ICE INCORPORAT⁼D

97690

SUBSIDIARY OF FIRE...M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Sc00818				F. S. D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		8/28/01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
					PREVENTIVE MAINTENANCE CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 8/28/01
WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe
SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

[illegible] On the
Performing of the Service
Contract

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ______ Date ______

FIRE SERVICE INCORPORATED

23499

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREAS	CLOSET		XTNDR	CABLE	SENS	S/D
24	PASS	ELEV.		001	2	2.8	BLK
	FREIGHT	ELEV		001	2	2.8	BLK
	COMM	A CLOSET		171	2	3.0	BLK
	ELECT	A "		171	2	3.0	BLK
	TELEPH	A "		171	2	3.0	BLK
	COMM	B "		171	2	3.0	BLK
	ELECT	B		171	2	2.8	BLK
	TELEPH	B		171	2	3.0	BLK
24	ELECT	C		173	2	3.0	BLK
	COMM	C		173	2	3.2	BLK
	TELEPH	C		173	2	3.0	BLK
	ELECT	D		173	2	2.8	BLK
	COMM	D		173	2	3.0	BLK
	TELEPH	D		173	2	3.0	BLK
	RETURN	DUCT DET. NORTH		230	2	3.2	Hochiki
	RETURN	DUCT DET. SOUTH		230	2	3.2	Hochiki
	BREAKER D/D			231	2	3.2	Hochiki
25	BREAKER D/D			231	2	3.0	Hochiki

16 STROBE PNL Repairs AFC 100
A-B LOOPS - / BATTERIES NEEDED
(2) 12 VLTS. -
TO Replace. -

PREVENTIVE MAINTENANCE
CONTRACT

INVOICE TO: ZWTC.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED 8-15-01
CONTRACT # S/C00 818	TYPE OF SYSTEM ZSN2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM) PM	430 AM (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) S. O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING As per Contract — Preventive Maintenance on Smoke Detectors 24 Fl. - as listed above. Sensitivity Test Serviced All Areas / Closets - MER's - Elevator Lobbies. - System Are Ready Back To Operation. —
Also Repairs on 16 Fl AFC 100 Panel - as per F.S.D. Trouble / Ready (C) Needed (2) Batteries 12 VLTS. - To replace. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OT

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME
DATE X
TIME

FIRE SERVICE INCORPORATED

23500

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS Area's -			DEVICES Qty	Model	Test Sens	Cleaned
22	Elev/Lby			1	021	3.0	✓
	Elect A			1	207	3.2	✓
	Comm A			1	207	3.0	✓
	Teleph A			1	207	3.0	✓
	Teleph B			1	207	3.0	✓
	Elect B			1	207	2.8	✓
	Comm B			1	207	3.0	✓
22	Freight Elev			1	021	3.2	✓
	Elect C			1	206	3.0	✓
	Comm C			1	206	3.0	✓
	Teleph C			1	206	3.0	✓
	Teleph D			1	206	2.8	✓
	Elect D			1	206	2.8	✓
	Comm D			1	206	3.0	✓
	Return Duct Det. S.			1	009	3.2	✓
	Return D/D North			1	009	3.2	✓
	Core Mer D/D			1	010	3.0	✓
22	Core Mer D/D			1	010	3.2	✓

16 Strobe Panel (AFC 100) Core Mer. Replaced (2) Batteries 12 Volts. - Back up Pwr. -

44 Security (Solomon Brother's) Office Fan Unit Check for Operation/Running as per Request. -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
22nd Fl

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED 8-21-01
CONTRACT # S/COD 818	TYPE OF SYSTEM LSN 2001
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 Volts Batteries	69.95

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE: Miguel [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.
NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/Contract. —
Preventive Maintenance & Sensitivity Test Performed on Smoke Detectors Areas Above Listed on 22nd Floor's - (Silverstein Spaces) -
Also Performed Repairs on 16th Fl. (2) Batteries 12 Volts Replaced. - For Strobe Pnl AFC 100 - (Old Batt's Defective). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23498

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	Area	Closet		Cable	Ytnd	S/D	Sens Test
25	Pass Elev.			2	002	Brk	3.0
	Freight Elev.			2	002	Edwds	3.2
	Elect	B		2	174	Brk	3.0
	Comm	B		2	174	Blk	3.0
	Teleph	B		2	174	Blk	3.0
	Elect	A		2	174	Blk	3.0
	Comm	A		2	174	Blk	3.0
	Teleph	A		2	174	Blk	3.0
	Elect	C		2	173	Blk	3.0
	Comm	C		2	173	Blk	3.2
	Teleph	C		2	173	Blk	3.0
	Elect	D		2	173	Blk	3.0
	Comm	D		2	173	Blk	3.2
	Teleph	D		2	173	Blk	3.2
25	Core	Mer	Duct Det	2	233	Hochiki	3.2
	Core	Mer	Duct Det	2	233	Hochiki	3.4
	Return	Duct	Det	North	232	Hochiki	3.2
25	Return	Duct	Det	South	232	Hochiki	3.2

13 Strobe Pnl check for trouble/reset AFC 100 panel - adjusted output voltage at panel. -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 8-14-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☒ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): S. O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.
NAME DATE TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance - Sensitivity Test - Service Contract - on smoke detectors area/elevator's on 25 Floor as listed above. - Also repair on strobe panel 13 Fl 'B' Comm. closet AFC 100 as per F.S.D. - Request/BLD. - Trouble/Trouble reset. - Back to normal. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

103631

SUBSIDIARY OF FI... ...OM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY. NY.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Shop	SC# 818				7/3/01

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7/3/01	am / pm	

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☑ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 am	9:00 am	3:30 pm	4:30 pm					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7/03/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Mercado

SERVICEMAN SIGNATURE:

PROBLEM—AS DESCRIBED — Trouble call —

SERVICE PERFORMED Assisted technician Jimmy T.
For more information see report #
16th floor strobe panel & 46th floor elev. lobby det.
Trouble status repalrs.
System Operational

WORK REMAINING

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

97626

SUBSIDIARY OF FI. ... OM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7 W.T.C. – N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.W.	@818				F.S.D.

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-2-01	AM	J. Torres

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900	3:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-2-01

WILL RETURN ON:

CUSTOMER SIGNATURE: Mercado

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED: Repairs as per previous S/Contract Report. / Strobes.

SERVICE PERFORMED: S/Contract - Check Troubleshooted 39th Floor Strobe panel Defective Circuits 'A' - 'B' - Wiring check found (1) unit with reverse wiring wall type (Wheelock) on 'B' circuit / and loose E.O.L. on 'A' CKT - by Restroom's. - Circuits Rewired Back in Operation /
System Ack/Reseted Back in Operation

WORK REMAINING:

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

103630

SUBSIDIARY OF FI... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED: 7 WTC NY NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
Shop		60##				F/D
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		7/02/	am/pm			[signature]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☑ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 am	9:00 am	3:30 pm	4:30 pm					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 7/02/01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature] Mercod

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the ... service of the equipment.

PROBLEM—AS DESCRIBED: — Trouble call —

SERVICE PERFORMED: Assisted technician Jimmy. For more information see report #

System Operational

WORK REMAINING

FIRE SERVICE INCORPORATED

97625

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Scm 8B				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-27-2001	AM.			[signature]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE 06-27-2001

WILL RETURN ON

CUSTOMER SIGNATURE Sean O'Keef[e]

SERVICEMAN SIGNATURE [signature]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy [Tapper] on the performing of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

FIRE SERVICE INCORPORATED

97623

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, NY.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-26-2001	AM.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-26-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

[illegible] in the performance of the Service Contract.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ______ Date ______ X

FIRE SERVICE INCORPORATED 97624

SUBSIDIARY OF FIR[illegible] M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, NY.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	SC00818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		06-25-2001	A.M.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 A.M.	9:00 A.M.	3:30 P.M.	4:30 P.M.					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-25-2001

CUSTOMER SIGNATURE: Sean O'Keeffe

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Raphael Vadgarro in the installation of the New LP-40 Audio Printer in 44th Floor Security Office and Downloading the System at the F.C.S. and also Assisting Jimmy Fiore Moving the Panel from 44th Floor Down to 4th Floor

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97617

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		Sc00818				F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-20/2001	A.M. -			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-20-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Time Warner On the Proforming of the Service Contract

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23496

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			W/STA	SPK	STRB	M/STA
34	TENANT SPACE			✓	✓	✓	ACTIV
						BATTERIES	
33	TENANT SPACE			✓	✓	✓	ACTIV.
						(1) LIGHT OUT	
32	TENANT SPACE.			✓	✓	✓	ACTIV.
31	TENANT SPACE.			✓	✓	✓	ACTIV.
-						(1) LIGHT OUT	
30	TENANT SPACE.			✓	✓	✓	ACTIV.
29	TENANT SPACE.			✓	✓	✓	ACTIV.
28	TENANT SPACE.			✓	✓	✓	ACTIV.
27	TENANT SPACE.			✓	✓	✓	ACTIV.
26	TENANT SPACE.			✓	✓	✓	ACTIV.
34	CONF. 'B' STROBE PNL (101) - TAKE. REPAIRED REPLACED (2) 12 VLT BATTERIES						

INVOICE TO: 7 W.T.C. SILVERSTEIN PROP. N.Y.C (SLOMON BARNEY)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 6-20-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - CHECK/TESTED AS per BLD ACCESS / TENANT AUDIO/COMMUNICATION / SPEAKERS PAGE - STROBES LIGHTS - W/STATIONS. - ON FLOOR'S (ABOVE LISTED). - SYSTEM ACK/RESET.

(*) NOTE: to Repair (1) Strobe Light on 33rd Fl. by Mail Rm. - 31st Fl (1) Strobe Light to repair by File Room. - To Follow up. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by deactivating the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

97619

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
TWTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
	S000818				F.S.D.

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		06-19-2001	A.M.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-19-2001
WILL RETURN ON:
CUSTOMER SIGNATURE: Sean O'Keeffe
SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lassa on the performing of the Service Contract.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23495

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				W/STA	SPKR	STROBE	H/STA ACTIV.
48	PLANT			✓	✓	✓ = REP.	✓
47	TENANT SPACE			✓	✓	✓ - (1) OUT	✓
46	TENANT SPACE.			X	✓	✓ - ½ CKT	✓
45	TENANT SPACE			X	✓	✓	✓
44	TENANT SPACE			✓	✓	✓	✓
43	TENANT SPACE			✓	✓	✓	✓
42	TENANT SPACE			✓	✓	✓	✓
41	TENANT SPACE			✓	✓	✓	✓
40	TENANT SPACE			✓	✓	✓	✓
39	TENANT SPACE			✓	✓ (1) OUT 'B' STAIR	X OUT	✓
38	TENANT SPACE			✓	✓	✓	✓
37	TENANT SPACE			✓	✓	✓	✓
36	TENANT SPACE			✓	✓	✓	✓
35	TENANT SPACE			✓	✓	✓	✓

INVOICE TO:
7 W.T.C.
SILVERSTEIN. PROP.
N.Y.C.
(SD/OHAW [illegible] TENANT)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED 6-19-01
CONTRACT # SC 00818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:30 AM	9:00 AM	4:30 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of the contracted work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O-Keeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING SERVICE CONTRACT. AS PER BLDG ACCESS / TENANT
PROCEEDED to CHECK / TESTING OF: WARDEN'S STATIONS. SPEAKERS PAGE
AUDIO / COMMUNICATIONS AND STROBES LIGHTS ACTIVATION ON FLOOR'S. AS (LISTED ABOVE)
SYSTEM ACKNOWLEDGED - ACTIVATION / RESETS. -
NOTE: for REPAIR TO FOLLOW UP ON FLOOR'S 48' STROBE PNL UPDATE - 47 FL (1) SPK OUT / STROBE
46' FL. STROBES LIGHT CKT (A) OUT. - 39' FL SPK OUT 'B' STAIR AREA / STROBE ACTIV. - OUT. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 97615

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, NY.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		S000818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-13-2001	A.M.			Frank

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-13-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank [signature]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

[illegible] [illegible] [illegible] Per the
Performing of the Service Contract

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

FIRE SERVICE INCORPORATED

23494

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR				CABLE	XMDR	S/D	CLEAN TEST
3rd	WEST MER			3	006	PEC3T	✓
	WEST MER			3	006	PEC3T	✓
	SECURITY CLOSET			3	048	PEC3	✓
	DUCT DET KITCHEN			3	042	EDWDS	✓
	(SUPPLY CEILING PLENUM)						
3rd	W. MER D/D FAN			3	040	EDWDS	✓
	W. MER D/D FAN			3	040	EDWDS	✓
	W. MER D/D FAN			3	040	EDWDS	✓
	W. MER. D/D FAN			3	041	EDWDS	(*)
(*)	(INSTALLED S/D) — UNIT REPLACED OLD N/G						
3rd	CONF. AREA			1	077	DI-3	✓
	RECEPT. AREA			1	077	DI-3	✓
	ELEV LBBY			3	029	PEC3	✓
2	FAN RM D/D			1	014	EDWDS	✓
2	ELEV. LBBY			3	028	PEC3	✓
2	ELEV. LBBY			3	005	PEC3T	✓
1st	PLANT MER D/D			3	039	EDWDS	✓
1st	PLANT MER D/D			3	037	EDWDS	✓
1st	PLANT MER ~~PLEN~~			1	012	PEC3T	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. (Solomon Smith Barney) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 6-13-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LW 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 (AM)	430 (PM)	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Miguel Rivera
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: As per contract. Test maintenance on smoke detection class E system in areas floors 3rd 2nd 1st BS (listed above). — System ack / reset / back to open.
(*) NOTE: W.M.ER. D/D (041) unit replaced / wired. (old defective N/G)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

Unit supplied by Bldg.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

23493

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S . CLOSET'S		CABLE	XTNDR	S/D	TST CLEAN
5	PASS ELEV.		1	004	BLK	✓
	FREIGHT		1	004	BLK	✓
	ELECT A		1	169	BLK	✓
	TELEPH A		1	169	BLK	✓
	ELECT B		1	169	BLK	✓
	COMM B		1	169	BLK	✓
	ELECT C		1	169	BLK	✓
	ELECT F		1	169	BLK	✓
	ROTO	CLONE AREA	3	013	PEL3T	✓
	ROTO	CLONE AREA	3	013	PEL3T	✓
4	ELECT B		1	167	BLK	✓
	TELEPH B		1	167	BLK	✓
	COMM B		1	167	BLK	✓
	TELEPH A		1	167	BLK	✓
	ELECT A		1	167	BLK	✓
	ELECT G		3	050	PEL3	✓
	MAIN	PASS ELEV.	1	003	BLK	✓
	FREIGHT ELEV.		1	003	BLK.	✓
	CHEF'S OFF. D/D		3	043	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
(Solomon Smith B.)

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. DORAN	F.S.D.	
	DATE SCHEDULED 6-12-01	
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000	
FEE SERVICE #	P.O. #	
CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	ALARM'S LOG'S BOOKS	45 Each
4	12 VLTS BATTERIES (STROBE'S PANEL'S)	69.95 EACH

CUSTOMER NAME (PRINT) [signature]
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING S/CONTRACT. S/DETECTORS ON FLOOR'S 5 + 4th. - (Solomon Brothers / Smith Barney) AREAS - CLOSET'S AS LISTED. - UNITS TESTED / CLEANED. - SYSTEM ACK / RESETED. -
(*) ALSO DELIVERED (2) ALARM'S LOG'S BOOK'S AS REQUESTED F.S.D. / BLD. -
- (4) BATTERIES TO BE REPLACED AT STROBE PNL'S (BACK UP PWR). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SE~VICE INCORPORA~ED

97668

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		S000818				FSI
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-12/2001	AM.			Frank R

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:00 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-12-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Firing House on the performance of the Service Contract. Also Replacing Batteries and Alarm Books for 7WTC

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

X

Name | Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23492

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S			CABLE	XTNDR	S/D	TST CLEANED
26	ELECT	A		2	176	BLK	✓
	COMM	A		2	176	BLK	✓
	TELEPH	A		2	176	BLK	✓
	COMM	B		2	176	BLK	✓
	ELECT	B		2	176	BLK	✓
	TELEPH	B		2	176	BLK	✓
	PASS ELEV.		(003)	2	003	BLK	✓
	COMM	C		2	175	BLK	✓
	ELECT	C		2	175	BLK	✓
	TELEPH	C		2	175	BLK	✓
	ELECT	D		2	175	BLK	✓
	COMM	D		2	175	BLK	✓
	TELEPH	D		2	175	BLK	✓
	FREIGHT ELEV		(003)	2	003	BLK	✓
	CORE HER D/D.			2	235	SIF24	✓
	CORE HER D/D.			2	235	SIF24	✓
	RETURN D/D NORTH			2	234	SIF24	✓
	RETURN D/D South			2	234	SIF24	✓
26	RET. D/D LADIES RM			NO ACCESS. –			
	BLD TO PROVIDE FUTURE. – NEXT. –						

44th Preaction PNL/TROUBLE – TERMINATION AT TTB (45th FL) (LIFTED – WIRES) due to MULTIPLY TROUBLE/ALARM'S – SUB CONTRACTOR TO CHECK SUB SYSTEM PREACTION PNL. – REPAIRED – – TO RESTORE WIRED SUPV. – WHEN Complete –

INVOICE TO: 7 W.T.C. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. ROSARIO	F.S.D.
	DATE SCHEDULED 6-6-01
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) [illegible]
CUSTOMER SIGNATURE [illegible]
SERVICEMAN SIGNATURE [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Service Contract – Prev Maintenance & Repairs on Listed Device. – Smoke Detector Alarm's Serviced on 26th Fl. Area closets Elev Lobbies Main F.C. Station Alarm's Acknowledged – Reset Properly. – System Back in operation. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE

FIRE SE[illegible]VICE INCORPORA[illegible]ED

97667

SUBSIDIARY OF FI[illegible]COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		Sc00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-04-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-06-2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting [illegible] [illegible] [illegible] the performing of the Service Contract.

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______

FIRE SE⌐VICE INCORPOR⌐ED

97666

SUBSIDIARY OF FI... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00318				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-04-2001	A.M.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
						PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 A.M.	900 AM	330 P.M.	430 P.M.					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-04-2001

CUSTOMER SIGNATURE: James Cayzylen

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Forzz on the testing of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

84035

SUBSIDIARY OF F[illegible] M INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC.
Emergency Service.

SUNDAY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Service.	Sc 818				FSD- Angel

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		22 April 2001		Newell

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				CONTRACT TROUBLE CALL		

CHECK APPROPRIATE BOX

☐ O.C ☐ EMERGENCY CALL
☐ I&T ☐ CONTRACT CALL
☐ FEE CALL ☐ PICK UP
☐ DELIVERY ☐ DEMO OWNER
☐ DEMO ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
930	1045	1100	1200	4.00				

☐ MAT REQD ☐ PARTIAL
☐ OTHER ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 22 April 2001

WILL RETURN ON:

CUSTOMER SIGNATURE: x [signature] Mercado

SERVICEMAN SIGNATURE: [signature] Newell

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name | Date

PROBLEM—AS DESCRIBED

Emergency Service.

SERVICE PERFORMED 930 rcvd beep. Contact service and customer. Customer reports FCS lite up 8500 Interface board trouble. Need service ASAP. 10:45 arrived at jobsite. Met with Security / FSD Checked F.C.S. 76 Trouble (6) supv (0) ASBL. Checked trouble list. 8500 IF # 240 in trouble and sub nodes. Reset 8500 IF - Trouble reset, However F.C.S. display locked up in trouble restart System. Performance checked F.C.S. -OK (65) Trouble (6) Supv. Fire Alarm system back on line. Call completed.

WORK REMAINING

FCI 155

FIRE SERVICE INCORPORATED

97664

SUBSIDIARY OF FI[illegible]COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		Sc00818				FSD
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-30-01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 05-30-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

[illegible handwriting] Per the [illegible] of the Service [illegible].

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23485

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				CABLE	XTNDR	TEST CLEAN	S/D
29	PASS	FREIGHT	(2)	2	006	✓	BLK
	ELECT	A-B	(2)	2	182	✓	BLK
	TELEPH	A-B	(2)	2	182	✓	BLK
	COMM	A-B	(2)	2	182	✓	BLK
	ELECT	D.W		2	181	✓	BLK
	ELECT	G/SEC	(2)	3	007	✓	PEC3
	ELECT	C-D	(2)	2	181	✓	BLK
	TELEPH	C-D	(2)	2	181	✓	BLK
	COMM	C		2	181	✓	BLK
	ELECT	F					
	SHUTTLE ELEV.			3	030	✓	PEC3
(3)	CORE	HER AREA	(3)	2	240	✓	PEC3T
(2)	CORE	HER D/D.	(2)	3	000	✓ SIF	[illegible]
	W. HER AREA		(2)	3	032	✓	EDWS
28	PASS	FREIGHT	(2)	2	005	✓	EDWS
	ELECT	A-B	(2)	2	180	✓	BLK
	COMM	A-B	(2)	2	180	✓	BLK
	TELEPH	A-B	(2)	2	180	✓	BLK
	ELECT	C-D	(2)	2	179	✓	BLK
	COMM	C-D	(2)	2	179	✓	BLK
	TELEPH	C	(1)	2	179	✓	BLK.
	ELECT	D.W.	(1)	2	179	✓	PEC3
	ELECT	F					
	ELECT	G		2	180	✓	PEC 3
(4)	SECURITY CLOSET	NO	S/D. —	NO WIRING EXISTING			
	SHUTTLE ELEV.			2	005	✓	PEC3
	CORE	HER. D/D.		2	239	✓	SIF 24
	CORE	HER D/D		2	239	✓	SIF 24
	W. HER	AREA	(3)	3	057	✓	PEC3T
	W. HER D/DET.			3	047	✓	DT-3

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
(Solomon Floor)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D.
	DATE SCHEDULED: 5-22-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8 AM	900 AM PM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Service Contract. Check/test clean S/detectors on Floor 29/28 Floor's areas all as listed. —
Note 29 Fl. Core Mec duct det. (1) unit & (1) area ceiling no safe access to maintenance/service due to high voltage riser power exposed by units. —
28 Fl. (Found) security closet with no S/D. protection as previous reported). —
System ack/reset back to operating/normal. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SF?VICE INCORPOR/?ED

84206

SUBSIDIARY OF Fi..COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-23-2001	A.M.			Frank P.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
					PREVENTIVE MAINTENANCE CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE 05-23-2001

WILL RETURN ON

CUSTOMER SIGNATURE Sean O'Kee

SERVICEMAN SIGNATURE Frank P.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Applying [illegible] on the Performing of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X ______ Date

FIRE SERVICE INCORPORATED

84207

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-22-2001	A.M. -			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE
CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-22-2001

CUSTOMER SIGNATURE: Sean O'Keefe

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Fox on the [illegible] of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ____________ Date ____________

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97660

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
	SC00818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		05-16-2001	AM.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-16-2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lurre [illegible]. In the performance of the Service Contract of Maintenance of the Smoke detectors and Duct detectors in the premises

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155

FIRE SERVICE INCORPORATED

23484

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR	AREA		CABLE	XTNDR	S/D	TST CLEAN
31	PASS/FREIGHT	(2)	2	008	BLK/D13	✓
	ELECT A-B	(2)	2	187	BLK	✓
	TELEPH A-B	(2)	2	187	BLK	✓
	COMM A-B	(2)	2	187	BLK	✓
	ELECT C-D	(2)	2	186	BLK	✓
	CONT/COMM D		2	186	BLK	
	CONT/D.W.		2	186	BLK	
	ELECT D.W.		2	186		
	ELECT 6/SEC	(2)	3	009	PEC 3	✓
	ELECT F		3	016	PEC 3	✓
	SHUTTLE ELEV		3	025	PEC 3	✓
	CORE HEX. AREA	(3)	2	244	PEC 37	✓
	CORE HEX D/D	(2)	2	245	SIF 24	✓
	W. HEX AREA	(2)	3	002	PEC 37	✓
	W. HEX D/D	(2)	3	034	EDWDS	✓
	N. SUPPLY CLOSET	(2)	2	186	BLK	✓
30	PASS/FREIGHT	(2)	2	007	BLK	✓
	ELECT A-B	(2)	2	184	BLK	✓
	COMM A-B	(2)	2	184	BLK	✓
	TELEPH A-B	(2)	2	184	BLK	✓
	ELECT C-D	(2)	2	183	BLK	✓
	TELEPH D/CONT		2	183	BLK	✓
	TELEPH C		2	183	BLK	✓
	COMM C		2	183	BLK	✓
	ELECT D.W.		2	183	BLK.	
	ELECT F		3	015	PEC 3	✓
	ELECT 6 SEC	(2)	3	008	PEC 3	✓
	SHUTTLE ELEV		3	024	PEC 3	✓
	CORE HEX AREA	(3)	2	242	PEC 37	✓
(*)	CORE HEX D/D	(2)	2	243	SIF 24	✓
	W. HEX AREA	(2)	3	001	PEC 37	✓
	W. HEX D/D	(2)	3	033	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.
J. Carrigan/F.S.D.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosillo	F.S.D.
	DATE SCHEDULED: 5-16-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component at the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE AS PER CONTRACT. - SMOKE DETECTORS (ABOVE LISTED) ON FLOOR'S 31 & 30 WERE TESTED & CLEANED. - CLASS E FIRE EQUIP - SYSTEM - ALARM'S/RESET'S ACKNOWLEDGED - OUTPUTS FUNCTION AS FIRE SIGN/FLOW PAGE FLOOR/ABOVE/SIGNAL ON/CENTRAL OFFICE - CHECK'S O.K TO BE CONTINUED -

30 FL (*) (1) DUCT DET. CORE HEX (2/243) N/ACCESS - HIGH VOLTAGE 'BUSS BARS' ON WAY/OBSTACLE

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 97659

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO:

SERVICED: 7 WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00 818				F.S.D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		05-15-2001				Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-15-2001

CUSTOMER SIGNATURE: James Cunnigan

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lives Leak. On the performing of the Service Contract of maintenance of the smoke detector and duct detector on the premises.

WORK REMAINING

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

23483

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	Area	Cable	Addr	S/D	Clean Test
32	Pass Elev	2	009	BRK	✓
	Elect A	2	190	BRK	✓
	Comm A	2	190	BRK	✓
	Teleph A	2	190	BRK	✓
	Elect B	2	190	BRK	✓
	Comm B	2	190	BRK	✓
	Teleph B	2	190	BRK	✓
	Freight Elev	2	009	BRK	✓
	Elect 'C'	2	189	BRK	✓
	Teleph C Cont	2	189	BRK	✓
	Comm C/Supply	2	189	BRK	✓
	Elect 'D'	2	189	BRK.	✓
	Teleph D Supply	2	189	BRK	✓
	Elect D.W	2	189	BRK	✓
	Elect F	3	017	PEC3T	✓
	Elect G	3	010	PEC3T	✓
	Security Closet	3	010	PEC3T	✓
	Shuttle Elev.	3	026	PEC3	✓
	Core HER Area	2	248	PEC3T	✓
	Core HER Area	2	248	PEC3T	✓
	Core HER Area	2	248	PEC3T	✓
	Core HER D/D	2	247	SIF24	✓
*	Core HER D/D	2	247	SIF24	—
	West HER Area	2	003	PEC3T	✓
	West HER Area	2	003	PEC3T	✓
	West HER D/D	3	035	EDW	✓
	West HER D/D	3	035	EDW	✓
42	Freight Elev. S/D – BRK Unit + Base Repaired – Back in Operation				

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.
Mr. Cherigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / F. Plano	F 59	
	DATE SCHEDULED 5-15-01	
CONTRACT # 5/C00818	TYPE OF SYSTEM LSN2000	
FEE SERVICE #	PO #	
CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING Preventive Maintenance as per Contract / Check / Test - Clean Smoke Detector Units / Class E System on 32nd Fl / all areas (as listed) –
(*) Note D/Detector Core HER Unit N/G / to replace or repair. –
Also as per Contract / Repaired / Freight Unit on 42nd Fl. – Base Defective Contacts Wiring Loose / Repaired O.K. – Back in Operation. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SFRVICE INCORPORATED 97658

SUBSIDIARY OF F... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		Scoo 818				F.S.D
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-14-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM.	9:00 AM	3:30 PM.	4:30 PM-					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-14-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Losse on the performing of the Service Contract

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

X

FIRE SERVICE INCORPORATED

23467

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS	DEVICES
FLOOR	
47	STROBE PNL AFC 100 CHECK - Replaced keylock (300 TYPE)
46	" "
45	STROBE PNL AFC 100 CHECK Replace (1) KEY LOCK (300 TYPE)
48	" "
13	Repairs on STROBE PNL AFC 101 PANEL. - Also check STROBE PNL #2 AFC 100 by 13 Pump. -
24	Fl. TAMPER S/W - Repair/Adj. Alarm status. -
30	Fl. TAMPER S/W - Adj/Repairs on Alarm status. -

TROUBLE CALL

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
Mr. J. Carrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D.
F. Rosario	DATE SCHEDULED: 5-14-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): J. Verstein
CUSTOMER SIGNATURE: James Carrigan
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/CONTRACT. Repairs on above Floor's as per F.S.D. - STATUS REPORT. - on Above LISTED. -
(+) Also ASISTED SOFTWARE Eng. FIRECOM on 6 Fl. ARCADE SYSTEM - FAN UNIT - STATUS -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97657

SUBSIDIARY OF F... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED

TWTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		Sc00818				F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-09-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 05-09-2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy [illegible] on the
performance of the Service Contract
[illegible] maintenance of the area
Smoke and Duct Detectors

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23482

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: AREA'S			DEVICES: CABLE	YTNDR	S/D	TST CLEAN
34	PASS/FREIGHT			2	011	BLK	✓
	ELECT	A-B	(2)	2	194	BLK	✓
	COMM	A-B	(2)	2	194	BLK	✓
	TELEPH	A-B	(2)	2	194	BLK	✓
	ELECT	C-D	(2)	2	193	BLK	✓
	ELECT	D.W.		2	193	BLK	✓
	ELECT	F		4	048	PEC3	✓
	ELECT FL/A.V. ROOM			4	043	PEC3	✓
	ELECT	S/SEC. (2)		4	072	PEC3T	✓
	TELEPH	C-D	(2)	2	193	BLK	✓
	MEDICAL DPT		AREA	2	193	BLK	✓
	SHUTTLE ELEV.			4	000	PEC3	✓
	CORE MER AREA (3)			2	252	PEC3T	✓
	CORE MER D/DET. (2)			2	251	EDWDS	✓
	W-MER AREA.			4	024	PEC3	✓
	W. MER D/DET.			4	096	EDWDS	✓
33	ELECT	A-B	(2)	2	191	BLK	✓
	COMM	A-B	(2)	2	191	BLK	✓
	TELEPH	A-B	(2)	2	191	BLK	✓
	ELECT/COMM 'C'		(2)	2	192	BLK	✓
	ELECT	D.W		2	192	BLK	✓
	ELECT	F		3	018	PEC3	✓
	ELECT	S/SECURITY (2)		3	011	PEC3	✓
	TELEPH/SUPPLY 'C'			2	192	BLK	✓
	TELEPH/CLST D			2	192	BLK	✓
	FREIGHT/PASS		(2)	2	010	BLK	✓
	SHUTTLE ELEV			3	027	PEC3	✓
	CORE MER AREA (3)			2	250	PEC3T	✓
	CORE MER D/D (2)			2	249	SIF24	✓
	W. MER	AREA	(2)	3	004	PEC3T	✓
	W. MER	D/D	(2)	3	036	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. (Solomon Brothers) N.Y.C.

SERVICEMAN ASSIGNED: J. Torres / J. Rosario

SEE AT JOB SITE: F.S.D.

DATE SCHEDULED: 5-9-01

CONTRACT #: S/C00818

TYPE OF SYSTEM: LS2000

FEE SERVICE #:

P.O. #:

CALL AUTHORIZED BY:

PHONE:

EXT:

☑ MAINTENANCE ☑ TEST

☑ JOB COMPLETE ☐ JOB INCOMPLETE

☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT / PREV MAINTENANCE SMOKE DETECTION ON FLOORS 34/33 AS LISTED ABOVE —
SYSTEM CLK/RESET BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97656

SUBSIDIARY OF F... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC New York, NY.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		05-08-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE 05-08-2001

CUSTOMER SIGNATURE [signature]

WILL RETURN ON

SERVICEMAN SIGNATURE Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lozzi on the inspection of the service contract of maintenance of the area smoke detectors and duct detectors.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FCI 155
REV 6186

FIRE SERVICE INCORPORATED 23481

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Area's		Cable	XTNDR	S/D	TST Clean
35	Elect	A	2	196	Blk	✓
	Comm	A	2	196	Blk	✓
	Teleph	A	2	196	Blk	✓
	Elect	B	2	196	Blk	✓
	Comm	B	2	196	Blk	✓
	Teleph	B	2	196	Blk	✓
	Pass/Freight (2)		2	012	Blk	✓
	Elect	G	4	073	Pec 3	✓
	Security Closet		4	073	Pec 3	✓
	Elect	C	4	049	Pec 3	✓
	Elect	D	4	049	Pec 3	✓
	Elect	F	4	049	Pec 3	✓
	Elect	F1	4	049	Pec 3	✓
	Shuttle Elev		4	001	Pec 3	✓
	W. Her Area		4	025	Pec 3	✓
	W. Her D/D		4	097	[illegible]	✓
42	TTB	Unit	Check's Terminal's			
39	TTB's	Unit	"		"	

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: W.T.C. (Solomon Smith Barney) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	FS-1
	DATE SCHEDULED: 5-8-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract / Prev. Maintenance on Smoke Detection Class E Fire Alarm Floor 35th (As Listed) All areas. — Also [illegible] Tech on 39/42nd Fl. For checks on input terminal's for Stop/Status Function Displays Floor's 40/41/42/43. — System left in good operation.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component as the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SF?VICE INCORPOR?TFD

84489

SUBSIDIARY OF F... , INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC NEW YORK
NEW . YORK

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	U.P.S 818				F.S.O

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5/4/01	AM	C. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900 AM	200 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 5-4-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: C. FORERO [signature]

PROBLEM—AS DESCRIBED PREVENTIVE MAINTENANCE / U.P.S SERVICE CONTRACT

SERVICE PERFORMED Arrived At Building, Checked U.P.S System, And Battery Racks (30 Batteries) Took Readings

TOTAL - BATTERY VOLTAGE = 139.8 Volts - A/DC
BATTERY AMP = .3 AMPS
L-1 = 11.3
L-2 = 10.9
INPUT - VOLTAGE = 208. A/C
246. A/C

WORK REMAINING Cleaned AND Checked U.P.S And Battery Racks, System ~~[crossed out]~~ (ON)

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

97655

SUBSIDIARY OF F... INC
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00518				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		5/2/2001	A.M.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5/2/2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech. Jimmy Lore
In the performing of the
Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23479

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		CABLE	XTNM	S/D	TST CLEAN
37	PASS/FREIGHT	(2)	2	014	BLK	✓
	SHUTTLE PASS E/L	✓	4	003	PEC 3	✓
	ELECT A-B	(2)	2	200	BRK	✓
	COMM. A-B	(2)	2	200	BRK	✓
	TELEPH A-B	(2)	2	200	BRK	✓
	ELECT C-D	(2)	2	199	BRK	✓
	ELECT D.W		2	199	BRK	✓
	ELECT "F" EAST		4	051	PEC 3	✓
	ELECT G/SEE	(2)	4	075	PEC 3	✓
	TELEPH C-D	(2)	2	199	BLK	✓
	COMM C		2	199	BRK	✓
	CORE HEL AREA	(3)	2/002	258	PEC3T	✓
	CORE HER D/D	(2)	2/001	257	HOCHIKI	✓
	W. HER AREA	(2)	4	027	PEC3T	✓
	W HER D/D	(2)	4	099	ENWDI	✓
36	ELECT A-B	(2)	2	198	BLK	✓
	COMM A-B	(2)	2	198	BK	✓
	TELEPH A-B	(2)	2	198	BRK	✓
	ELECT "F" EAST		4	050	PEC 3	✓
	ELECT D.W		2	197	BLK	✓
	ELECT G/SEE	(2)	4	074	PEC 3	✓
	ELECT C-D	(2)	2	197	BLK	✓
	TELEPH C-D	(2)	2	197	BRK	✓
	COMM/STORAGE C		2	197	BK	✓
	PASS/FREIGHT ELEV	(2)	2	013	BRK	✓
	SHUTTLE ELEV. PASS		4	002	PEC 3	✓
WEST	~~CORE~~ HER D/D		4	098	ENWDI	✓
WEST	~~CORE~~ HEL D/D		4	098	ENWDI	✓
WEST	~~CORE~~ HER AREA	(3)	4	026	PEC3T	✓
	CORE HER D/D		2	255	SIF24	✓
	CORE HER D/D		2	255	SIF24	✓
	CORE HER AREA	(3)	2	000	PEC3T	✓

INVOICE TO: 7W.T.C. Solomon Brothers Realty N.Y.C.

SERVICEMAN ASSIGNED: J. Torres	SEE AT JOB SITE: F.S.D
	DATE SCHEDULED: 5-2-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: CSN2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/contract - Doing Maintenance on floors 37/36th (Solomon Realty Bonney) All area/closets/elev. lobby/mech rm - smoke detector with EX listed above -- System all reset announciation at F.C.S. -- back in operation --

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

FIRE SERVICE INCORPORATED 97654
SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NYC

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	SC00818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5/1/2001	AM.	Frank R

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 5/1/2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech: Timer Fire
See the performing of the service
Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______ X

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23478

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	AREAS		CABLE	XTND?	S/D	TST CLEAN
40	ELECT A		2	207	BLK	✓
	COMM A		2	207	BLK	✓
	TELEPH A		2	207	BLK	✓
	ELECT B		2	207	BLK	✓
	COMM B		2	207	BLK	✓
	TELEPH B		2	207	BLK	✓
	PASS/FREIGHT ELEV (2)		2/	017	BLK	✓
	ELECT C		2	208	BLK	✓
	COAT/COMM C		2	208	Apllo	✓
	TELE/STORAGE C		2	208	Apllo	✓
	ELECT D		2	208	BLK	✓
	TELE/STORAGE D		2	208	Apllo	✓
	COMM/STORAGE D		2	208	Apollo	✓
	CORE MED D/D		2	015	Apllo	✓
	CORE MED D/D		2	015	Apllo	✓
	CORE AREA CEILING		2	208	Apllo	✓
	CORE AREA CEILING		2	208	Apollo	✓
(*)	ELECT 'F' MISSING/NO S/D DETECTOR					—
	SECURITY CLOSET		4	078	PEC3	✓
	ELECT 'G'		4	078	PEC3	✓
	FILE RM		2	208	Apllo	✓
	FILE RM		2	208	Apllo	✓
LOBBY	F.C. STATION REPAIR DCM 40/DISPLAY #16					
	PURGE/PRESS FLOORS					
18	TTB REPAIR ON 795 MOTHER BOARD					
	& REPLACED (2) 792 P.C.'s BOARDS - DEFECTIVE					
	FOR REPAIR ON PURGE/PRESSURIZATION ON					
	18th FL. —					

INVOICE TO: 7 W.T.C (SOLOMON SMITH BARNEY) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.I
	DATE SCHEDULED: 5-1-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	792 P.C. BOARDS	
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTORS ON 40 FL (SOLOMON) ALL ELEC'L CLOSET'S / ELEVATOR LOBBIES / STORAGE & MACHINE RM'S / CORE MED'S AS LISTED. —
(*) NOTE: "F" ELECT CLOSET S/D NOT EXISTING - MISSING. —
(*) ALSO PERFORMED REPAIR/REPLACING BOARDS ON 18 FL TTB / PURGE / PRESS. FAN OPER.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

23480

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREA'S			CARD	XTNDL	S/D	T/S CLEAN
41	ELECT A			2	209	BLK	✓
	COMM A			2	209	BLK	✓
	TELEM A			2	209	BLK	✓
	COMM B			2	209	BLK	✓
	ELECT B			2	209	BLK	✓
	TELEM B			2	209	BLK	✓
	PASS ELEV.			2	018	BLK	✓
	FREIGHT ELEV			2	018	BLK	✓
	COMM/COAT C			2	195	Apllo	✓
	ELECT C			2	195	Apllo	✓
	TELEM C			2	195	Apllo	✓
	CORE HER	D/D		2	016	Apllo	✓
	CORE HER	D/D		2	016	Apllo	✓
	CORE AREA HEL.			2	019	Apllo	✓
	CORE AREA HEL.			2	019	Apllo	✓
	ELECT G			4	079	FEC3T	✓
	SECURITY CLOSET			4	079	FEC3T	✓
	SHUTTLE ELEV			4	007	FEC3	✓
46	STROBE PANEL AFC 100 / 'A' CKT OR - SHORT (2) BATTERIES 12 VLT REPLACED.						
39	STROBE PNL AFC 100 / (2) BATTERIES 12 VLT REPLACED - PNL UPDATE MODIF -						
18	PURGE / PRESS. FAN / ACTIVATION TROUBLESHOOTING / REPAIRS -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. Solomon Smith Barney N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. ROSARIO	J.S.	
	DATE SCHEDULED: 4-30-01	
CONTRACT #: 5/C00818	TYPE OF SYSTEM: LSN 2000	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
900 AM	900 AM	5:30 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	792 P.C. BOARDS	385
4		

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE AS PER CONTRACT ON 41st FLOOR SMOKE DETECTORS AREAS / ELEV. LOBBIES AS LISTED ABOVE. - AND REPAIRS ON DEFECTIVE OR MALFUNCTION ON STROBES PANELS 46th FL & 39th FL - REPLACED DEFECTIVE BATTERIES LOW OUTPUT VOLTAGE - (4) UNITS 12 VLT. AND TROUBLESHOOTED / STATUS PROBLEM WITH 18th FL PURGE / PRESSURIZATION FAN UNIT - (2) 792 P.C. REPLACED - NEEDS TO REPAIR 795 BOARD PANEL TTB / DATA CONTROL S/W. - SYSTEM OK / RESET BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 97653

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC NYC

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
	SC00818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		4/30/2001	A.M.	Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 4/30/2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED Service Contract

SERVICE PERFORMED

Assisting Tech. Jimmy Fosse due to the performing of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____ Date ____

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23473

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CABLE	XTNDR.	S/D	TST CLEAN
37	E.H.R. AREA (X2)		1	201	BLK	✓
	CAR'S 16-20					
31	E.H.R. AREA		1	188	BLK	✓
	CAR'S 13-14-15 (X2)					
31	E.H.R DUCT DET		2	246	SIF24	✓
	E.C.R					
31	E.H.R AREA		1	188	BLK	✓
	E.H.R DUCT DET. E.C.R		2	246	SIF24	✓
	CAR'S 11-12					
30	E.H.R AREA (X2)		1	185	BLK	✓
	CAR'S 13-14-15					
30	EHR AREA		1	185	BLK	✓
	CARS 11-12					
16	E.H.R AREA EAST		1	195	BLK	✓
16	E.H.R AREA EAST		1	195	BLK	✓
16	E.H.R D/D EAST		1	254	EDWARDS	✓
16	EHR AREA WEST		1	195	BLK	✓
16	EHR DUCT DET. WEST		1	254	EDWARDS	✓
15	E.H.R AREA EAST		1	192	BLK	✓
15	E.H.R AREA EAST		1	192	BLK	✓
15	E.H.R AREA WEST		1	192	BLK	✓
3RD	SHUTTLE ELEV SHAFT		3	049	PE3	✓
2ND	EHR H.E. 3+2		3	005	PE3T	✓
23	EHR AREA (X2)		1	170	BLK	✓
	EHR D/D		2	229	SIF24	✓

INVOICE TO: W.T.C. / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Pofran	F.S.I.
	DATE SCHEDULED: 4-28-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: CSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	7:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature] (Alvarez)

SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING: S/C CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTION, SHAFT'S - AS LISTED - ASSISTED BY OTIS MECH ELEV HOIST WAY'S (SHAFT'S) - ALSO REPAIR (1) D/D EHR - 31ST FL REWIRED ALSO AT BASE UNIT - BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

94445

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		S000818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		04-28-2001	A.M.	Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
					PREVENTIVE MAINTENANCE CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	7:00 A.M.	3:30 P.M.						

- ☐ MAT RECD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR RECD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 04-28-2001

CUSTOMER SIGNATURE: [signature] (Ahmed)

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature] Frank [illegible]

PROBLEM—AS DESCRIBED Service Contract

SERVICE PERFORMED

Assisting [illegible] during the performance of the Service Contract of [illegible] of the [illegible] and [illegible] inside of EMR and Staff elevators. See Service Report #23473

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of the assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

X

FIRE SERVICE INCORPORATED

97652

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C. -
Silverstein Prop. -
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
E.T.		S/C 00 818				F.S.D.
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		4-25-01	AM			G. Torres

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			Batteries 12 VLT (Strobe Pnl)	6995		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	4:30						
	AM	PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 4-25-01

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Repair Strobe Panel's - Various Floor's Also to check Purge Fan 18th Fl. N/G. - As per F.S.D. -

SERVICE PERFORMED Performed Repair on Strobes Panel's - Trouble's / Troubleshooting Replaced (6) Set's of 12 VLTS Batteries on Floors 7th - 8th - 39th Floors and Traced / Troubleshooting panel on 46th Fl. Strobe pnl. - Circuit #2 listing due to High Resistance - Trouble Condition. - Circuit hose activating / Trace unit defective Panel back on line. - Also check / Troubleshooting 18th Fl. Purge Unit not Lacking on Alarm Condition at F.C. Station Display / as well Dissimilating 17 + 19th Fl. - Further check's leads to also Malfunction on Purging 17 & 19th Floor's. - Check TTB's on 18th Fl. Inputs O.K. / PCI 792 Replaced / Problem persisting / F.C. Station

WORK REMAINING Power Download / ~~[illegible]~~ - Purging 1&3 still defective. - Program to be check / 8500 I.F. Unit at Console. -

(A) Also Arcade Unit (Fan's) on 6th Fl Not Displaying Current Event's Account Billing. - Showing Acc Billing - | Run Time Error 3021 | NO CURRENT RECORD

Notified Marty on Eng / Dale's Dept

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

94436

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00818				F-S D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		4/25/01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

SERVICE DATE: 4/25/01

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

I & T COMPLETE ☐ CALL COMPLETE ☐

PROBLEM—AS DESCRIBED Service Contract

SERVICE PERFORMED Assisting Tech. Tino Torres on the repairs of Strobe Panels on 7th floor, 8th floor, 39th and 46th floors. Also on the replacing of Batteries on 7th, 8th and 39th floors. Also assisting on the checking of Purge and Pressurization of the 18th floor. See Service Report # 97452.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23476

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	AREAS			CABLE	XTNDR	S/D	TEST CLEAN
42	PASS	FREIGHT	(2)	2	019	BRK	✓
	ELECT	A-B	(2)	2	211	BRK	✓
	COMM	A-B	(2)	2	211	BRK	✓
	TELEPH	A-B	(2)	2	211	BRK	✓
	SUPPLY	'C'		2	210	Apollo	✓
	TOWER	'C'		2	210	Apollo	✓
	ELECT	C		2	210	Apollo	✓
	COAT	D		2	210	Apollo	✓
42	CORE	HEL AREA (2)		2	212	Apollo	✓
42	CORE	HEL D/D (2)		2	017	Apollo	✓
	SHUTTLE	ELEV. PASS		4	008	PEC3	✓
	ELECT	D		2	210	Apollo	✓
	COAT/STORAGE 'D' - TTB			2	210	PEC3	✓
42	G	ELECT/SEC. (2)		4	080	PEC3	✓
43	PASS	FREIGHT	(2)	2	020	BRK	✓
	ELECT	A-B	(2)	2	213	BRK	✓
	TELEPH	A-B	(2)	2	213	BRK	✓
	COMM	A-B	(2)	2	213	BRK	✓
	COMM	C-D	(2)	2	212	BRK	✓
	TELEPH	C-D	(2)	2	212	BRK	✓
	ELECT	C-D	(2)	2	212	BRK	✓
	CORE	HEL AREA	2	2	253	Apollo	✓
	CORE	HEL D/D	2	2	018	Apollo	✓
	ELECT	G		4	081	BRK	✓
43	SECURITY			4	081	PEC3T	✓
	SHUTTLE	ELEV. PASS		4	009	PEC3	✓
43	F ELECT	NO S/D	IN	PREMISES. —			

INVOICE TO: 7 W.T.C. (SOLOMON BROTHERS) N.Y.C. -

SERVICEMAN ASSIGNED: J. TORRES
SEE AT JOB SITE: F.S.D.
DATE SCHEDULED: 4-24-01
CONTRACT #: S/C00818
TYPE OF SYSTEM: LSN 2000
FEE SERVICE #:
P.O. #:
CALL AUTHORIZED BY: | PHONE: | EXT:

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	BATTERIES 12 VOLTS (STROBE PNL'S)	69.95

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT):
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT PREV MAINT. ON SMOKE DETECTION ON FLOOR'S 43 & 42ND AT LISTED ABOVE. - DEFICIENCY BATTERIES. 42ND FL. FREIGHT ELEV. UNIT - POOR SENS. NEED TO BE REPLACED TO CONTINUE. - SYSTEM BACK IN OPERATION - 43RD FL (4) F ELECT CLOSET - S/D MISSING / NEED UNIT TO BE WIRED / INSTALLED.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(3) BATTERIES TO BE REPLACED ON 7 & 8TH FL. - STROBE PNL'S. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SER'ICE INCORPORAT'D

94437

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
ZWTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		4/24/01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 4/24/01

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank Repasi

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______ X

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech Jimmy Torres On the
Performing of the Service Contract
Of Cleaning and Testing of the Area
Smoke Detectors and Duct Detectors
On #32nd and #22nd Floors
See Service report #25476.

WORK REMAINING

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

77450

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N-Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Sc0818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		4/21/01	AM-			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	7:AM	33PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 4/21/01

CUSTOMER SIGNATURE: [signature] (Ackman)

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank Parisi

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tommy Torres Tech. on the cleaning and testing of the smoke and heat detectors in the elevator motor rooms and elevator shafts from 48th floor down to 43rd floor.
See report #23475

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23475

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES CABLE	XTNDR	S/D	CLEAN TEST
48	ROOF	E.HR	CAR 31	2	226	BAK	✓
47	SHUTTLE	ELEV. SHAFT		4	037	PEC3T	✓
47	SHUTTLE	ELEV. SHAFT		4	037	PEC3T	✓
47	E.H.R	AREA	CAR'S 29-30	2	224	BAK	✓
47	ELEV. SHAFT	CAR 44/47		4	037	PEC3T	✓
	BANK	H-SHUTTLE					
47	E.HR	CARS	21-28	2	220	BAK	✓
47	E.HR	AREA	21-28	2	220	BAK	✓
47	E.H.R	AREA	21-28	2	220	BAK	✓
47	EHR	AREA	21-28	2	220	BAK	✓
47	EHR	AREA	21-28	2	220	BAK	✓
47	EHR	AREA	21-28	2	220	BAK	✓
46	KITCHEN	SHUTTLE	CAR 38	4	036	PEC3T	✓
	SHAFT	BANK K —	(PIPE)				
46	FREIGHT SHUTTLE	HKE-1 AREA. EHR	CAR 38				
	BANK I	—		4	036	PEC3T	✓
47	E.H.R	AREA -	32-33	4	067	PEC3T	✓
46	E.H.R	H.KE1 AREA		4	065	PEC3T	✓
	CAR'S 2-3						
46	E.H.R	HKE-1	-AREA	4	066	PEC3	✓
	BANK J	CAR 37					
46	SHAFT	SHUTTLE	CAR 37	4	036	PEC3T	✓
	BANK J	CAR 37					
43	E.H.R	AREA	61-2	4	064	PEC3	✓
	CAR'S	34-35	BATH	ENT./LADIES -			

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED SAT 4-21-01
CONTRACT # S/C 00818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	7:30 AM	3:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE AHMED

SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTION SYSTEM / UNITS BY ELEVATOR'S SHAFTS & ELEV. MOTOR RM'S ASSISTED BY OTIS MECH (BOB) - UNITS CLEANED / CLEAN TESTED MONITORED / RESET AT F.C. STATION OUTPUTS - NORMAL - SYSTEM BACK IN OPERATION. — TO BE CONTINUE

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 23474

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	AREA'S.			CABLE	XMTR	S/D	TEST ALARM
38	W. HER. AREA.			4	028	PEC 3T	✓
	W. HER. D/D.			4	0100	Hochiki	✓
	ELECT	A-B	(2)	2	202	BLK	✓
	TELEPH	A-B	(2)	2	202	BLK	✓
	COMM	A-B	(2)	2	202	BLK	✓
	ELECT	C		2	203	BLK	✓
	ELECT	D		2	203	BLK	✓
	ELECT	D.W.		2	203	EDWARDS	✓
	ELECT	F		4	052	PEC 3	✓
	ELECT	G		4	076	PEC 3	✓
	SECURITY			4	076	PEC 3	✓
	PASS/FREIGHT ELEV. (2)			2	015	BLK	✓
	ELEV. SHUTTLE			4	004	PEC 3	✓
	CORE HER AREA (3)			2	004	PEC 3T	✓
	CORE HER D/D		(2)	2	005	Hochiki	✓
	W. HER AUDTM AREA			4	046	PEC 3T	✓
	W. HER D/D AUDTM			4	127	EDWARDS	✓
39	ELECT	A-B	(2)	2	205	BLK	✓
	COMM	A-B	(2)	2	205	BLK	✓
	TELEPH	A-B	(2)	2	205	BLK	✓
	ELECT	C		2	204	BLK	
	ELECT	D.W		2	204	BLK	
	ELECT	DF		2	053	PEC 3	
	ELECT	'G'		4	077	PEC 3	
	SECURITY CLOSET			4	077	PEC 3	
	ELECT	D1		2	204	BLK	
	FREIGHT/PASS ELEV (2)			2	016	BLK	
	ELEV. SHUTTLE			4	005	PEC 3	
	RECP. CEILING D/D (2)			2	254	Apollo	
	RECEP. CEILING D/D/SDZ (3)			2	254	Apollo	
	CORE HER AREA		(3)	2	006	PEC 3	
	CORE D/DET.		(2)	2	007	Hochiki	
	W. HER AREA			4	029	PEC 3T	
	W. HER. D/D.			4	101	EDWARDS	

INVOICE TO: 7. W.T.C.
(SOLOMON/SMITH BARNEY)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES C. TABARES	F.S.D.
	DATE SCHEDULED 4-18-01
CONTRACT # S/C 00818	TYPE OF SYSTEM CSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM / PM	800 AM	4:30 PM	AM / PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [illegible]

SERVICEMAN SIGNATURE: [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: SERV. CONTRACT - PREV. MAINT. SMOKE DETECTION (SOLOMON) FLOOR'S 39 + 38 AS LISTED ALL AREA CLOSET'S. SYSTEM ACK/RESET'S. - AT F.C. STATION. - BACK TO NORMAL OPERATION. -

(*) ALSO CHECK AS PER F.S.D. STROBE (PNL) 7 + 8 FL. TROUBLE CONDITION. - TAKEN TO LOW BATTERIES 12VLT/7AMH. TO BE REPLACED (2) SET'S. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 23470

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				Cable	XTNDR	S/O	TST Chan
44	Elect	A		2	215	BLK	✓
	Comm	A		2	215	BLK	✓
	Teleph	A		2	215	BLK	✓
	Pass	Elev.		2	021	BLK	✓
	Elect	B		2	215	BLK	✓
	Comm	B		2	215	BLK	✓
	Teleph	B		2	215	BLK	✓
44	Freight	Elev.		2	021	BLK	✓
	Elect	G		4	082	PEC3	✓
	Security	Closet		4	082	PEC3	✓
	Shuttle	Elev.		4	010	PEC3	✓
	Shuttle	Elev.		2	018	PEC3	✓
	West	Fan Rm	D/D	4	112	EDWDS	✓
	West	Fan Rm	Area	4	034	PEC3T	✓
44	Elect	F		4	058	PEC3	✓
2nd	Elect	D		1	163	BLK	✓
2nd	Front	Ent - High	Ceiling	1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	Front	Ent	Escalators	1	163	BLK	✓
	•	•	•	•	•	•	•
2nd	Hallway	Display	Lobby	1	163	BLK	✓
	"	"	"	1	163	BLK	✓
2nd	Fan Rm	East	D/D	1	270	Hochiki	✓
1st	Freight	Elev.		1	000	PEC3	✓
	Pump Rm		(2)	1	160	BLK	✓
	Elect	A		1	160	BLK	✓
	Trash Rm	Storage		1	160	PEC3T	✓
	Handicap	Elev	Lobby	1	000	BLK	✓
1st	Low Ceiling	Lobby	(2)	1	161	BLK	✓
1st	Elect	D		1	161	BLK	✓

INVOICE TO: 7 W.T.C. Prop. / Silverstein Prop. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	FS
	DATE SCHEDULED: 4-11-01
CONTRACT #: SK00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☒ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM / PM	8:00 AM	4:30 PM	AM / PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING

Service Contract / Prev. Maintenance Smoke Detection Units on 44 Fl and 2nd / 1st Fl. Lobbies as listed above (Silverstein Area). — Used of "Genie Boom" to reach High Ceiling Lobby Entrance. — System Just Reset Back to Operation. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

23468

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREA'S	CABLE	XTNGR	S/D	TSI CLEAN
47	STAIR 'A' - ELEV.	2	024	BLK	✓
	ELEV. SHUTTLE	4	016	PEC 3T	✓
	SECURITY CLOSET	4	085	PEC 3	✓
	ELECT 'G'	4	085	PEC 3	✓
	ELECT A	2	222	BLK	✓
	ELECT B	2	222	BLK.	✓
	ELECT 'C'	2	223	BLK	✓
	ELECT F	4	061	PEC 3	✓
	TELEPH B	2	222	BLK	✓
	'B' STAIRWAY/LANDING	2	221	EDWDS	✓
	TELEPH A	2	222	BLK	✓
	COMM D	2	223	BLK	✓
	CUSHMAN OFFICE AREA	4	113	EDWDS	✓
	SHAFT VERTICAL CONV.	4	068	EDWDS	✓
	W. MER	4	069	EDWDS	✓
	W. MER D/D 47-1	4	115	EDWDS	✓
	CORE MER D/D	2	023	[illegible]	✓
	CORE MER AREA (3)	2	022	PEC 3	✓
46	FREIGHT ELEV. LBBY	2	023	BLK	✓
	ELEV. SHUTTLE 'F'	4	014	PEC 3	✓
	ELEV. SHUTTLE 'H'	4	015	PEC 3	✓
	KITCHEN SHUTTLE ELEV	4	013	PEC 3	✓
	ELECT 'G'/SEC. (2)	4	084	PEC 3	✓
	ELECT B	2	219	BLK	✓
	COMM B	2	219	BLK	✓
	ELECT A	2	218	BLK	✓
	COMM A	2	218	BLK	✓
	TELEPH A	2	218	BLK	✓
	TELEPH D	2	219	BLK	✓
	ELECT D	2	219	BLK	✓
	COMM D	2	219	BLK	✓
	CORE MER D/D (2)	2	021	[illegible]	✓
	CORE MER AREA (3)	2	020	PEC 3	✓
	ELECT F	4	060	PEC 3	✓
	ELECT C	2	219	PEC 3	✓

INVOICE TO: 2 W.T.C. Silverstein Prop. N.Y.C.

SERVICEMAN ASSIGNED: J. Torres / F. Rosario

SEE AT JOBSITE: T.S.

DATE SCHEDULED: 4-10-01

CONTRACT #: 5/C00 818

TYPE OF SYSTEM: LSN 2000

FEE SERVICE #:

PO #:

CALL AUHTORIZED BY:

PHONE:

EXT:

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - PREV. MAINTENANCE SMOKE DETECTION CHECKS - CLASS E SYSTEM - ON FLOOR'S 47-46 - AREAS/LOCATIONS AS LISTED ABOVE. - EQUIP/ACK/RESET PROPERLY. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

23465

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S			S/D	CASE	YTNGR	TEST CLEAN
6	SWITCHGEAR	VAULT		BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	HIGH VOLTAGE VAULT			BRK	1	171	✓
6	High Voltage	VAULT	(x4)	BRK	1	171	✓
	"	"	" (4)	BRK	1	171	✓
	"	"	" (4)	BRK.	1	171	✓
5	H.V. VAULTS	(x6)		BRK	1	170	✓
5	H.V. VAULTS	(x6)		BRK	1	170	✓
5	SWITCH GEAR		NORTH	BRK	1	170	✓
	SWITCH GEAR		NORTH	BRK	1	170	✓
	SWITCH GEAR		NORTH	BRK	1	170	✓
5	SWITCH GEAR		SOUTH	BRK	1	170	✓
	SWITCH GEAR		SOUTH	BRK	1	170	✓
18	CORE HEL STROBE PNL AT 101 No. #2 (2) Batteries Replaced/exch. Trouble Unit back in order						✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7W. T.C. Silverstein Prop. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D.
	DATE SCHEDULED: 4-4-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LW 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLT PAN (STROBE PNL)	69.95

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN'S SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection system by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING

Prev. Maintenance Smoke Detection Silverstein Area Only on 6th / 5th Fl. As Listed (High Voltage Vault - Escort Needed) Also Repairs done on 18th Fl Strobe Pnl. - (101) Batteries Replaced) O.K.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23466

REPORT OF FIELD SERVICE

LOCATIONS	DEVICES				
FLOOR	AREA'S.	Cable	XTMTR	S/D	TEST
3rd	Hallway Top Escalator	1	166	BLK	✓
	Hallway Top Escalator	1	166	BLK	✓
	Tele A	1	166	BLK	✓
	Comm A	1	166	BLK	✓
	Elect A	1	166	BLK	✓
	Comm B	1	166	BLK	✓
	Comm/Tele B	1	166	BLK	✓
3	Freight Elev Lbby	1	0021	BLK	✓
	Pass Elev. Lbby (43-44)		002	BLK	✓
	Elev. Min Rise (22-28)	1	166	BLK	✓
	Elev. High Rise (36-45)	1	166	BLK	✓
	Elev Min Rise (22-28)	1	0021	BLK	✓
	(Repair / Reset's Tampers)				
45	Tamper S/W	2	147		✓
	Alarm / Reseted. Adjusted				
42	Tamper S/W	2	139		✓
	Alarm / Reseted Adjusted.				
40	Tamper S/W	2	137		✓
	Trouble / Repaired (Wiring Broken)				
37	Tamper S/W	2	134		✓
	Alarm / Reseted Adjusted.				
20	Tamper S/W	2	143		✓
	Alarm / Reseted / Adjusted	—			

INVOICE TO: 7W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	7-S-0
	DATE SCHEDULED: 4-3-01
CONTRACT #: SC00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Service Contract Preventive Maintenance on Smoke Unit's Floor's 3rd (Silverstein Area) - Only. - Also Adjusted / Alarm Reseted on Tamper S/W on Flor (Listed Above) B Riser only - DSKTJ). - Unit Back on Service. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

11842

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREAS/CLOSETS	CABLE	XTNDR	S/D	TS/CLEAN
23	PASS ELEV.	2	000	BRK	✓
	COMM B	2	169	BRK	✓
	ELECT B	2	169	BRK	✓
	TELEPH B	2	169	BRK	✓
	ELECT A	2	169	BRK	✓
	COMM A	2	169	BRK	✓
	TELEPH A	2	169	BRK	✓
	CORE MEN D/D.	2	228	Hochiki	✓
	CORE MEN D/D	2	228	Hochiki	✓
	ELECT C	2	168	BRK	✓
	COMM C	2	168	BRK	✓
	TELEPH C	2	168	BRK	✓
	FREIGHT ELEV	2	000	BRK	✓
	COMM D	2	168	BRK	✓
	ELECT D	2	168	BRK	✓
	TELEPH D	2	168	BRK	✓
	RETURN D/D LADIES	2	227	Hochiki	✓
*	RETURN D/D NORTH	N/A — AS PREVIOUS			
*	RETURN D/D. SOUTH (SILVERSTEIN AREA)	N/A — AS PREVIOUS			
5	FAN RM - STEAM RM D/D	1	223	Hochiki	✓
5	FAN RM DUCT DET.	1	224	Hochiki	✓
5	FAN RM D/DET.	1	228	Hochiki	✓
5	FAN RM D/DET	1	267	Hochiki	✓
	AS REQUEST / MARTY = SILVERSTEIN / D. CAMPBELL. SOLOMON				
32	CHECK / TEST AUDIO VISUAL / ALARM DEVICES				
33	" " " "				
	AS MR CAMPBELL REQUEST / P.A. TEST.				
	audibility (DECIBELS) INTENSITY. —				

INVOICE TO: 2 W.T.C. Prop. SILVERSTEIN PROP. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.I.
	DATE SCHEDULED: 3-28-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe

CUSTOMER SIGNATURE: [illegible]

SERVICEMAN SIGNATURE: [illegible]

SERVICE PERFORMED & REMAINING: S/CONTRACT — PREV. MAINTENANCE ON SMOKE DETECTION SYSTEM - CLASS 'E' DEVICES LOCATED BY CLOSET'S AREA CORE MEN'S / DUCT UNIT - ELEVATOR LOBBYES AS LISTED. — ALSO ASSISTED BUILDING / SOLOMON BATHES REQUEST P.A. TEST AUDIO VISUAL ALARM'S ON 32/33 FLOORS — AS REQUESTED MR. ED CAMPBELL — NOTIFY SYSTEM ACK/RESETTED PROPERLY. — (POINT OUT)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection service during their service of the equipment.

NAME

DATE

TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

27005

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	Area/Class			Cable	XMDR	S/D	TEST
10	Elect	A		1	181	BLK	✓
10	Comm	A		1	181	BLK	✓
10	Teleph	A		1	181	BLK	✓
10	Comm	B		1	181	BLK	✓
10	Elect	B		1	181	BLK	✓
10	Teleph	B		1	181	BLK	✓
10	Pass/Freight		(2)	1	009	BLK	✓
10	Elect	C		1	180	BLK	✓
10	Comm	C		1	180	BLK	✓
10	Teleph	C		1	180	BLK	✓
10	Teleph	D		1	180	BLK	✓
10	Elect	D		1	180	BLK	✓
10	Comm	D		1	180	BLK	✓
10	Core	Her	(2)	1	241	Hochiki	✓
10	Return	D/D	(3)	1	240	Hochiki	✓
9	Elev.	Pass		1	008	BLK	✓
9	Comm	A		1	179	BLK	✓
9	Elect	A		1	179	BLK	✓
9	Teleph	A		1	179	BLK	✓
9	Elect	B		1	179	BLK	✓
9	Comm	B		1	179	BLK	✓
9	Teleph	B		1	179	BLK	✓
9	Freight	Elev		1	008	BLK	✓
9	Elect	C		1	178	BLK	✓
9	Comm	C		1	178	BLK	✓
9	Teleph	C		1	178	BLK	✓
9	Elect	D		1	178	BLK	✓
9	Comm	D		1	178	BLK	✓
9	Teleph	D		1	178	BLK	✓
9	Return	D/D	South	1	238	Hochiki	✓
9	Return	D/D	North	1	238	Hochiki	✓
9	Return	D/D	East	1	238	Hochiki	✓
9	Core	Her	D/D	1	239	Hochiki	✓
9	Core	Her	D/D	1	239	Hochiki	✓

INVOICE TO: 7 W.T.C. / Silverstein Prop. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 3-27-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

DATE — TIME — NAME

SERVICE PERFORMED & REMAINING: S/Contract - Preventive Maintenance Smoke Detectors Built on Floor's 9 & 10 / Areas Above Listed. - System OK / Detecting properly. - (Print out). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 27004

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO: 7 WTC
New York, N.Y.

LOCATIONS			DEVICES			
FLOOR	Areas		Cable	Trans	S/D	Test Clean
7TH	Comm A		1	175	BRK	✓
	Elect A		1	175	Edwards	✓
	Teleph A		1	175	BRK	✓
	Pass Elev		1	006	BRK	✓
	Freight Elev		1	006	BRK	✓
	Comm B		1	175	BRK	✓
	Elect B		1	175	BRK	✓
	Teleph B		1	175	BRK	✓
	Comm C		1	174	BRK	✓
	Elect C		1	174	BRK	✓
	Teleph C		1	174	BRK	✓
	Comm D		1	174	BRK	✓
	Elect D		1	174	BRK	✓
	Teleph D		1	174	BRK	✓
	Core MER		1	222	Hochiki	✓
	Core MER		1	235	"	✓
	Return North D/D		1	234	"	✓
	Return South N/A		—	—	—	—
6TH	Pass Elev		1	005	BRK	✓
	Freight Elev		1	005	BRK	✓
	Comm A		1	172	BRK	✓
	Elect A		1	172	BRK	✓
	Teleph A		1	172	BRK	✓
	Comm B		1	172	BRK	✓
	Elect B		1	172	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room D/D		1	231	Hochiki	✓
	Fan Room D/D		1	229	Hochiki	✓
	Fan Room D/D		1	232	Hochiki	✓
	Fan Room D/D		1	233	Hochiki	

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank K / Marcos D	F.S.D.
	DATE SCHEDULED: 03-21-01
CONTRACT #: SC00818	TYPE OF SYSTEM: LSH 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE: Frank [signature] Marcos Claudio

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notifications of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during that service of the equipment.
NAME DATE TIME

SERVICE PERFORMED & REMAINING: Preventive Maintenance
See all Smoke and Duct Detectors Located see 7th & 6th floors. Performing Satisfactorily.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11840

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Areas		Cable	S/D	Type	Test Clean
8	Elev	Lobby	1	BRK	007	✓
			1			
"	Freight Elev		1	BRK	007	✓
"	Elect	A	1	BRK	177	✓
"	COMM	A	1	BRK	177	✓
	Teleph	A	1	BRK	177	✓
"	COMM	B	1	BRK	177	✓
"	Elect	B	1	BRK	177	✓
"	Teleph.	B	1	BRK	177	✓
"	COMM	C	1	BRK	176	✓
"	Elect	C	1	BRK	176	✓
"	Teleph	C	1	BRK	176	✓
"	Com	D	1	BRK	176	✓
"	Elect	D	1	BRK	176	✓
"	Teleph.	D	1	BRK	176	✓
"	Return D/D North		1	Hochiki	236	✓
"	Return D/D South		N/A	—	—	—
"	Return D/D East	(File)		Hochiki	236	✓
"	Core	MER D/D	1	Hochiki	237	✓
"	Core	MER D/D	1	Hochiki	237	✓

Note: Removed of a BRK Detector on 21st Floor Electric Closet AND Replaced with a New One. Hochiki Detector. Report Made By JAY.

INVOICE TO: 7WTC
New York, N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank K. / Jay	F.S.D.
	DATE SCHEDULED 03-20-01
CONTRACT # Scc0818	TYPE OF SYSTEM LSH 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING Preventive Maintenance
As per contract cleaned and tested elevator lobby detectors, and detectors and duct smoke detectors on 8th Floor. All devices tested are working properly.
System is operational

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11839

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CODE	XNDR	S/D	TEST
11'	COMM B		1	182		✓
	ELEC B		1	182		
	TELEPH B.		1	182		
	FREIGHT ELEV.		1	010	BAK	✓
	ELEC A		1	182		
	COMM A		1	182		
	TELEPH A		1	182		
	PASS ELEV.		1	010		
	COMM C		1	183		
	ELEC C		1	183		
	TELEPH C		1	183		
	TELEPH D		1	183		
	ELEC D		1	183		
	COMM D		1	183		
11'	CORE HER D/D		1	243	HOCHIKI	✓
	CORE HER D/D		1	243	HOCHIKI	✓
	RETURN D/D North		1	242	HOCHIKI	✓
	RETURN D/D SOUTH		1	242	HOCHIKI	✓
12'	STROBE PNL AFC 101 (2) PANEL'S					
	North SIDE UNIT REPAIRED. — B COMM.					
	(12VDC BATTERY Replaced) — Clear.					
1	B STAIR [illegible] (1-126) Repairs/Adj.					
	Check OK. —					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. — SILVERSTEIN PROP. — N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / A. ZINGER	F.S.D.
	DATE SCHEDULED: 3-14-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
1	12VDC BATTERIES	

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.
NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT. PREV. MAINTENANCE ON SMOKE DETECTOR DETECTORS INSIDE AREA CLOSETS AS (LISTED) ON 11' FLOOR. — ALSO REPAIRS ON 12' FL. STROBE PNL & 1'ST FL [illegible] S/W. — SYSTEM ACK/RESET BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11838

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA			Loop?	XTNDR	S/D	TEST
13	ELEV. PASS			1	012	BLK	✓
	FREIGHT ELEV			1	012	BLK	✓
	COMM A-B	(2)		1	186	BLK	✓
	ELECT A-B	(2)		1	186	BLK	✓
	TELEPH A-B	(2)		1	186	BLK	✓
	CORE MECH D/D			1	247	HOCHIKI	✓
	CORE MECH D/D			1	247	HOCHIKI	✓
	PLENUM D/D	NORTH		1	246	HOCHIKI	✓
	PLENUM RET D/D	SOUTH		1	246	HOCHIKI	✓
	COMM C-D	(2)		1	187	BLK	✓
	ELECT C-D	(2)		1	187	BLK	✓
	TELEPH C-D	(2)		1	187	BLK	✓
12	PASS ELEV.			1	011	BLK	✓
	ELECT A-B	(2)		1	184	BLK	✓
	TELEPH A-B	(2)		1	184	BLK	✓
	COMM A-B	(2)		1	184	BLK	✓
	FREIGHT ELEV			1	011	BLK	✓
	CORE MECH D/D			1	245	HOCHIKI	✓
*	CORE MECH D/D (LED)			1	245	HOCHIKI	✓
	RETURN D/D	NORTH		1	244	HOCHIKI	✓
	RETURN D/D	SOUTH		1	244	HOCHIKI	✓
	COMM C			1	185	BLK	✓
	ELECT C			1	185	BLK	✓
	TELEPH C			1	185	BLK	✓
	TELEPH D			1	185	BLK	✓
	COMM D			1	185	BLK	✓
	ELECT D			1	185	BLK	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 3-13-01
CONTRACT #: 5/COO 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	400 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Open (Routine) Manual (?) 8500 (?) Smoke Detection System (?) Class-E / As listed above (?) floors 13 + 12 all areas (?) — Semi annually (?)

(*) NOTE: Core Mech D/D (L.E.D.) Replacement required (?) Unit O.K. (?)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE X
TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

14546

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S.		Cable	Addr	S/D	TST Clean
15	PASS/FREIGHT	(2)	1	014	BLK	✓
	COMM. B-A	(2)	1	190	BLK	✓
	ELECT B-A	(2)	1	190	BLK	✓
	TELEPH B-A	(2)	1	190	BLK	✓
	CORE HER D/D Supply		1	251	Hochiki	✓
	CORE HER D/D Supply		1	251	Hochiki	✓
	COMM C		1	191	BLK	✓
	ELECT C		1	191	BLK	✓
	TELEPH C		1	191	BLK	✓
	TELEPH D		1	191	BLK	✓
15	COMM D		1	191	BLK	✓
	ELECT. D		1	191	BLK	✓
	RETURN DUCT North		1	250	Hochiki	✓
(A)	- DUCT South		NO ACCESS	-		—
14	COMM A-B	(2)	1	188	BLK	✓
	ELECT A-B	(2)	1	188	BLK	✓
	TELEPH A-B	(2)	1	188	BLK	✓
	PASS ELEV./FREIGHT (2)		1	013	BLK	✓
	CORE HER D/D		1	249	Hochiki	✓
	CORE HER D/D		1	249	Hochiki	✓
	TELEPH C		1	189	BLK	✓
	ELECT C		1	189	BLK	✓
	COMM C		1	189	BLK	✓
	TELEPH D		1	189	BLK	✓
	ELECT D		1	189	BLK	✓
	COMM D		1	189	BK	✓
14	RETURN D/D South		1	248	Hochiki	✓
	" D/D North		NO ACCESS	/ As Previous		

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
Silverstein Prop.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres F. Rosario	F.S.I.	
	DATE SCHEDULED: 3-07-01	
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Service Contract - Prev. Maintenance on Smoke
(1) Detectors Units on Floor's 15 / 14 Floor Areas Above Listed
(A) NOTE: Units on 15/14 " Return Duct Units not accessable / As previous listed. - Bldg Notified
System Ack / Reseted. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22383

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO: 7 W.T.C.
N.Y.C.

LOCATIONS FLOOR	AREAS			DEVICES Cab	XTNDC	S/D	TST Clean
17	PASS ELEV			1	096	BLK	✓
	ELECT	A		1	197	BLK	✓
	COMM	A		1	197	BLK	✓
	TELEPH	A		1	197	BLK	✓
	COMM	B		1	197	BLK	✓
	TELEPH	B		1	197	BLK	✓
	ELECT	B		1	197	BLK	✓
	CORE	HER.		1	000	Hochiki	✓
	CORE	HER.		1	000	Hochiki	✓
	FREIGHT ELEV.			1	016	BRK	✓
	ELECT	C		1	196	BRK	✓
	COMM	C		1	196	BLK	✓
	TELEPH	C		1	196	BLK	✓
	COMM	D		1	196	BRK	✓
	ELECT	D		1	196	BRK	✓
	TELEPH	D		1	196	BRK.	✓
(*)	PLENUM RETURN (NO ACCESS SOLID CEILING) - AS PREVIOUS REPORTED N/A. -						
16	PASS	FREIGHT (2)		1	015	BLK	✓
	COMM	A-B (2)		1	193	BLK	✓
	ELECT	A-B (2)		1	193	BLK	✓
	TELEPH	A-B (2)		1	193	BLK	✓
	CORE	HER D/D (1)		1	253	Hochiki	✓
	CORE	HER D/D (1)		1	253	Hochiki	✓
	COMM	C		1	194	BLK	✓
	ELECT	C		1	194	BLK	✓
	TELEPH	C		1	194	BRK	✓
	TELEPH	D		1	194	BRK	✓
	COMM	D		1	194	BRK	✓
	ELECT	D		1	194	BRK.	✓
	PLENUM RET D/D NORTH.			1	252	Hochiki	✓
(+)	PLENUM RET. D/D SOUTH N/A NO ACCESS SOLID CEILING AS PREVIOUS REPORTED TO BLD. -						

SERVICEMAN ASSIGNED: J. TORRES, F. ROSARIO

SEE AT JOB SITE: F.S.D.

DATE SCHEDULED: 3-6-01

CONTRACT #: S/C00818

TYPE OF SYSTEM: 8500

FEE SERVICE #:

P.O. #:

CALL AUTHORIZED BY:

PHONE:

EXT:

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
PREVENTIVE MAINTENANCE CONTRACT		

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: PERFORMED SERVICE ON SMOKE DETECTION UNITS ON FLOOR'S 17TH & 16TH FL. ALL AREAS (ABOVE LISTED) - SYSTEM OK/RESET AS OPERATIONAL. -

* NOTE: 17TH FL. RETURN UNIT NO ACCESS AS PREVIOUS -
(+) 16TH FL NO ACCESS SOUTH RETURN UNIT AS PREVIOUS REPORTED. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22382

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		Cable	XTNDR	S/D	TST Clean
19	Elev. Lbby		1	018	BLK	✓
	Elect B		1	201	BLK	✓
	Comm B		1	201	BLK	✓
	Teleph B		1	201	BLK	✓
	Comm A		1	201	BLK	✓
	Elect A		1	201	BLK	✓
	Teleph A		1	201	BLK	✓
	Freight Lbby		1	018	BLK	✓
	Comm C		1	200	BLK	✓
	Elect C		1	200	BLK	✓
	Teleph C		1	200	BLK	✓
	Elect D		1	200	BLK	✓
	Comm D		1	200	BLK	✓
	Teleph D		1	200	BLK	✓
19	Core HGR.	(2)3D	1	004	Hochiki	✓
	Return D/D	(2)	1	003	Hochiki	✓
18	Elect A		1	199	BLK	✓
	Comm A		1	199	BLK	✓
	Teleph A		1	199	BLK	✓
	Pass Elev.		1	017	BLK	✓
	Elect B		1	199	BLK	✓
	Comm B		1	199	BLK	✓
	Teleph B		1	199	BLK	✓
	Freight Elev.		1	017	BLK	✓
	Comm C		1	198	BLK	✓
	Elect C		1	198	BLK	✓
	Teleph C		1	198	BLK	✓
	Comm D		1	198	BLK	✓
	Elect D		1	198	BLK	✓
	Teleph D		1	198	BLK	✓
	Return Duct North		1	001	Hochiki	✓
18	Return Duct South		1	001	Hochiki	✓
	Core HGR Duct		1	002	Hochiki	✓
	Core HGR D/D		1	002	Hochiki	✓

INVOICE TO: 7 W.T.C.
Silverstein Prop.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres E. Rosario	F.S.D.
	DATE SCHEDULED: 2-28-01
CONTRACT #: SKC00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/ Contract - Prev. Maintenance on Smoke Detectors Class E System on Areas / Floors 19/18th as listed above System Chk / Devices Functions outputs

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22381

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S			Cable	XTNGR	TST CLEAN	S/D
21	Pass Elev.			1	020	✓	BLK
	Freight Elev.			1	020	✓	BLK
	Comm	A		1	204	✓	BLK
	Teleph	A		1	204	✓	BLK
	Elect	A		1	204	✓	BLK
	Elect	B		1	204	✓	BLK
	Comm	B		1	204	✓	BLK
	Teleph	B		1	204	✓	BLK
	Elect	C		1	205	✓	BLK
	Comm	C		1	205	✓	BLK
	Teleph	C		1	205	✓	BLK
	Core	HER	Supply Duct	1	008	✓	Hochiki
	Core	HER	Supply Duct	1	008	✓	Hochiki
	Teleph	D		1	206	✓	BLK
	Elect	D		1	206	✓	BLK
	Comm	D		1	205	✓	BLK.
21	Return	Duct North		1	007	✓	Hochiki
	Return	Duct South		1	007	✓	Hochiki
20th	Comm	A		1	203	✓	BLK
	Elect	A		1	203	✓	BLK
	Teleph	A		1	203	✓	BLK
	Elect	B		1	203	✓	BLK
	Comm	B		1	203	✓	BLK
	Teleph	B		1	203	✓	BLK
	Teleph	C		1	202	✓	BLK
	Comm	C		1	202	✓	BLK
	Elect	C		1	202	✓	BLK.
	Pass Elev.			1	019	✓	BLK
	Freight Elev.			1	019	✓	BLK
	Elect	D		1	202	✓	BLK
	Comm	D		1	202	✓	BLK
	Teleph	D		1	202	✓	BLK
	Core	HER Duct (2)		1	006	✓	Hochiki
	Return	Duct North		1	005		
20	Return	Duct South		1	005	✓	

INVOICE TO: 7th W.T.C.
Silverstein Properties
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-27-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Retn Duct N.E. 3 045 ✓ Hochiki

S/Contract / Preventive Maintenance on Smoke Detector Units On Floor's 21st/20th Area/Closet's As Listed Above - System ACK/Reset Functions / Print Out. - O.K. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22380

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S	LOC'S	CABLE	XTNDR	TST	S/D
22	ELEV	S/D.	1	021	✓	~~2K3~~ (DFS)
	ELEV	'C'	1	206	✓	BRK.
	COMM	C	1	206	✓	BRK
	TELEPH	C	1	206	✓	BRK
	TELEPH	'D'	1	206	✓	BRK
	COMM	'D'	1	206	✓	BRK.
	ELEV	'D'	1	206	✓	BLK
22	ELEV	'A'	1	207	✓	BLK
	COMM	'A'	1	207	✓	BLK
	TELEPH	'A'	1	207	✓	BLK
	COMM	'B'	1	207	✓	BLK
	ELEV	'B'	1	207	✓	BLK
	TELEPH	'B'	1	207	✓	BLK
	CORE	HER D/DET	1	010	✓	Hochiki
	CORE	HER D/D.	1	010	✓	Hochiki
	RETURN	D/D SOUTH	1	009	✓	Hochiki
	RETURN	D/D. NORTH	1	009		Hochiki
22	FREIGHT ELEV.		1	021	✓	BRK.

11 Speaker Page - (3) Shorts out (repaired) wiring for existing FTB - Tested Mait/Fiber O.K. -

INVOICE TO: 7 W.T.C. (Silverstein) N.Y.C. Att. J. Carrozza

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres, E. Rosario	F.S.D.
	DATE SCHEDULED: 2-21-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT
☒ MAINTENANCE	☒ TEST
☐ JOB COMPLETE	☐ JOB INCOMPLETE
☐ SYSTEM ON LINE	☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/Contract - Repairs - as above listed - 22nd Fl. S/Detectors tested & cleaned [illegible] Preventive Maintenance also checked repairs on Audio Speaker's Page on 11 Fl (3) shorts N/G - 12 Fl. (3) wiring corrected with test OK - (as per previous report).

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22379

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

(W/STA) (SPEAKERS)

LOCATIONS **DEVICES**

FLOOR			CABLE	XTNDR	TST	SPKR'S	UNITS
6	H.E.R.		1	338	✓	O.K	1
	H.E.R-H.V.		1	338	✓		1
	ENG. RAN II		1	335	✓	↓	1
	Hallway		1	317	✓		1
5	Hallway/Freight		1	336	✓	OK	1
	Switch Gear H.V.		1	336	✓		1
	H.E.R. NORTH.			337	✓	↓	1
	H.E.R. SOUTH			337	✓		1
	H.E.R. N.W.			316	✓		1
4	AREA 'B' EXIT			315	✓	OK.	1
3	RAN I. F.S.D. OFFICE			314	✓	OK.	1
2	H.E.R. WEST			334	✓	OK	1
2	TELE/RANE RM			334	✓	↓	1
2	'A' EXIT			313	✓		1
1	PUMP RM			341	✓	OK.	1
(*) 1	ENTRANCE BOOTH			N/G	OUT	SERVICE	1

Ground/Burned Wiring (A) previous repairs
F.S.D. notified

INVOICE TO:
7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / F. Rosario	F.S.D.	
	DATE SCHEDULED: 2-20-01	
CONTRACT #: SKOO 818	TYPE OF SYSTEM: LSN 2000	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	930 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: S/CONTRACT -
Check/Test for operations on Communication/Audio Fire System as: Warden's phone stations & Speaker's page on each floor's above listed floor's complete. —.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22378

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES S/D		Cable	
25	Elect	B		BRK		2	
	Comm	B		"		"	
	Tele	B		"		"	
	Pass	Elev		"		"	
	Freight	Elev		Edwards		2	
	Comm	A		BRK		"	
	Elect	A		"		"	
	Tele	A		"		"	
	Elec	C		"		"	
	Comm	C		"		2	
	Tele	C		"		"	
	Tele	D		"		"	
	Elect	D		"		"	
	Comm	D		"		"	
	Return	D/D	North	Hochiki		"	
	Return	D/D	South	Hochiki		2	
	Core	MER	D/D	Hochiki		"	
	Core	MER	D/D	Hochiki		"	
24	Elev	Lobby	Pass	BRK		2	
	Elev	Lobby	Freight	BRK		"	
	Comm	A		"		"	
	Elect	A		"		"	
	Tele	A		"		"	
	Comm	B		"		"	
	Elect	B		"		2	
	Tele	B		BRK		"	
	Comm	C		"		"	
	Elect	C		"		"	
	Tele	C		"		"	
	Comm	D		"		"	
	Elect	D		"		"	
	Tele	D		"		"	
	Return	D/D	North + South	Hochiki		"	
	Core	MER	D/D	North South Hochiki		"	

INVOICE TO: 7WTC
N.Y., N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank R / Tom White	F.S.D
	DATE SCHEDULED 02-14-01
CONTRACT # S000818	TYPE OF SYSTEM LSM 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE Frank [illegible] Thomas White

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING
Contract Preventive Maintenance
Tested and Cleaned all Smoke and Duct Detectors on the 25th and 24th Floors. Found that every unit working Properly. System Back to Normal Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

27009

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR			Warden Phones			Speakers	
25th			✓			✓	
24th			✓			✓	
22nd			✓			✓	
21st			✓			✓	
20th			✓			✓	
19th			✓			✓	
18th			✓			✓	
17th			✓			✓	
16th			✓			✓	
15th			✓			✓	
14th			✓			✓	
13th			✓			✓	
12th			✓			✓	
MS. 11th			✓			✓	* Horns (N-G) by stairs A+B.
8th			✓			✓	
7th			✓			✓	

INVOICE TO: #7 World Trade Centre. N.Y.C., N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
(I) Clifton Barden (II) Frank Rosario (III) Tom White	F.S.D.
	DATE SCHEDULED: 13th FEB, 2001
CONTRACT #: SC00818	TYPE OF SYSTEM: ASN 2000.
FEE SERVICE #: -	PO #
CALL AUTHORIZED BY: Shop.	PHONE / EXT
☑ MAINTENANCE	☑ TEST
☐ JOB COMPLETE	☐ JOB INCOMPLETE
☐ SYSTEM ON LINE	☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
11 30 AM	12:00 AM	4 30 AM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: Clifton Barden

SERVICE PERFORMED & REMAINING: Performed service - contract of Bldg. Class-"E" Warden Phones and Floor-Page Speakers from 25th floor down through 7th floor. Found (1) problem - Horns by Stair 'A' and Stair 'B' are not operating. All other devices tested are operating properly. Restored system back to normal operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22375

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

EXITS — LOCATIONS | MANUAL STATIONS — DEVICES

FLOOR	A	B	C		H/STA		UNITS
48	147	147			✓		2
47	080	081	082		✓		3
47	FITNESS CENTER			084	✓		1
46	079	078			✓		2
45	076	077			✓		2
44	074	075			✓		2
43	072	073			✓		2
42	071	070			✓		2
41	068	069			✓		2
40	067	066			✓		2
39	065	064	193		✓		3
39	AUDITM EXIT 194				✓		2
38	062	063	192		✓		3
37	060	061	145		✓		3
36	058	059	144		✓		3
35	056	057	195		✓		3
34	054	055			✓		2
33	051	050			✓		2
31	048	049			✓		2
30	046	047			✓		2
29	044	045			✓		2
28	042	043			✓		2
27	040	041			✓		2
27	040	EAST Corridor			✓		1
26	038	039			✓		2
26	038	EAST Corridor			✓		1
5	N	A			—		
4	033	034			✓		2
4	EAST HALL	202	ESCALATOR		✓		3
3	029	030	S.E 032 · SW 031		✓		4
3	N.W. ENTRANCE /	COAT RM /	CONF. EAST		✓	201	3

SERVICE PERFORMED & REMAINING Floor	A	B	TST	UNITS
2	027	028	✓	2
1	S.E. Door 024		✓	1
1	S.W. DR 025		✓	1
1	LOADING POST 026		✓	1

Prev. Maint. Service Contract.
TEST ACTIVATION OF MANUAL PULL STATIONS
ON FLOORS (LISTED) 48TH FL / 1ST FL. –
ANNUNCIATION / ALARM, ACK / RESETS F.C. STA. –
(PRINT OUT AVAIL.)

INVOICE TO:
7 W.T.C.
(SOLOMON SMITH BARNEY)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F-57
F. ROSARIO	DATE SCHEDULED 2-07-01
CONTRACT # S/00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM PM	430 AM (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keefe.
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22374

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	STAIR	EXIT		CABLE	M/STA	TST	
25		A		2	036	✓	
25		B		2	037	✓	
24		A		2	034	✓	
24		B		2	035	✓	
23		A		2	032	✓	
23		B		2	033	✓✓	
22		A		2	070	✓	
22		B		2	071	✓	
21		A		2	068	✓	
21		B		2	069	✓	
20		A		2	066	✓	
20		B		2	067	✓	
19		A		2	064	✓	
19		B		2	065	✓	
18		A		2	062	✓	
18		B		2	063	✓	
17		A		2	060	✓	
17		B		2	061	✓	
16		A		2	058	✓	
16		B		2	059	✓	
15		A		2	056	✓	
15		B		2	057	✓	
14		A		2	054	✓	
14		B		2	055	✓	
13		A		2	052	✓	
13		B		2	053	✓	
12		A		1	050	✓	
12		B		1	051	✓	
11		A		1	048	✓	
11		B		1	049	✓	
10		A		1	046	✓	
10		B		1	047	✓	
9		A		1	044	✓	
9		B		1	045	✓	
8		A		1	042	XAN. o.k.	
8		B		1	043	✓	
7		A		1	040	✓	
7		B		1	041	✓	
6		A		1	038	✓	
6		B		1	039	✓	

INVOICE TO: 7W.T.C
Silverstein Prop.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / A. Ellgen	F.S.D.
	DATE SCHEDULED: 2-06-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING:
Prev. Maint & Service Contract.
Test / Activation manual pull stations on floor (above listed). — 25/6 Fl. w/ exit to stairs A + B. — Annunciation alarm / ack / reset at F.C. Sta. — (Print out avail). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22373

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR			TAMP		W/F.	TEST CHECK
35	STAIR	'B' RISER	2.132		2.100	✓
34	STAIR	'B' RISER	2-131		2-099	✓
33	STAIR	'B' RISER	2.130		2.098	✓
32	STAIR	'B' RISER	2.129		2.097	✓
31	STAIR	'B' RISER	2.128		2.096	✓
30	STAIR	'B' RISER	2.127		2.095	✓
29	STAIR	'B' RISER	2-126		2.094	✓
28	STAIR	'B' RISER	2.125		2-093	✓
27	STAIR	'B' RISER	2.124		2.092	✓
26	STAIR	'D' RISER	2-123		2.091	✓
G	PUMP RM.		2.113			
G	"	"	2.115			
G	"	"	2.116			
G	"	"	2.118			
G	"	"	2.117			
G	"	"	2.119			
G	"	"	2.120			
G	"	"	2.121			
G	"	"	2.122			
G	"	"	2.124			
G.	COMPRESSOR DRAIN		2.157			

INVOICE TO: W.T.C.
N.Y.C.
J. CARLIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSALIO	F.S.D.
	DATE SCHEDULED: 1-31-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - PREV. MAINTENANCE CHECK/TEST OF WATERFLOW S/W & TAMPER'S ON STANDPIPE RISER 'B' STAIRCASE. - ON FLOOR'S ABOVE LISTED (PRINT OUT AVAILABLE). - SYSTEM FIRE COMMAND UNIT ACKNOWLEDGE ALARMS / RESETS. - SEE ABOVE. - COMPLETE. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

22372

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR				TAMPERS		W/F	TSI CHECK
47	STAIR 'B' RISER			2-155		2-112	✓
46	WATER TANK RM			2-148			
	"	"		2-149			
	"	"		2-150			
	"	"		2-151			
	"	"		2-152			
	"	"		2-153			
46	STAIR 'B' RISER			2-154		2-111	✓
45	STAIR 'B' RISER			2-147		2-110	✓
44	"	"		2-142		2-109	✓
44	"	"		2-146			
43	"	"		2-140		2-108	✓
42	"	"		2-139		2-107	✓
41	STAIR 'B' RISER			2-138		2-106	✓
40	"	"		2-137		2-105	✓
39	"	"		2-136		2-104	✓
38	"	"		2-135		2-103	✓
37	"	"		2-134		2-102	✓
36	STAIR 'B' RISER			2-133		2-101	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: WTC
N.Y.C
M. J. CARRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F.S.I.
	DATE SCHEDULED: 1-30-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSH2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract. Year 2001 / WFlows / Tampers Switches Check / Test Alarms / Reset to Fire Comm Unit. Acknowledge / Reset - (Print out Activity). - See above list Floors 47 to 36th - to be continued

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

TIME DATE NAME

FIRE SERVICE INCORPORATED

22212

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR	B	RISER	CABLE	TAMPR	CABLE	W/F	
25	B	"	2	122	2	090	
24	B	"	2	121	2	089	
23	B	"	2	120	2	088	
22	B	"	1	150	1	103	
21	B	"	1	149	1	102	
20	B	"	1	143	1	101	
20	B	"	1	144	—	—	
20	B	"	1	145	—	—	
20	B	"	1	146	—	—	
19	B	RISER	1	142	1	100	
18	B	"	1	141	1	099	
17	B	"	1	140	1	098	
16	B	"	1	139	1	097	
15	B	"	1	138	1	096	
14	B	"	1	137	1	095	
13	B	"	1	136	1	094	
12	B	"	1	135	1	093	
11	B	"	1	134	1	092	
10	B	RISER	1	133	1	091	
9	B	*	1	132 (C)	1	090	
8	B		1	131	1	089	
7	B		1	130	1	087	

INVOICE TO: 7 W.T.C.
N.Y.C.
MR. J. CURRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 1-24-01
CONTRACT #: 3/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 (AM)	430 (PM)	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Service Contract - Year 2001 (Tested activation) Alarm's / Reset's on Tamper's / Waterflow's S/W as (listed above) Floor's 25 to 7. Note: 9 Fl Tamper S/W to check / adjustment - [illegible] to follow up - Contrary Test - Print out available. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22211

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR		TTB'S		STRB. PNL'S	MAINT
6	'B' STAIRCASE	2			✓
	'B' COMM.		AFC 100	1	✓
5	'B' COMM		AFC 100	1	OUT SERV.
5	'B' Stair	1			✓
5	W. MER. (FAN RM)	2			✓
4	'B' COMM		AFC 100	1	✓
3	'B' Stair	1			✓
3	'B' COMM		AFC 100	1	✓
2	FREIGHT AREA WALL		AFC 100	1	✓
1	PUMP RM		AFC 100	1	✓
1	PUMP RM	1			✓
48	PLANT MER		AFC 100	1	✓
47	'A' STAIR CLOSET		AFC 100	1	✓
46	ELEV. S/D by SHUTTLE ELEVATOR (Salomon Fl.) Replaced / Installed. - old unit Broken BACK IN OPERATION. -				
46	'B' COMM		AFC 100	1	✓

INVOICE TO: 7 W. T.C.
N.Y.C.
Mr. J. Carrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F.S.D.
	DATE SCHEDULED: 1-23-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Contract Prev. Maintenance on Listed TTB'S Units & Strobes Lights Fire Alarm PNL'S. - Batteries - Supervision / Door Release Voltages outputs. - Checked O.K. -
Also Repairs on 46 Fl. (Salomon Floor) Smoke Elev. Shuttle Detector Broken Replaced / Installed New Unit - (Bldg provided). - Pro Rec 3 -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22210

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR				TTB'S		PANEL STRIPS	MAINT
15	CORE HER			3	AFC 100	1	✓
14	CORE	HER			AFC 102	1	✓
13	'B' COMM / 'C' ELECT.				AFC 100	2	✓
12	'B' COMM / CORE HER			3	AFC 101	2	✓
11	'B' COMM				AFC 101	2	✓
					(BATTERIES CHK.)		
10	N/A						
9	N/A.						
8	'B' COMM				AFC 101	1	✓
7	'B' COMM / CORE HER			1	AFC 100	1	✓
Lbby	(DCM - 40)	F.C. STATION				CHECK	
		#10	NETWORK /	OPER.		PLUGS	ADJ.

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	
	DATE SCHEDULED 1-17-01
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: CONTINUE PREV. MAINTENANCE ON RISER'S TTB'S / STROBE PNL'S / SUBSYSTEMS — DOOR RELEASES / POWER VOLTAGES READINGS CHECKS O.K.
ALSO REPAIRING STROBE PNL ON 16 FL. — CKT / DISABLED DUE TO FAULTY. WAIT AL FIELD — TO BE ACTIV. / TRACED. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22208

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR				TTB'S	PANEL STRBS		MAINTN
24	CORE	HER		(3)	1	AFC100	✓
23	CORE	HER					
22	'B' COMM.				(2)	AFC100	✓
21	CORE	HER		(2)	1	AFC100	✓
20	CORE	HER			1	AFC100	✓
19	CORE	HER			1	AFC100	✓
18	CORE	HER		(2)	2	AFC100	✓
17	CORE	HER			1	AFC100	✓
16	CORE	HER			1	AFC100	✓
			(1) CKT DEFECT / UNIT REPAIRED				

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F.S.D.
	DATE SCHEDULED: 1-16-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #: -
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Continuing S/contract - Prev. Maintenance on TTB'S Riser (Floor's above) / listed strobe pnl's / subsystems door l[illegible] power voltages outputs O.K. - Normal levels. - System put back to operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 26939

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

PREVENTIVE MAINTENANCE CONTRACT

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES TTB's	STROBE PNL
38	FREIGHT AREA		(1) DLC3	(1) AFC100
37	FREIGHT AREA.		(1) D3C3	(1) AFC 100
36	FREIGHT AREA			(1) AFC 100
	OPPOSITE/RECEPT (South)		(1) D1C1	
35	FREIGHT AREA.			(1) AFC 100
34	FREIGHT/AREA		(1) D3C4	(2) AFC100 PAD102
	CONF RM EXIT			(1) PAD102
33	FREIGHT/AREA		(1) D1C1 CORE HEY.	(1) AFC 100
32	FREIGHT AREA		(1) D3C3	(1) AFC100
31	FREIGHT AREA		(1) D3C3	(1) AFC100
30	CORE HEY		(1) D1C1	(1) FREIGHT AFC100 AREA.
29	FREIGHT AREA			(1) AFC100
28	FREIGHT AREA		(1) D3C4	(1) AFC100
27	CORE HEY.		(1) D6C3	(1) Pyro Syty 3
26	CORE HEY		—	(1) Pyro Syty 3
25	CORE HEY		—	(1) AFC100

INVOICE TO: 7W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED 1-10-01
CONTRACT # 5/0 00918	TYPE OF SYSTEM ISN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: Service Contract Maintenance on TTB's Riser's As Listed on Floor's 38 Thru 25. — And Strobe PNL's — Door Releases Door Riser's Check/Voltage O.K. — Also Amplify PNL Check Floor Page/Radio 37 Fl O.K. — (Trouble Page 37 Fl) clear (Elect. Forest Correcting Units Away). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SE[illegible]VICE INCORPORA[illegible]ED 97640

SUBSIDIARY OF FI[illegible]C[illegible] INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C. N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Skof -	5/C00 818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		1-9-01	AM	G. Torres / A. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800 AM.	420 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE 1-9-01

WILL RETURN ON

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

PROBLEM—AS DESCRIBED Service Contract / Status Repairs Purge / Pressuration - floor's 25/26/24th Fl. - as/F.S.D. Requested - and 23 Fl. Pressuration. -

SERVICE PERFORMED As per Contract check follow up on Purge / Pressuration Activation FAN'S Unit Malfunctions on: 25 Fl. purge. Pressuration 26' and 24' Floor's. - + Pressuration 25th Fl. Units. Repaired / Exchanged (1) 792 P.C. Board (Output Function) Down Lower System - Units Back in Operation Check O.K. - 24 Fl TTB Unit - Also check with Electrician Fiest / Fir Floor Page 39 Fl + Strobe Pull. - Check defective circuits / short + ground - all corrected. - CKT's Normal. - Trouble Condition clear. - - Back in operation. -

WORK REMAINING C/ Service Contract.

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED 22207

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR						CHK	
47		(1)	TTB	DATA	3/4	✓	
47		(1)	TTB	DATA	1/2.	✓	
47		(1)	STROBE	PNL		✓	
46		(1)	STROBE	PNL		✓	
45		(1)	TTB	DATA	3/4	✓	
45		(1)	TTB	DATA	1/2	✓	
45		(3)	STROBES	PNL'S		✓	
44		(1)	STROBE	PNL		✓	
43		(1)	STROBE	PNL		✓	
43		(1)	TTB	DATA	3/4	✓	
42		(1)	STROBE	PNL		✓	
42		(1)	TTB	DATA	3/4	✓	
42		(1)	TTB	DATA	1/2	✓	
41		(1)	STROBE	PNL		✓	
40		(1)	STROBE	PNL		✓	
40		(1)	TTB	DATA	3/4	✓	
39		(1)	STROBE	PNL		✓	
39		(1)	TTB	DATA	1/2	✓	

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 1-3-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature] [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT - CHECK / P. MAINTENANCE ON TTB'S RISER ON FLOOR'S 47 - 46 - 45 - 44 - 43 - 42 - 41 - 40 - 39 FL. -
ALSO CHECK FOR FLOOR PAGE SPK TROUBLE ON 39 FL. (FOREST ELECTRIC AND UNITS) (1) CKT GROUNDED / SHORTED. - ALSO (1) STROBE CRT SHORTED. - ELECTRICIAN TO TRACE WIRING. - SPKR'S / STROBES ONLY (1) CKT EACH IN OPERATION. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22206

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR		Purge		Press	Press		
7		✓		8	—		
8		✓		8	7		
9		✓		10	8		
10		✓		9	11		
11		✓		12	10		
12		✓		13	11		
13		✓		14	12		
14		✓		15	13		
15		✓		14	16		
16		✓		17	15		
17		✓		16	18		
18		✓		17	19		
19		✓		20	18		
20		✓		21	19		
21		✓		22	20		
22		✓		21	23		
23		✓		22	—		
24		✓		23	—		
25		—	N/G	—	—		
26		✓		27	—		
27		✓		28	26		
28		✓		27	29		
29		✓		28	30		
30		✓		29	31		
31		✓		30	32		
32		✓		31	33		
33		✓		32	34		
34		✓		33	35		
35		✓		36	34		
36		✓		37	35		
37		✓		38	36		
38		✓		37	39		
39		✓		38	40		
40		✓		41	39		
41		✓		40	42		

SERVICE PERFORMED & REMAINING

42	✓	43	41	As per Bldg Request - Check for operation	
43	✓	44	42	on Purge / Press. Status Indications at Console	
44	✓	43	45	Found Missing Pressurization on 23rd - 24 - 25 - 26 as	
45	✓	44	46	Listed above. Also 47/46 as Listed. —	
46	✓	45	—	Manual Press. on Floors 47/46 - 5th - 3rd	
47	—	—	—	Manual Purge on Floors 4th - 3rd - 2nd FP. —	

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

See Print Out. —

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D
	DATE SCHEDULED 1-2-01
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #

CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SER‹'‹CE INCORPORAT‹‹‹

93978

SUBSIDIARY OF FIRE‹O‹ INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WORLD TRADE CENTER
NEW YORK. NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T		SCH UPS				J F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		1-4-2001	AM			G. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE	CUSTOMER SIGNATURE
1-4-2001	X
WILL RETURN ON	**SERVICEMAN SIGNATURE**
	G. FORERO

PROBLEM—AS DESCRIBED Preventive maintenance / Service Contract (UPS)

SERVICE PERFORMED Checked U.P.S System Took Readings (OK)
Total Battery Voltage 140.5 V-DC, output HZ 62.2
L1=12.5 L=10.9 (OK) Checked and Cleaned Battery Rack #1 & #2
And Main Cabinet, Filters Mini-Fans (OK)
System operational.

OK Tony 1/4/01

WORK REMAINING

(Battery Rack = 30 pcs)

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name X

Date

FIRE SERVICE INCORPORATED

22204

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS — DEVICES

FLOOR	AREAS	S/D	CHK	XTNAL	SENS TEST	CHANGE
45	FREIGHT ELEV	BLK	2	022	3.0	✓
	PASS ELEV	BLK	2	022	3.2	✓
	ELECT A	BLK	2	217	3.0	✓
	COMM A	BLK	2	217	3.0	✓
	ELECT B	BLK	2	217	2.8	✓
	TELE B	BLK	2	217	3.0	✓
	COMM B	BLK	2	217	3.0	✓
	'G' ELECTRIC	PEL3	4	083	2.8	✓
	SECURITY	PEL3T	4	083	2.8	✓
45	SHUTTLE ELEV	PEL3	4	011	3.0	✓
	KITCHEN SHUTTLE ELEV	PEL3	4	012	3.0	✓
'D'	AREA STAIR	PEL3T	4	063	3.0	✓
	SHUTTLE FREIGHT KITCHEN	PEL3T	4	019	3.0	✓
	AUDIO/VISUAL	PEL3T	4	091	3.0	✓
	AREA RISER SHAFT		4	089	3.0	✓
	EAST ELECT-F	PEL3T	4	059	3.0	✓
	DUCT DET. KITCHEN	EDWDS	4	094	3.2	✓
	D/DET. KITCHEN	EDWDS	4	123	3.2	✓
	D/D. KITCHEN F45	EDWDS	4	092	3.2	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. N.Y.C. (Solomon Brothers)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED 12/27-00
CONTRACT # 5/C00 818	TYPE OF SYSTEM CSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	9:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Silverstein

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING Prev. Maintenance & Sensitivity Test on Smoke Detection Device / Class 'E' Fire System. CSN 2000 Model — on 45th Fl. (Solomon Brothers) — System fully restored — Back to normal

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding the interruption of the fire protection service during their service of the equipment.

NAME / DATE / TIME

FIRE SERVICE INCORPORATED

22205

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			Chime	Cable	XTNDL	S/D	SENS TEST
GROUND	CEILING			1	163	BBK	3.0
	"			1	163	BLK	3.2
	"			1	163	BLK	3.2
	"			1	163	BLK	3.0
G	CEILING			1	163	BBK	3.2
	—				—		
G	ELEV. Hoistway		1		000	BLK	3.0
16	STBY PNL	CHECK/	NORMAL	WIRING			
				SYSTEM	NORMAL.		—

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 12-26-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: CSN 2000
FEE SERVICE #: -	PO #
CALL AUTHORIZED BY	PHONE / EXT

- ☒ MAINTENANCE ☒ TEST
- ☐ JOB COMPLETE ☐ JOB INCOMPLETE
- ☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
12:00 AM	12:45 PM	2:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME

DATE X

NAME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE. / SILVERSTEIN AREA - GROUND FLOOR - HIGH CEILING MAIN ENTRANCE (USED "GENIE BOOM") SMOKE DETECTORS CLASS "E" FIRE ALARM SYSTEM. - SYSTEM CHK/NORMAL. - - ASSISTED BY BLD SILVERSTEIN ENG. "KEVIN" ALSO CHECKED 39 FL STBY PNL CKTS - FIELD WIRING SHORTED / PANEL REMAINS DISABLED. - (FLOOR UNDER CONST/RENOVATION) ALSO FLOOR PAGE (OK CKTS. - TROUBLE STATUS;

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22203

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR			Cable	XMDR	S/D	SENS TEST	Clean
3rd	SECURITY		3	048	PEC3	3.0	✓
	D/D AHU 34		3	042	EDWDS	3.2	✓
	KITCHEN Supply						
	W. HER AREA		3	006	PEC3T	3.0	✓
	W. HER AREA		3	006	PEC3T	3.0	✓
3rd	W.HER D/D		3	040	EDWDS	3.2	✓
	W.HER D/D		3	041	EDWDS	3.4	✓
	W HER D/D		3	040	EDWDS	3.2	✓
	W.HER D/D		3	040	EDWDS	3.2	✓
3rd	CONF. AREA		1	077	DI-3	3.0	✓
	RECEPTION AREA		1	077	DI-3	3.0	✓
	ELEV. Lobby		3	029	PEC3	3.0	✓
2nd	ELEV Lbby		3	028	PEC3	3.0	✓
2nd	ELEV RH		3	005	PEC3T	3.2	✓
1st	PLANT HER D/D		3	039	EDWDS	3.2	✓
	PLANT HER D/D		3	037	EDWDS	3.2	✓
	PLANT AREA		1	012	PEC3T	2.8	✓
30	Communications B		1	184	RETESTED / CHECK		
	(AREA S/D) BAK UNIT -					O.K.	

INVOICE TO: WTC (Solomon Bros) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	FSD
	DATE SCHEDULED 12-20-00
CONTRACT # S/C 00818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: PREVENTIVE MAINTENANCE / SENSITIVITY TEST ON SMOKE UNITS CLASS E SYSTEM - SEMI ANNUAL TEST COMPLETE. - As per Contract On Area / Floor's Above Listed. -
Also Unit on 30 Fl "B" Communication Closet - RETESTED / CHECK For Normal OPERATION / all - O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22184

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			Cable	XTNDR	S/D	SENS TEST	Change
5TH	MAIN ELEV.		1	004	BRK	3.0	✓
	FREIGHT ELEV		1	004	BRK	3.2	✓
	ROTO CLONE		3	013	PECST	3.0	✓
	ROTO CLONE		3	013	PECST	3.0	✓
	ELECT	A	1	169	BRK	3.0	✓
	ELECT	B	1	169	BRK	3.2	✓
	ELECT	C	1	169	BRK	3.0	✓
	ELECT	F	1	169	BRK	3.2	✓
	TELEPH	A	1	169	BRK	3.0	✓
	COMM	B	1	169	BRK	3.0	✓
4TH	MAIN ELEV.		1	003	BRK	3.0	✓
	FREIGHT ELEV		1	003	BRK	3.2	✓
	CHEF'S OFFICE		3	043	[illegible]	3.0	✓
	ELECT	B	1	167	BRK	3.0	✓
	TELEPH	A	1	167	BRK	3.0	✓
	ELECT	A	1	167	BRK	3.0	✓
	ELECT	G	3	050	PEC3	2.8	✓
	TELEPH	B	1	167	BRK	3.0	✓
	COMM	B	1	167	BRK	3.0	✓

37TH Floor Page Trouble Status — Check due to B Loop grounded. — (Forest Elect. notified). — to locate unit(s) grounded. —

INVOICE TO: 7 WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED 12-19-00
CONTRACT # SK00818	TYPE OF SYSTEM LSN2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	930 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME
DATE
TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING Preventive Maintenance / Servicing Smoke Detection on Solomon Smith Floors 5th/4th. — Areas as listed above) — Also 37TH Spare Page Trouble Condition found B Loop grounding — Elect. 'Forest' notified (W.T.C. were aware) — to locate unit + correct. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22183

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR				XTNSTL	SENS TEST	S/D.	Cleaned
27	ELECT	A-B	(2)	2-178	3.0	BLK	✓
	COMM	A-B	(2)	2-178	3.0	BLK	✓
	TELEPH	A-B	(2)	2-178	3.2/3.0	BLK	✓
	COMM	C-D	(2)	2-177	3.0	BLK	✓
	ELECT	C-D	(2)	2-177	3.2/3.0	BLK	✓
	TELEPH	C-D	(2)	2-177	3.0/3.2	BLK	✓
	PASS ELEV.		(1)	2-004	3.0	BLK	✓
	FREIGHT ELEV		(1)	2-004	3.0	BLK	✓
	CORE HER D/D			2-237	3.4	SIF24	✓
	CORE HER D/D			2-237	3.2	SIF24	✓
27	LADIES BATH D/D R.			2-236	3.2	SIF-24	✓
	RET. D/D N/SOUTH		(2)	2-236	3.2	SIF24	✓
26	ELECT	A-B	(2)	2-176	3.0	BLK	✓
	COMM	A-B	(2)	2-176	3.2	BLK	✓
	TELEPH	A-B	(2)	2-176	3.0	BLK	✓
	COMM.	C-D	(2)	2-175	3.0	BLK	✓
	ELECT	C-D	(2)	2-175	3.0	BLK	✓
	TELEPH	C-D	(2)	2-175	3.2/3.0	BLK	✓
	PASS ELEV.		(1)	2-003	3.0	BLK	✓
	FREIGHT ELEV		(1)	2-003	3.2	BLK	✓
	CORE HER D/D		(1)	2-235	3.4	SIF24	✓
	CORE HER D/D		(1)	2-235	3.4	SIF24	✓
	RET. D/D LADIES		(1)	2-234	3.2	SIF24	✓
	NORTH D/D RET		(1)	2-234	3.2	SIF24	✓
	SOUTH D/D RET		(1)	2-234	3.4	SIF24	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 12-13-00
CONTRACT #: SFC00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Preventive Maintenance & Check Smoke Detectors Units Sensitivity & Maintenance by Areas (Above Listed) on Floors 27/26 Floors System Check/Reset. - Functions Operating Normal. -

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22182

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES: Model	Sens Test	Clean	S/D
29	Elect	A-B	(2)	2-182	3.0	✓	BRK
	Teleph	A-B	(2)	2-182	3.2	✓	BRK
	Comm.	A-B	(2)	2-182	3.0	✓	BRK
	Elect	C		2-181	3.0	✓	BRK
	Elect	DW/D	(2)	2-181	3.2/3.0	✓	BRK
	Elect	G/Sec	(2)	3-007	3.0	✓	PEC 3
	Elect	F		3-014	3.2	✓	PEC 3
	Teleph	C-D	(2)	2-181	3.2/3.0	✓	BRK
	Comm	C		2-181	3.0	✓	BRK
	Pass/Freight Elev (2)			2-006	3.0	✓	BRK
	Shuttle Elev			2-030	2.8	✓	PEC 3
*	Core	Mer Area (3)		2-240	3.0	✓	PEC 3T
*	Core	Mer D/D	(2)	2-241	3.2	✓	SIF 24
29	W. Mer Area		(2)	3-000	3.0	✓	PEC 3T
	W. Mer Duct Det (2)			3-032	3.2	✓	EDWDS
28	Elect	A-B	(2)	2-180	3.0	✓	BRK
	Comm	A-B	(2)	2-180	3.2	✓	BRK
	Teleph	A-B	(2)	2-180	3.0	✓	BRK
	Elect	C-D	(2)	2-179	3.0	✓	BRK
	Comm	C-D	(2)	2-179	3.2/3.0	✓	BRK
	Tele/Equ	C	(1)	2-179	3.0	✓	BRK
	Elect	D.W	(1)	2-179	3.0	✓	PEC 3T
	Elect	F	(1)	2-179	2.8	✓	PEC 3T
	Elect	G/Sec	(1)	2-180	3.0	✓	PEC 3
	Pass Elev		(1)	2-005	2.8	✓	EDWARDS
	Freight Elev		(1)	2-005	3.0	✓	EDWARDS
	Shuttle Elev		(1)	2-005	3.0	✓	PEC 3
	Core	Mer Area Duct		2-239	3.2	✓	SIF 24
	Core	Mer Duct Det		2-239	3.2	✓	SIF 24
	W. Mer Area		(3)	3-057	3.0	✓	PEC 3T
28	W. Mer D/Det			3-047	3.2	✓	DT 3

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 12-12-00
CONTRACT #: 5/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Continue Prev. Maintenance clean/tested - sensitivity on smoke units floors 29 & 28 as listed above. - System back/restored
(*) NOTE: 29 Fl Core Mer D/D (1) Front Unit u/w Fan ... & danger High Power line ... (1) Area Unit ceiling - Bldg to provide safe access for service / Core Mer. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22215

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			Cable	XTNDR	S/D	SENS TEST	Change
31	ELECT	A-B	2	187	BRK	3.0	✓
	TELEPH	A-B	2	187	BRK	3.2/3.0	✓
	COMM	A-B	2	187	BLK	3.0	✓
	ELECT	C-D	2	186	BLK	3.2	✓
	ELECT	D.W	2	186	BRK	3.0	✓
	ELECT	F	3	016	PEC 3	3.0	✓
	ELECT	G	3	009	PEC 3	2.8	✓
	SECURITY		3	009	PEC 3	3.0	✓
	COAT/COMM	'B'	2	186	BLK	3.0	✓
	COAT	A.W.	2	186	BLK	3.0	✓
	PASS ELEV. MAIN		2	008	BLK	3.0	✓
	FREIGHT ELEV		2	008	BLK	3.0	✓
	SHUTTLE ELEV		3	025	PEC 3	3.0	✓
	CORE MER AREA	(3)	2	244	PEC3T	3.0	✓
	CORE MER D/D	(2)	2	245	SIF24	3.2	✓
	W. MER AREA	(2)	3	002	PEC3T	3.0	✓
	W. MER D/D	(2)	3	034	EDWDS	3.2	✓
	N. SUPPLY CLOSET	(2)	2	186	BLK	3.0	✓
30	ELECT	A-B (2)	2	184	BRK	3.0	✓
*	COMM	A-B (2)	2	184	BLK	3.0	✓
	TELEPH	A-B (2)	2	184	BRK	3.0	✓
	ELECT	C-D (2)	2	183	BRK	3.2	✓
	ELECT	D.W	2	183	BLK	3.0	✓
	ELECT	F	3	015	PEC 3	3.2	✓
	ELECT	G/SEC. (2)	3	008	PEC 3	3.0/3.2	✓
	TEL/COMM	C (2)	2	183	BRK	3.0	✓
	COAT/TELEP	'D'	2	183	BLK	3.0	✓
	PASS/FREIGHT ELEV	(2)	2	007	BLK/DIB	3.0	✓
	SHUTTLE PASS ELEV.		3	024	PEC 3	2.8	✓
	CORE MER AREA	(3)	2	242	PEC3T	3.2	✓
	CORE MER D/D	(2)	2	243	SIF24	3.2	✓
	W. MER D/D	(2)	3	033	EDWDS	3.0	✓
	W. MER D/D		3	033	EDWDS	3.2	✓
	W. MER AREA		3	001	PEC3T	3.2	✓
	W. MER AREA		3	001	PEC3T	3.0	✓

INVOICE TO: 7 W.T.C.

N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F. S. D.
	DATE SCHEDULED: 12-6-00
CONTRACT #: S/C 008118	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE SMOKE DETECTION UNITS LOCATED ON FLOORS 31 & 30 AS LISTED. - SYSTEM ACK/RESETED. - SENSITIVITY TEST CHECK. - AS ABOVE. -
NOTE: 30 FL. COMM 'B' CLOSET - BASE/TERMINAL S/D DEFECTIVE to check repair. - to CONTINUE —.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22214

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S	CABK	XTUDR	S/D	SENS TEST	CLEANED
33	ELECT A-B (2)	2	191	BRK	3.2	✓
	COMM A-B (2)	2	191	BRK	3.0	✓
	TELEPH A-B (2)	2	191	BRK	3.2/3.0	✓
	ELECT [illegible] C (2)	2	192	BRK	3.0	✓
	ELECT D.W	2	192	BRK	3.2	✓
	ELECT F	3	018	PEC 3	2.8	✓
	ELECT G/SEC. (2)	3	011	PEC 3	3.0	✓
	TEK/SUPPLY C	2	192	BRK	3.0	✓
	COAT D/TEK	2	192	BRK	3.2	✓
	FREIGHT/PASS (2)	2	010	BRK	3.0	✓
	SHUTTLE ELEV.	3	027	PEC3	2.8	✓
	CORE MER AREA (3)	2	250	PEC3T	3.0	✓
	CORE MER D/D (2)	2	249	SIF24	3.2/3.0	✓
	W. MER AREA (2)	3	004	PEC3T	2.8	✓
	W. MER D/D (2)	3	036	EDWDS	3.2	✓
32	ELECT A-B (2)	2	190	BRK	3.0	✓
	COMM A-B (2)	2	190	BRK	3.2/3.0	✓
	TELEPH A-B (2)	2	190	BRK	3.0	✓
	ELECT C-D (2)	2	189	BRK	3.0	✓
	ELECT D.W	2	189	BRK	3.2	✓
	ELECT F	3	017	PEC3T	3.0	✓
	ELECT G/SEC.	3	010	PEC 3T	3.2	✓
	TEK D/SUPPLY	2	189	BRK	3.0	✓
	COMM C/SUPPLY	2	189	BRK	3.2	✓
	MAIN/FREIGHT ELEV	2	009	BRK	3.0	✓
	SHUTTLE ELEV	3	026	PEC 3	3.2	✓
	CORE MER AREA (3)	2	248	PEC3T	3.0	✓
	CORE MER D/D (2)	2	247	SIF24	3.0	✓
	W. MER AREA (2)	2	003	PEC3T	3.2	✓
	W. MER [illegible]	3	035	EDWDS	3.4	✓
	W. MER D/D	3	035	EDWDS	3.2	✓
	TELEPH C/COAT	2	189	BRK	3.0	✓

INVOICE TO: 7W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 12-5-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSW 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE / SENSITIVITY TEST OF SMOKE DETECTION
CLASS E FIRE SYSTEM ON FLOORS 33 + 32ND AREAS ABOVE LISTED
SYSTEM CHECKED/RESTORED.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22371

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		CABLE	XTNDR	SENS TEST	CLEANED
35	ELECT A-B	(2)	2	196	3.0	✓
	COMM A-B	(2)	2	196	3.2/3.0	✓
	TELEPH A-B	(2)	2	196	3.2/3.0	✓
	ELECT C		4	049	3.2	✓
	ELECT D		4	049	3.0	✓
	ELECT F		4	049	3.2	✓
	ELECT F1		4	049	3.0	✓
	ELECT G/SEC.	(2)	4	073	3.0	✓
	FREIGHT ELEV		2	012	3.0	✓
	PASS ELEV MAIN		2	012	3.0	✓
	ELEV SHUTTLE		4	001	3.0	✓
	W. HER AREA		4	025	3.0	✓
	W. HER D/D		4	097	3.2	✓
34	ELECT A-B	(2)	2	194	3.0	✓
	COMM A-B	(2)	2	194	3.0	✓
	(#) TELEPH (A) B	(2)	2	194	3.0	✓
	ELECT C-D	(2)	2	193	3.2/3.0	✓
	ELECT DW		2	193	3.0	✓
	ELECT F		4	048	3.2	✓
	ELECT F1/AV ROOM		4	048	3.0	✓
	ELECT G/SEC.	(2)	4	072	3.0	✓
	TELEPH C-D	(2)	2	193	3.0	✓
	MEDICAL OPEN AREA		2	193	3.0	✓
	PASS ELEV. MAIN		2	011	3.0	✓
	FREIGHT ELEV.		2	011	3.2	✓
	SHUTTLE ELEV.		4	000	3.0	✓
	CORE HER AREA	(3)	2	252	3.2	✓
	CORE HER DUCT	(2)	2	251	3.2	✓
	W. HER AREA		4	024	3.2	✓
	W. HER D/D		4	096	3.2	✓
#	TELEPH (A) 34th FL.		N/A	(BLOCKED ENTRANCE)		
+	EXH. UNIT KITCHEN		N/A	PENDING. +		

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 11-29-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE ON SMOKE DETECTION ON FLOORS 35/34th AREAS LISTED ABOVE - SENSITIVITY TEST / UNIT ALARMED PROPERLY - SYSTEM BACK TO NORMAL -
NOTE: (1) UNIT D/D EXHAUST TO BE DONE. / 34th FL. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22370

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CABLE	XTNDR	SENS TEST	S/D
37	ELECT A-B	(2)	2	200	3.0	BRK
	COMM A-B	(2)	2	200	3.2/3.0	BRK
	TELEPH A-B	(2)	2	200	3.0/3.2	BRK
	ELECT C-D	(2)	2	199	3.0	BRK
	ELECT DW		2	199	3.2	BRK
	ELECT F		4	051	3.0	PEC3
	ELECT 6/SEC.	(2)	4	075	3.0	PEC 3
	TELEPH C-D	(2)	2	199	3.0	BRK
	COMM C		2	199	3.2	BRK
	PASS ELEV.		2	014	3.0	BRK
	FREIGHT ELEV		2	014	3.2	BRK
	ELEV. SHUTTLE		4	003	3.0	PEC3
	CORE MEH AREA (3)		2	258	3.2	PEC3T
	CORE MEH D/D	(2)	2	257	3.2	SIF24
	W. MEH AREA	(2)	4	027	3.0	PEC3T
	W. MEH D/D	(2)	4	099	3.2	EDWDS
36	ELECT A-B	(2)	2	198	3.0	BRK
	COMM A-B	(2)	2	198	3.0	BRK
	TELEPH A-B	(2)	2	198	3.0	BRK
	ELECT C-D	(2)	2	197	3.0	BRK
	ELECT F		4	050	3.0	PEC3
	ELECT D.W		2	197	3.0	BRK
	ELECT 6/SEC	(2)	4	074	3.0	PEC3
	TELEPH C.D (CONT) (2)		2	197	3.2	BRK
	COMM STORAGE C		2	197	3.0	BRK
	PASS ELEV		2	013	3.0	BRK
	FREIGHT ELEV.		2	013	3.2	BRK
	SHUTTLE ELEV.		4	002	3.2	PEC3
	CORE MEH AREA (3)		2	256	3.0	PEC3T
	CORE MEH D/D	(2)	2	255	3.2	SIF24
	W. MEH AREA	(2)	4	026	3.2	PEC3T
	W. MEH DUCT DET		4	098	3.4	EDWDS
	W. MEH D/DET		4	098	3.2	EDWDS

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 11.28-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/CONTRACT – Prev. Maintenance Smoke Detection on Floors 37/36 as listed above & per Silverstein Bothers Floors – Sensitivity Test – System ok operated properly

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) C

FIRE SERVICE INCORPORATED

22369

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	AREA'S			CABk	XTNDR	S/D	SENS TEST
39	E/ECT	A-B	(2)	242	205	BRK	3.0
	COMM	A-B	(2)	242	205	BRK	3.0
	TELEPH	A-B	(2)	242	205	BRK	3.2/3.0
	ELECT	C		242	204	BRK.	
	ELECT	D.W.		242	204	BLK	
	ELECT	D1		242	204	BRK	
	ELECT	F		246	053	PEC3	
	ELECT	G/SEC	(2)	246	077	PEC3	
	FREIGHT ELEV			222	016	BRK	
	PASS ELEV. MAIN			242	016	BRK	
	ELEV. SHUTTLE			246	005	PEC3	
	RECPTN CEILING DUCT			242	254	Apllo	
	RECPTN CEILING DUCT			242	254	Apllo	
	RECPTN " DUCT			242	254	Apllo	
	RECPTN " DUCT			242	254	Apllo	
	RECPTN " DUCT			242	254	Apllo	
	CORE HER AREA			243	006	APOLLO PEC3	
	CORE HER AREA			243	006	APOLLO PEC3	
	CORE HER AREA			243	006	PEC3	
	CORE DUCT DET.			243	007	HOCHIKI	
	CORE DUCT DET			243	007	HOCHIKI	
	WEST HER AREA			246	029	PEC3T	
	W. HER. DUCT DET.			246	101	EDWDS	
38	W HER CEILING AREA			246	026	PEC3T	
38	W. HER DUCT DET.			246	127	EDWDS	

AUDITORIUM (39)

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO:
T.W.T.C.
N.Y.C.
(SOLOMON/SMITH BARNEY)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.I.
F. ROSARIO	DATE SCHEDULED: 11-21-00
CONTRACT #	TYPE OF SYSTEM: LSN 500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING

Prev. Maintenance smoke detection units on 39th floor as listed above and 38 floor pertaining line W. HER facility. - Sensitivity tested, tested breaker box to operating

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22368

REPORT OF FIELD SERVICE

FLOOR	AREA'S (LOCATIONS)	CABLE	XTNDE	S/D	SENS (DEVICES)
39/38	W. HER AREA. AUDITN	246	046	PEC3T	3.0
39 38	W. HER DID AUDITN	246	127	EDWDS	3.2
	ELECT A-B (2)	242	202	BRK	3.0
	TELE A-B (2)	242	202	BRK	3.0
	COMM A-B (2)	242	202	BRK	3.0
	ELECT C-D (1)	242	203	BRK	3.0
	ELECT D- (1)	242	203	BRK	3.2
	ELECT D.W.	242	203	EDWDS	2.8
	ELECT F	246	052	PEC3	2.9
	ELECT G	246	076	PEC3	2.8
	SECURITY CLOSET	246	076	PEC3	2.8
	PASS ELEV. MAIN	242	015	BRK	3.0
	FREIGHT ELEV.	242	015	BRK	3.2
	ELEV. PASS SHORE	246	004	PEC3	3.0
	CORE HER AREA	243	004	PEC3T	3.0
	" " "	243	004	PEC3T	3.0
	" " "	243	004	PEC3T	3.0
	CORE HER DUCT	243	005	HOCHIKI	3.2
	CORE HER DUCT	243	005	HOCHIKI	3.2
	W. HER AREA	246	028	PEC3T	3.0
38	W. HER DUCT	246	0100	HOCHIKI	3.2
			—	EDWDS	—

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 11-22-00
CONTRACT #	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continue Service Contract

PREV. MAINTENANCE ON SMOKE DETECTION UNITS ON 38th FL. ABOVE & SYSTEM ACT/RESET - BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION: The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME DATE NAME

FIRE SERVICE INCORPORATED 22366

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CABLE	XTNDR	S/D	SENS
41	PASS ELEV		2	018	BLK	3.2
	FREIGHT ELEV		2	018	BLK	3.0
	PASS SHUTTLE		4	007	PEL3	3.0
	ELECT A-B	(2)	2	209	BLK	3.0/3.0
	COMM A-B	(2)	2	209	BLK EDWDS	3.0/2.8
	TELEPH A-B	(2)	2	209	BLK	3.0/3.0
	TELEPH C-D	(2)	2	195	Apllo	2.8
	COMM C-D	(2)	2	195	Apllo	2.8
	ELECT C-D	(2)	2	195	Apllo	2.8
	'G'/SECURITY	(2)	4	079	PEL3	3.0/3.0
	H.E.R. AREA	(2)	2	019	Apllo	2.8
	H.E.R. D/DET.	(2)	2	016	Apllo	3.0
40	PASS		2	017	BLK	3.0
*	FREIGHT - (BURIED)		2	017	BLK	3.0
	SHUTTLE ELEV.		4	006	PEL3	2.8
	AREA ELECT A-B	(2)	2	207	BLK	3.0
	COMM A-B	(2)	2	207	BLK	3.0
	TELEPH A-B	(2)	2	207	BLK	3.0
	TELEPH C-D	(2)	2	206	Apllo	2.6
	COMM C-D	(2)	2	206	Apllo	2.8
	ELECT C-D	(2)	2	206	Apllo	2.6
	H.ER. AREA	(2)	2	208	Apllo	2.8
	H.ER D/D	(2)	2	015	Apllo	2.8
	FILE RM AREA Solomon		4	258	Apllo	2.8
	FILE RM AREA Solomon		4	251	Apllo	2.8
	'G' ELECT.		4	078	PEL3	2.8
	SECURITY		4	078	PEL3	2.8

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7W.T.C. N.Y.C. (Solomon)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 11-15-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME

DATE

NAME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE. SERVICE CONTRACT - On SMOKE DETECTION CLASS 'E' SYSTEM ON FLOOR'S 41 + 40 (Solomon SMITH BARNEY) ON AREA (ABOVE LISTED). -
(*) SMOKE DETECTOR 40TH FREIGHT AREA 'BURIED' TOP CEILING ABOVE TILES

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

— "MUST BE EXPOSED. — (FOREST ELECT/Solomon) —

FIRE SERVICE INCORPORATED 22367

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				Cab#	XTNDR	S/D	Sens.
42	PASS ELEV.			2	019	BLK	3.0
*	FREIGHT ELEV (BURIED)			2	019	BLK.	3.2
	SHUTTLE PASS.			4	008	PEC3	3.0
	TELEPH A			2	211	BLK	3.0
	ELECT A			2	211	BLK	3.0
	COMM A			2	211	BLK	3.2
	COMM B			2	211	BLK	3.0
	ELECT B			2	211	BLK	3.0
	TELEPH B			2	211	BLK	3.2
	TELEPH C			2	210	Apllo	3.0
	ELECT C			2	210	Apllo	3.0
	COMM C			2	210	Apllo	2.8
	COMM D			2	210	Apllo	2.8
	ELECT D			2	210	Apllo	3.0
	TELEPH D			2	210	Apllo	2.8
	MER AREA			2	212	Apllo	2.8
	MER AREA			2	212	Apllo	2.8
	MER D/D			2	017	Apllo	2.8
	MER D/D			2	017	Apllo	2.8
	'G' ELECT.			4	080	PEC3	2.8
	SECURITY CLOSET			4	080	PEC3	3.0

'F' ELECT → MISSING S/D / NO WIRING

(*) ASISTED FIRECOM KENNY WALL / RICK TRADING ON CHECK'S FOR FAN'S SHUTDOWN / ACTIVATIONS ON 18 FL CHECK / ALLADL SYSTEM

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C
N.Y.C

SERVICEMAN ASSIGNED: G. TORRES, F. ROSARIO
SEE AT JOB SITE: F.S.D
DATE SCHEDULED: 11-14-00
CONTRACT #: S/C 00 818
TYPE OF SYSTEM: 8500 LSN 2000
FEE SERVICE #:
P.O #:
CALL AUTHORIZED BY:
PHONE:
EXT:

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	5:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT -
Contract Prev. Maintenance on Smoke Detection Class E System. - Firecom LSN 2000 Model. - Sensitivity Test / Semiannually. - On Floor's Listed Above / Area. -
(*) NOTE: FREIGHT ELEV. S/D. (BURIED) Above Ceiling Tiles. - Must be Removed / Exposed Ceiling - (Forest Elect / Solomon). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22365

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES: Cools	S/D	Sens Test
46	Elect	B	2	BRK	
	Comm	D	2	BRK	
	Freight Elev		2	BRK	
	Elect	D	4	PEC3	
	Sec. Closet		4	DI3	
	Elect	A	1	BRK	
	Comm	A	1	BRK	
	Teleph	A	2	BRK	
	Teleph	D	2	BRK	
	Elect	D	2	BRK	
	Comm	D	2	BRK	
	Elev. W Shuttle		4	Pec3	
	Elev. E Shuttle		4	Pec3	
	Core HER D/D (2)		2	[illegible]	
	Core HER Area (2)		2	Pec3 T	
	Elect	F	4	Pec3	
	Elect	C	2	Pec3	
	[illegible] Elev Shuttle		4	Pec3	
43	Freight/Pass (2)		2	BRK	
	Elect A+B (2)		2	BRK	
	Teleph A+B (2)		2	BRK	
	Comm A+B (2)		2	BRK	
	Elect		4	BRK	
	Security		4	Pec3 T	
	Shuttle Elev		4	Pec3 T	
	East HER D/D		4	Apollo	
	East HER Area		4	Apollo	

Note F Elect None S/D

Note Code 213 on 43rd in trouble

INVOICE TO: 7WTC
NYC

SERVICEMAN ASSIGNED	SEE AT JOB SITE
F. Rosario / Zinser	F.S.D.
	DATE SCHEDULED: 11-8-2000
CONTRACT #: SC00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract
Preventive Maintenance Check for Sensitivity Test on Smoke Detectors Units on 46th and 43rd Floors Salomon Smith Barney

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED
SUBSIDIARY OF FIRECOM INC
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

55015

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WORLD TRADE
NY NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	SC 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		11-1-00	AM	C Blyth

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900 AM	400 PM	430 PM					

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 11-1-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Calvin Blyth

PROBLEM—AS DESCRIBED: SERVICE CONTRACT

SERVICE PERFORMED: ASSIST TECH with TESTING ON AREA SMOK DETECTOR, and DUCT SMOKE DETECTOR Floor WORK ON WAS 45, 44 and 46 Floor.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

FIRE SERVICE INCORPORATED

22361

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABK	XTUDL	S/D	SENS TEST
47	ELECT	A	CLOSET	2	222	BLK.	3.0
	ELECT	B	"	2	222	BLK	3.0
	ELECT	C	"	2	223	BLK	3.2
	ELECT	F	"	4	061	PEC3	3.0
	ELECT	G	"	4	035	PEC3	2.8
	TELEPH	B	"	2	222	BLK	3.0
	B STAIRWAY			2	221	EDWDS	3.2
	TELEPH	A	CLOSET	2	222	BLK	3.0
	COMM	D	"	2	223	BLK	3.0
	CUSHMAN OFFICE	AREA		4	113	EDWDS	3.0
	SHAFT/VERTICAL	CONVYR		4	068	EDWDS	3.0
	SECURITY	CLOSET		4	221	EDWDS	3.0
	ELEVATOR	SHUTTLE		4	016	PEC3T	2.8
	WEST	HER		4	069	EDWDS	3.0
	W. HER	D/D. 47-1		4	115	EDWDS	3.0
	CORE	HER	D/D	2/023	279	PEC3T	3.0
	CORE	HER	AREA	2/022	278	PEC3	3.2
	CORE	HEY	AREA	2	022/278	PEC3	3.2
	CORE	HEY	AREA	2-022	/278	PEC3	3.0
47	A STAIR/ELEV	S/D		2	024	BRK	3.0
48	D/D.	EF	2	4	117	EDWDS	3.2
⊕ 48	D/D	AC	1	4	118	EDWDS	3.0
⊕ 48	D/D	AC	2	4	118	D138	3.2

⊕ UNITS REPLACED/due to FALSE ACTIVATION. -
RETESTED BACK TO OPERATION -

45 RETEST SPK - STROBE AS per FOREST ELECT. REQUEST. -

24 DOOR RELEASE CHECK AS PER BLD/ ENTRANCE GLASS DOORS. -

INVOICE TO: 2 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. LOCKER / F. ROSARIO	F.S.D.
	DATE SCHEDULED 11-01-00
CONTRACT # S/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. # 25N2000
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) [signature]
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING SERVICE CONTRACT AS ABOVE LISTED FLOORS 47th
All AREAS S/DETECTORS SENSITIVITY TEST / MAINTENANCE ALSO
TEST/ REPAIR CHECK SPK/STROBE 45th Fl as FOREST Request.
AND 24 Fl. door release as per BLG Mgr. Requested. -
S/C to CONTINUE —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Services Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Services Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22363

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	PLANT			CABLE	XTNDR	S/D	SENS TEST
48	Area Ceiling			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.2
	"			4	086	PEC3T	3.0
48	D/Detector	48-1 AH2		4	070	EDWIS	3.4
48	"	48-1 TE2		4	[illegible]	EDWIS	3.2
48	"	EF-1		4	118	EDWIS	3.4
48	"	EF-2		NO ACCESS AT THIS TIME			
48	"	AR1			"	N/A	
48	"	AC 2			"	N/A	
44	ELECT	G		4	082	PEC3	3.0
	ELECT	A		2	215	BRK	3.2
	ELECT	B		2	215	BRK	3.0
	TELEPH	A		2	215	BRK	3.2
	TELEPH	B		2	215	BRK	3.0
	COMM	B		2	215	BRK	3.2
	COMM	A		2	215	BRK	3.0
	FREIGHT ELEV			4	021	BRK	3.0
44	PASS ELEV. MAIN			4	021	BRK	3.0
	ELEV. PASS SHUTTLE			4	010	PEC3	3.2
	ELEV PASS SHUTTLE			4	018	PEC3	3.2
	SECURITY CLOSET			4	082	PEC3	3.0
	W. MER AREA			4	034	PEC3T	3.2
	W. MER D/D			4	112	EDWIS	3.4

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C. (Solomon Bros?)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario?	F.S.
CONTRACT # S/C 00 818	DATE SCHEDULED 10-31-00
	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING: Preventive Maintenance / Sensitivity Test / Cleaned smoke units on 48th Fl M.E.R / Plant - as listed. - (3) Duct detectors pending service / need an assist / access. - Also service 44th areas / as listed. - System OK / [illegible] LSN 2000 Model. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

97635

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	SC 00818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		10-30-00	AM	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8W	900	3:30	430					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 10-30-00

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Maintenance — Repairs

SERVICE PERFORMED As per Contract check / Repairs on 16 Fl. strobe panel AFC 100
Correct. Traced ckt - unit repaired back to normal. —
Also as per F.S.D. check / Repaired 35 Fl. AFC 100 strobe panel / Modifications
update P.C. Mother Board. - Rewired back to operation. —
Also check 37 Fl. page trouble / strobe pnl trouble. — Conditions due
to construction on floor / SPKR'S / strobes ceiling being removed / relocated
by Forest Elect. / Solomon Brothers. —
System OK / Back to operations —

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED 97613

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
B.T.		C/C 60818				F.S.D
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		10-25-00	AM.			J. Torres A. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO.	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	900	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 10-25-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract – Repairs Status –

SERVICE PERFORMED As per contract check traced 37th Fl. page spk trouble. (Floor under renovation). – Located open unit dummy wires fixed by Forest Electric. – 37 Floor page normalized – Also proceeded to asist Firecom tech Igor to install door release relay supv. top TTB unit cable #1, 47th Fl. riser. – Unit mounting wiring installed. – Check supv./release CP40 indicator O.K. – Also proceeded after to check printer unit – RA40 unit on 44th Fl security office – wiring RA40 to printer – software P.C. driver unit S/W's positions – jumper 1 – as per Espers – Eng./Firecom. – Unit down/print n/g. – Need to check R.A40 unit - DB-25 connected pins

WORK REMAINING (#R's 25/17 O.K.) – Also check for audio rack trouble status – traced to 796 P.C. card open jumper at O.C.P./AL6-11 to AR4-9 repaired O.K. – Trouble audio rack cleared. –

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

22360

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

10/24/00

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CABLE	ADDR	S/D	SENS TEST
3	TOP ESCALATOR		1	166	BLK	3.0
	TOP ESCALATOR		1	166	BRK	3.2
3rd	ELECT. 'D' (Locker's)		1	165	BLK	3.0
	TELEPH 'A'		1	166	BLK	3.0
	ELECT A		1	166	BLK	3.0
	COMM A		1	166	BLK	3.2
	COMM/TEL B		1	166	BLK	3.2
	COMM B		1	166	BLK	3.2
3	ELEV. Lobby Freight		1	002	BLK	3.0
	ELEV. Lobby Pass (4-13/14-21)		1	002	BLK	3.2
	ELEV. Hi Rise 22/28		1	166	BLK	3.0
	ELEV. Hi Rise (36-45)		1	166	BLK	3.0
	ELEV. Hi Rise (22-28)		1	002	BLK	3.2
3	SPT - Security/FSD		1	109	Apollo	3.0

Floor	TEST LIVE			Floor		
44	P.A. SPK TONES			29	P.A. SPK TONES	
43	"	"	OK	28	"	OK
42	"	"	OK	27	"	OK
41	"	"	OK	26	"	OK
40	"	"	OK	25	"	OK
39	"	"	OK			
38	"	"	OK			
37	"	"	OK			
36	"	"	OK			
35	"	"	OK			
34	"	"	OK			
33	"	"	OK			
32	"	"	OK			
31	"	"	OK			
30		"	OK			

INVOICE TO: 1W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D 10-24-00
	DATE SCHEDULED: 10-24-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: KSW 8500/2000
FEE SERVICE #	PO #

CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Service Contract

Preventive Maintenance Smoke Sensitivity Test on Silverstein Spaces As Listed Above. - System Ack / Reset - Output Functions O.K. - * NOTE: Also Traced and Repaired Tones / Audio Manual Evacuation on Floor's 25 thru 44 as listed. - (Defective No Tones on these Floor's) Power Rack Audio. - Levels Adj. [Detail?]

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER O.K.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

22362

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS / DEVICES
7	Area S/D Photo/Heat 1-046 open — Anex Device wiring to be located
7	Duct S/D Anex 1-047 open — Device wiring to be located —
7	Fan Shutdown Anex 1-050 open wiring/Relay to be located. —
7	Damper Control/Anex to located — wiring/Relay - 1-055 open ext —

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C (Silverstein)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I
	DATE SCHEDULED: 10-23-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM/PM	2:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Check/As per Contract. Repairs per Status Report On 7th Fl. (Core Wet) Area S/D (2) Units located inside closet's - Units Disabled No Power wiring open loop (From Previous). — Wiring need Tracing up ceiling — Need to located Photo Heat Det/Anex Cable - Either 046 Trouble & D/Det. Anex (046) job appears to be Incompleted. Fan Shutdown Anex (1-050) And Damper Control Anex (1-055) 7th floor — Also started to Trace Audio/Tones Missing on Floors 35 Up to Roof / Mic/Page OK.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

Microphone - page O.K. Entire Bld. — Tones Manual Evac - Defect/Missing Riser. — 1.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE X TIME

FIRE SERVICE INCORPORATED

22386

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		S/D	CABLE	XMDR	SENS
6	SWITCHGEAR		BRK	1	171	3.0
	"		BRK	1	171	3.0
	"		BRK	1	171	3.2
	"		BRK	1	171	3.2
	"		BRK	1	171	3.0
6	H.V. VAULT	(4)	BRK	1	171	3.0
	H.V. VAULT	(4)	BRK	1	171	3.0
	H.V. VAULT	(4)	BRK	1	171	3.0
	H.V. VAULT	(1)	BRK	1	171	3.2
5	STEAM RM	FAN'S	HOCHIKI	1	223	3.4
	"	"	HOCHIKI	1	224	3.2
	"	"	HOCHIKI	1	228	3.4
	"	"	HOCHIKI	1	011	3.4
5	SWITCHGEAR	NORTH	BRK	1	170	3.0
	SWITCHGEAR	NORTH	BRK	1	170	3.0
	SWITCHGEAR	NORTH	BRK	1	170	3.2
	"	NORTH	BRK	1	170	3.2
	"	SOUTH	BRK	1	170	3.2
	"	SOUTH	BRK	1	170	3.0
	"	SOUTH	BRK	1	170	3.2
	"	SOUTH	BRK	1	170	3.0
	H.V. VAULTS	(6)	BRK	1	170	3.0/3.2
	H.V. VAULTS	(6)	BRK	1	170	3.0/3.2

PREVENTIVE MAINTENANCE
CONTRACT

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D
F. ROSARIO	DATE SCHEDULED 10-16-00
CONTRACT # S/C 00818	TYPE OF SYSTEM LX N2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	330 PM	420 PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME
DATE
NAME

SERVICE PERFORMED & REMAINING: CONTINUE S/CONTRACT SEMIANNUAL TEST SENSITIVITY AS LISTED ABOVE FLOOR'S 6 - 5 FLOOR'S - H. VOLTAGE VOLTAGE VAULTS & SWITCHGEAR AREA'S. SYSTEM ACK/RESETED AS OUTPUT FUNCTIONS O.K.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22385

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	AREAS			CABLE	XINDR	S/D	SENS
9	ELECT	A		1	179	BRK	3.2
	COMM	A		1	179	BLK	3.0
	ELEC	A		1	179	BRK	3.0
	COMM	B		1	179	BRK	3.2
	ELECT	B		1	179	BLK	3.0
	TELEPH	B		1	179	BRK	3.2
	PASS	ELEV		1	008	BLK	3.0
	ELECT	C		1	178	BLK	3.2
	COMM	C		1	178	BLK	3.2
	TELEPH	C		1	178	BLK	3.0
	FREIGHT ELEV			1	008	BLC	3.2
	RETURN D/D NORTH			1	238	HOCHIKI	3.4
	RETURN D/D EAST			1	238	HOCHIKI	3.2
	RET. D/D SOUTH			1	238	HOCHIKI	3.4
	—						
9	ELECT	D		1	178	BRK	3.0
	COMM	D		1	178	BRK	3.2
	TELEPH	D		1	178	BRK	3.0
	CORE	HER D/D		1	239	HOCHIKI	3.2
	CORE	HER D/D		1	239	HOCHIKI	3.2
2	TAMPER S/W			1	123	RESET	ALM
	(SPINDLE NOT SITTING PROPERLY)						—
37	TAMPER	S/W	(CLOSE VALVE / CONSTRUCTION)				
20	TAMPER			1	146	ALM	
	DUE TO NEED GROOVE/CUT ON SHAFT						
	AND ADJUSTMENT MECHANICALLY						

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torrer / F. Rosario	F.S.D
	DATE SCHEDULED: 10-11-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: XN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: Covered S/Contract – Repairs
Prev. Maintenance as per contract. Check/test sensitivity on devices above listed 9 fl. – also check/repair on tamper S/W floor 2nd/20th – 37th as required. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22359

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CABLE	XTNDR	S/D	SENS. TEST
8	COMM A		1	177	BLK	3.2
	ELEC A		1	177	BLK	3.0
	TELEPH A		1	177	BLK	3.0
	ELEC B		1	177	BLK	3.2
	COMM B		1	177	BLK	3.0
	TELEPH B		1	177	BLK	3.2
	COMM C		1	180	BLK	3.2
	ELECT C		1	180	BLK	3.0
	TELEPH C		1	180	BLK	3.2
	TELEPH D		1	180	BLK	3.0
	ELECT D		1	180	BLK	3.0
	COMM D		1	180	BLK	3.0
	PASS ELEV.		1	007	BLK	3.2
	FREIGHT ELEV		1	007	BLK	3.2
	CORE HGR D/D		1	237	Hochiki	3.4
	CORE HGR D/D		1	237	Hochiki	3.4
	RETURN D/D North		1	236	Hochiki	3.2
	RETURN D/D East		1	236	Hochiki	3.4
*	RETURN D/D South Elev.		NO ACCESS.			—
12	STROBE PNL - Trouble / Repair (Loose Terminal P.C.)					
Lobby	F.C. STATION CXN 2000 Check'd. CP40 Unit —					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 10-4-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: As per contract check tested smoke detection on 8th Fl. Area as listed. - Also repair on 12th Fl. Strobe PNL's and check'd all equipment area on F.C. STA. / CP40 Unit - Reset system restore back to operation / ACK.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SER*V*ICE INCORPORA*T*ED

52145

SUBSIDIARY OF FIR*ECO*M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC.
New York NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Shop	U.P.S 818				T.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		9/26/2000	AM	C. Forero & C Tabare

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:30 AM	9.15 AM							

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 9/26/2000

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: C. Forero and C Tabar

PROBLEM—AS DESCRIBED U.P.S maintenance / service contract (80 Batteries)

SERVICE PERFORMED Took Reading, Checked Fans, Filters And cleaned Cabinet. Each All Batteries Test O.K. U.P.S it's operational OK
Total Amps = .3
Total Battery Voltage 146.9 DC
Frequency = (60) 62.5 HZ
Load 1 = 11.7
Load 2 11.5
input V/AC 208/AC
output 245

PREVENTIVE MAINTENANCE CONTRACT

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____ X ____ Date

FIRE SERVICE INCORPORATED

76793

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
K.W	S/C 00 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		9-27-00	A.M.	J. Torres F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	5:30						
	Am	Pm						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 9-27-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED to perform S/Contract - Test P. Authority. As Requested

SERVICE PERFORMED At F.S.D. Request / Safety G.C. = J.C. Hegan / Elect. Contractor Solomon Brothers on Post Auth. Fire Inspection on floors 31-32 + 36. Also check 45 Fl stairway lights. – NOTE: Ladies Bathroom Strobe Light not operational – Also as per Contract Service Trouble Shooting 35 Fl. Sub Safety Smoke panel Alarm. Wiring Termination Corrected back to Normal & trouble status. due to Units Disabled / Floors under Renovation. – Also performed 'DRY' TEST on Area I/O. Core HV FAN Rooms on 43 and Area closets 40 to 42nd Fl. – (See Print out) As Requested

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 8186

FIRE SERVICE INCORPORATED 22358

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CHAN	XTNDR	S/D	SENS TEST CLEAN
7TH	ELECT A		1	175	BLK	5.0
	COMM A		1	175	BLK	5.0
	TELEPH A		1	175	BLK	3.2
	PASS ELEV		1	006	BLK	3.0
	FREIGHT ELEV		1	006	BLK	3.2
	COMM B		1	175	BLK	3.0
	ELECT B		1	175	BLK	3.0
	TELEPH B		1	175	BLK	3.2
	TELEPH C		1	174	BLK	3.0
	ELECT C		1	174	BLK	3.2
	COMM C		1	174	BLK	3.2
	TELEPH D		1	174	BLK	3.0
	ELECT D		1	174	BLK	3.0
	COMM D		1	174	BLK	3.0
7TH	CORE NER D/D		1	235	Hochiki	3.4
	CORE NER D/D		1	235	Hochiki	3.4
	RETURN D/D NORTH		1	234	Hochiki	3.2
	RETURN D/D SOUTH		1	234	Hochiki	3.4
3RD	AREA S/D (2)		1	166	BLK	

UNITS CHECK / SENSITIVITY AS REQUIRED. (3.2 RANGE NORMAL)

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. Silverstein Prop. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / E. Rosario	F.S.D.
	DATE SCHEDULED: 9-26-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #: -	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:20 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: As per contract serviced smoke detectors on 7th floor areas as listed above / sensitivity check O.K. - See Readings

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22356

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO: 7 W.T.C.
N.Y.C.

LOCATIONS			DEVICES			
FLOOR	AREA	(CLOSET)	CABLE	XTNDR	S/D	SENS TEST
11	COMM	A-B (2)	1	182	BRK	3.2/3.0
	ELECT	A-B (2)	1	182	BRK	3.0/3.0
	TELEPH	A-B (2)	1	182	BRK	3.2/3.0
	PASS	ELEV	1	010	BRK	3.0
	FREIGHT ELEV		1	010	BRK	3.0
	COMM	C	1	183	BRK	3.0
	TELEPH	C	1	183	BRK	3.0
	ELECT	C	1	183	BRK.	3.0
	TELEPH	D	1	183	BRK	3.0
	ELECT	D	1	183	BRK	3.2
	COMM	D	1	183	BRK	3.0
	CORE WEST D/D		1	243	Hochiki	3.4
LED *	CORE WEST D/D		1	243	Hochiki	3.2
	RETURN D/D NORTH		1	242	Hochiki	3.4
	RETURN D/D SOUTH		1	242	Hochiki	3.2

35 SUBSYSTEM PAGATION PNL ALARMED
ZINE - TTB TERMINAL CHECK
Repair - O.K. - (4-163)
[illegible] F.S.D. - XTNDR - -

PREVENTIVE MAINTENANCE CONTRACT

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 9-20-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION — DATE — TIME — NAME

SERVICE PERFORMED & REMAINING: S/CONTRACT - Routine S/C Prev. Maintenance on Smoke Detection Check on Area locations (Above Listed.) - Floors 11th & Repairs on 35th Fl Subsystem Alarm. - Back to operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

[illegible]

FIRE SERVICE INCORPORATED

22357

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREAS/CLOSET			CABLE	XTNDR	S/D	SENS TEST
14	COMM.	A-B	(2)	1	188	BRK	3.0/3.2
	TELEPH	A-B	(2)	1	188	BRK	3.0/3.0
	ELECT	A-B	(2)	1	188	BRK	3.2/3.0
	PASS	ELEV.	(1)	1	013	BRK	3.0
	FREIGHT ELEV		(1)	1	013	BRK	3.2
	ELECT	C-D	(2)	1	189	BRK	3.2/3.0
	COMM	C-D	(2)	1	189	BRK	3.0/3.0
	TELEPH	C-D	(2)	1	189	BRK	3.2/3.0
	CORE	HER	D/D	1	249	HOCHIKI	3.4
	CORE	HER	D/D	1	249	HOCHIKI	3.4
	PLENUM RETURN SOUTH			1	248	HOCH	3.2
*	PLENUM	RETURN NORTH		NO ACCESS	- LOC. UNKNOWN		
12	ELECT	A-B	(2)	1	184	BRK	3.0/3.2
	COMM	A-B	(2)	1	184	BRK	3.2/3.0
	TELEPH	A-B	(2)	1	184	BRK	3.0/3.0
	PASS	ELEV	(1)	1	011	BRK	3.0
	FREIGHT ELEV		(1)	1	011	BRK	3.2
	CORE	HER D/D	(2)	1	245	HOCHIKI	3.4/3.2
	RETURN PLENUM NORTH			1	244	HOCHIKI	3.2
	RETURN PLENUM SOUTH			1	244	HOCHIKI	3.2
	ELECT	C-D	(2)	1	185	BRK	3.2/3.0
	COMM	C-D	(2)	1	185	BRK	3.2/3.2
	TELEPH	C-D	(2)	1	185	BRK	3.2/3.2

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	T.S.D
	DATE SCHEDULED: 9-19-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING

S/CONTRACT PREV. MAINTENANCE SMOKE DETECTOR - SENSITIVITY TEST ON AREAS LOCATIONS (ABOVE LISTED) FLOOR'S 14 & 12 FLOORS. — SYSTEM ACK/RESET - OUTPUT O.K. - BACK TO OPERATION. —

(*) NOTE: 14TH PLENUM RETURN D/D NORTH (NO ACCESS/LOCAT. UNK AS PREVIOUS LISTED). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22355

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREAS			PASK	YTUM	TST SENS	S/D
16	CORE HER		(1)	1	253	3.2	Hochiki
	CORE HER		(1)	1	253	3.4	Hochiki
	ELEC	A-B	(2)	1	193	3.0	BLK
	COMM	A-B	(2)	1	193	3.2	BLK
	TELEPH	A-B	(2)	1	193	3.0	BLK
	PASS	ELEV.	(1)	1	015	3.2	BLK
	FREIGHT	ELEV.	(1)	1	015	3.2	BLK
	ELEC	C-D	(2)	1	194	3.0	BLK
	COMM	C-D	(2)	1	194	3.0	BLK
	TELEPH	C-D	(2)	1	194	3.0	BLK
	PLENUM	RET.	D/D NORTH	1	252	3.4	Hochiki
	"	RET-D/D SOUTH		NO ACCESS - U/L -			
15*	CORE HER D/D		(1)	1	251	3.4	Hochiki
*	CORE HER D/D		(1)	1	251	3.2	Hochiki
	COMM	A-B	(2)	1	190	3.0	BLK
	ELEC	A-B	(2)	1	190	3.2	BLK
	TELEPH	A-B	(2)	1	190	3.2	BLK
	TELEPH	C-D	(2)	1	191	3.2	BLK
	ELEC	C-D	(2)	1	191	3.2	BLK
	COMM	C-D	(2)	1	191	3.2	BLK
	PASS	ELEV.		1	014	3.0	BLK
	FREIGHT	ELEV.		1	04	3.0	BLK
	PLENUM	RET.	NORTH D/D	1	250	3.4	Hochiki
	"	RET. SOUTH	N/A	NO ACCESS -			

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. P. / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED: J. TORRES / J. ROSARIO	SEE AT JOB SITE: FSD
	DATE SCHEDULED: 8-30-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
(2)	I.C. Prom's - Bypass	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT -
PREV. MAINTENANCE ON SMOKE DETECTION SYSTEM - FLOORS 16 + 15 AS LISTED ABOVE - UNITS TESTED / SENSITIVITY / CLEANING - SYSTEM ACK/RESET OUTPUTS FUNCTIONS / BYPASS CHECK - OK -
NOTE: CORE HER D/D (2) LED's N/G to repair [illegible] . (2) 15 FL. -
RETURN SOUTH SIDE @ 16 - 15 FL. NO ACCESS / AS PREVIOUSLY REPORTED -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(2) I.C.'s Prom's replaced in BPZ / Floors 20/14 BYPASS DEFECTIVE / CORRECTED O.K. -

FIRE SERVICE INCORPORATED 76792

SUBSIDIARY OF FIRE... INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO:

SERVICED: 7 W.T.C. / Silverstein Prop. / N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
R.T.	SK 00 818				M. Carrigan F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		8-29-00	AM	J. Torres / J. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	4:30						

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 8-29-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED: S/Contract - Semiannual - Repairs -

SERVICE PERFORMED: Performed Repairs on 44th Strobe Panel AFC100 - Main P.C. Board - Update Changes - Intermittent Signal Trouble. - Replaced Part / Installed - Also as per Contract Maintenance on 13 Fl. all areas [illegible] Smoke Detectors Sensitivity Test - As:

Location		Sens	Test	XTNDR	
Teleph Clset	A+B	3.0	✓		BLK
Comm. "	A-B	3.2	✓	1-186	BLK
Electric "	A-B	3.0	✓	1-186	BLK
Comm "	C-D	3.2	✓	1-187	BLK
Elect "	C-D	3.0	✓	1-187	BLK
Teleph "	C-D	3.2	✓	1-187	BLK
~~Pass Elev~~		~~3.0~~	✓	~~1-012~~	~~BLK~~
Freight Elev		3.0	✓	1-012	BLK
Core Hol (2) D/D		3.4	✓	1-247	Hochiki
Plenum Return D/D North		3.4	✓	1-246	Hochiki
Plenum Return D/D South		3.4	✓	1-246	Hochiki

(13th Fl)

WORK REMAINING:

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name / Date: X

FCI 155
REV 6186

FIRE SERVICE INCORPORATED : 22354

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		S/D	CABLE	XTNDR	SENS
17	PASS ELEV		BLK	1	016	3.2
	FREIGHT ELEV		BLK	1	016	3.0
	ELECT. A		BLK	1	197	3.0
	COMM A		BLK	1	197	3.2
	TELEPH A		BLK	1	197	3.0
	ELECT B		BLK	1	197	3.0
	COMM B		BLK	1	197	3.2
	TELEPH B		BLK	1	197	3.2
	COMM C		BLK	1	196	3.0
	ELECT C		BLK	1	196	3.0
	TELEPH C		BLK	1	196	3.2
	ELECT D		BLK	1	196	3.0
	COMM D		BLK	1	196	3.0
	TELEPH D		BLK	1	196	3.2
	CORE	MER	Hochiki	1	256	3.4
	CORE	MER	Hochiki	1	256	3.4
17	PLENUM RET. D/D - N/A . (4 2) -					
	(Plaster Ceiling - Solid) -					

PREVENTIVE MAINTENANCE CONTRACT

44th STROBE PNL: CHECK/Replaced Low Batteries output - (2) NEW with 12 VLTS - Replacing O.K.

19th STROBE PNL: CHECK/Trouble shooting (2) Batteries Replaced Low voltage output (12 VLTS) O.K.

INVOICE TO: 7 W.T.C. - SILVERSTEIN Prop. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.J
	DATE SCHEDULED: 8-23-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	12 VLT Batteries	69.95
-	(Strobes PNL's) -	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME

DATE

NAME

SERVICE PERFORMED & REMAINING: Continuing S/Contract!

Preventive Maintenance Smoke Detection Units on 17th Fl. Areas (above listed) Class E Fire Alarm System. - Units on Alarm/Reset - Plenum D/D N/A - Ceiling plaster - System ACK/Reset. Also Repairing/Replaced Batteries for Strobes PNL's on Floors 44th + 19th as listed. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22353

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		S/D	CABLE	XTNDR	TST RDAN
19TH	ELEV PASS		BRK	1	018	✓3.2
	TELEPH A-B	(2)	BRK	1	201	3.0
	COMM A-B	(2)	BRK	1	201	3.0
	ELECT. A-B	(2)	BRK	1	201	3.2
	CORE MER D/D		Hochiki	1	260	3.2
	CORE MER D/D		Hochiki	1	260	3.4
	ELEV. FREIGHT		BRK	1	018	3.0
	PLENUM RET-D/D South		Hochiki	1	259	3.4
	" RET. D/D North		Hochiki	1	259	3.4
	ELECT C-D	(2)	BRK	1	200	3.2
	COMM C-D	(2)	BRK	1	200	3.0
19TH	TELEPH C-D	(2)	BRK	1	200	3.0
18	ELECT A-B	(2)	BRK	1	199	3.2
	COMM A-B	(2)	BRK	1	199	3.0
	TELEPH A-B	(2)	BRK	1	199	3.2
	PASS ELEV.		BRK	1	017	3.0
	FREIGHT ELEV		BRK	1	017	3.2
	CORE MER D/D		Hochiki	1	258	3.4
	CORE MER D/D		Hochiki	1	258	3.4
	TELEPH. C-D	(2)	BRK	1	198	3.2
	ELECT C-D	(2)	BRK	1	198	3.0
	COMM C-D	(2)	BRK.	1	198	3.0
	PLENUM RET D/D N.		Hochiki	1	257	3.4
18TH	PLENUM RET D/D South		Hochiki	1	257	3.4

INVOICE TO: 7 W.T.C
Silverstein Properties
N.Y.C.

SERVICEMAN ASSIGNED: J. Torres, F. Rosario
SEE AT JOB SITE: F.S.D.
DATE SCHEDULED: 8-22-00
CONTRACT #: S/C00818
TYPE OF SYSTEM: 8500
FEE SERVICE #:
P.O. #:
CALL AUTHORIZED BY:
PHONE:
EXT:

☐ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM) PM	430 AM (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT
Preventive Maintenance on Smoke Detection Units on Floors (Above Listed)
Class "E" Fire Equipment/System - Units in Working Order. - System Set Back to Operation.
to be Pointing Bldg Riser. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22352

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREAS			S/D	CABLE	XMDR	TST CHAN
20	PASS ELEV.			BLK	1	019	3.0
	FREIGHT ELEV.			BLK	1	019	3.0
	COMM A				1	203	3.2
	ELECT A				1	203	3.0
	TELEPH A				1	203	3.2
	COMM B				1	203	3.0
	ELECT B				1	203	3.2
	TELEPH B				1	203	3.0
	TELEPH C				1	202	3.0
	ELECT C				1	202	3.2
	COMM C				1	202	3.0
	ELECT D				1	202	3.0
	TELEPH D				1	202	3.2
	COMM D				1	202	3.0
	CORE HEL D/D			HOCHIKI	1	262	3.4
	CORE HEA D/D			HOCHIKI	1	262	3.2
	RETURN D/D NORTH			HOCHIKI	1	261	3.2
	RETURN D/D SOUTH			HOCHIKI	1	261	3.4
20	RETURN D/D EAST			HOCHIKI	3	045	
13	STROBE PNL AFC 100 Replaced (2) Batteries						
	12 VLTS - BACK UP POWER - OK -						
44	STROBE PNL AFC 100 TROUBLE STATUS (4-370)						
	NEEDING (2) BATTERIES 12 VLT UNITS						
	to be replaced. -						

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 8-16-00
CONTRACT #: S/C 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VLTS BATTERIES	69.95

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Sean O'Keefe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

SERVICE PERFORMED & REMAINING: Continuing Scheduled Preventive Maintenance on Smoke Detection Flr's & Equipment on 20th (as listed). - Also Repairs on 13th Floor / 44th Fl Pending - (2) Batteries Back up units needed - 12 VLTS. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22351

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				S/D	CABLE	XTNDR	TST SENS.
22	FREIGHT ELEV.			BRK	1	021	3.0
	PASS ELEV.	21·3		BRK	1	021	3.0
	COMM	'A'		BRK	1	207	3.0
	ELECT	'A'		BRK	1	207	3.2
	TELEPH	'A'		BRK	1	207	3.2
	COMM	'B'		BRK	1	207	3.0
	ELECT	'B'		BRK	1	207	3.2
	TELEPH	'B'		BRK	1	207	3.0
	ELECT	'C'		BK	1	206	3.0
	TELEPH	'C'		BRK	1	206	3.0
	COMM	'C'		BRK.	1	206	3.2
	TELEPH	'D'		BRK	1	206	3.2
	ELECT	'D'		BRK	1	206	3.0
	COMM	D		BRK	1	206	3.0
	CORE	HER D/D		Hochiki	1	266	4.0
	CORE	HER D/D		Hochiki	1	266	3.8
(+)	RETURN	SOUTH (LED)		Hochiki	1	265	3.8
	RET.	NORTH		Hochiki	1	265	3.8
21	ELECT.	A-B	(2)	BRK	1	204	3.0/2.0
	TELEPH	A-B	(2)	BRK	1	204	3.2/3.0
	COMM	A-B	(2)	BRK	1	204	3.0/3.0
	ELECT	C-D	(2)	BRK	1	205	3.0/3.2
	COMM	C-D	(2)	BRK	1	205	3.0/3.0
	TELEPH	C-D	(2)	BRK	1	205	3.2/3.0
	CORE	HER D/D		Hochiki	1	264	3.4
	CORE	HER D/D		Hochiki	1	264	3.4
(+)	RETURN D/D	North LED		Hochiki	1	263	3.4
	RETURN D/D	South		Hochiki	1	263	3.4
	PASS ELEV.			BRK.	1	020	3.2
	FREIGHT ELEV.			BRK	1	020	3.0

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
FSD, J. Carrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED 8-15-00
CONTRACT # S/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Courtesy S/Contract - Preventive Maintenance on smoke detectors all areas floors 22/21st Fl. -
(+) = 22nd + 21st Fl. LED's to replace (light indicators N/G). - to continue. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED 22350

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREAS	S/D	CABLE	XTNDR	TEST SENS
24	ELEV. Lobby Pass	BRK	2	001	3.0
	COMM A	BLK	2	172	3.0
	ELECT A	BLK	2	172	3.2
	TELEPH A	BLK	2	172	3.0
	COMM B	BLK	2	172	3.2
	ELECT B	BLK	2	172	3.0
	TELEPH B	BLK	2	172	3.0
	RETURN D/D NORTH	Hochiki	2	230	3.4
	RETURN D/D SOUTH	Hochiki	2	230	3.2
(*)	FREIGHT ELEV.	BRK	2	001	4.0 (*)
	COMM C	BLK	2	171	3.0
	ELECT C	BLK	2	171	3.2
(*)	TELEPH C	BLK	2	171	3.4 (*)
	TELEPH D	BRK	2	171	3.0
	ELECT D	BLK	2	171	3.2
	COMM D	BLK	2	171	3.0
	CORE MEA. D/D	Hochiki	2	231	3.2
	CORE MEA D/D	Hochiki	2	231	3.4

47 E.M.R. AREA S/D (X2) UNITS RETESTED DUE TO SMOKE CONDITION AS BLD MANAG. REQUEST. – SENSITIVITY CHECK / NORMAL LEVEL (3.0 SENS. FIRING DOTC). – UNITS DIDNT ACTIVATED POSSIBLE CAUSE TO AIR FAN'S BLOWN ON FLOOR PUSHING AIR / SMOKE AWAY FROM UNITS. SUGGESTED TO INSTALL ONE (1) EXTRA UNIT CENTER OF ROOM – DUE TO SIZE OF ROOM. –

15 STROBE PANEL (Replaced) INSTALLED (2) NEW 12VOLTS BATTERIES. – PANEL RESET BACK TO NORMAL. –

INVOICE TO: 7 W.T.C. Silverstein Prop. N.Y.C. F.S.D.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / Carlos Tavares	8-9-00
	DATE SCHEDULED: 8-9-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12VOLT BATTERIES	
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Continuing Prev. Maintenance 24th Fl. All Areas S/D. As Listed Above. SENSITIVITY TEST / CHECK. – NOTE: UNITS (*) TO BE RETESTED / SENS. TO BE TO HIGH AS PER LOCATION. – Also check's done on 47th Fl as Bld Request – & Repairs on 15th Fl. AFL. Strobe Panel's Batteries Replaced due to low output voltages. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22349

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				S/D	CABLE	ADDR	TST CLEAN
25	ELECT	B		BLK	2	174	3.2
	COMM	B		BLK	2	174	3.0
	TELEPH	B		BLK	2	174	3.0
	PASS ELEV.			BLK	2	002	3.2
	FREIGHT ELEV			EDWDS	2	002	3.0
	COMM	A		BLK	2	174	3.2
	ELECT	A		BLK	2	174	3.0
	TELEPH	A		BLK	2	174	3.0
	ELEC	C		BRK	2	173	3.2
	COMM	C		BLK	2	173	3.0
	TELEPH	C		BLK	2	173	3.0
	TELEPH	D		BLK	2	173	3.0
	ELECT	D		BRK	2	173	3.2
	COMM	D		BLK	2	173	3.0
	RETURN D/D	NORTH		HOCHIKI	2	232	3.4
	RETURN D/D	SOUTH.		HOCHIKI	2	232	3.4
25	CORE	HER D/D		HOCHIKI	2	233	3.4
	CORE	HER D/D.		HOCHIKI	2	233	3.2

16 STROBE PNL Trouble / check's Dove DC. Replaced / SIGNAL output. – OK.

15 STROBE PNL: BATTERIES NEEDED (2) 12V (BACK UP UNITS)

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES C. TAMORES	F.S.D
	DATE SCHEDULED: 8-8-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING

Century Yearly (2) TEST Sensitivity Cleaning of Smoke Detectors units on 25th Fl. All addr as listed. – Also repairs on 16th + 15th Fl. STROBE PNLS. – (2) Batteries to be replaced on 15th Fl. (STROBE PNL)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

90405

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	S/C 00 818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		8-2-00	A.M.	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
5			387 Bulbs (Bypass PNL'S) -	N/C		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8 A	4 30						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

SERVICE DATE: 8-2-00

CUSTOMER SIGNATURE: Sean O'Keeffe

I & T COMPLETE ☐

CALL COMPLETE ☐

WILL RETURN ON

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Status Repairs. ~~Troubleshooting~~ - Trouble.

SERVICE PERFORMED As per contract - Troubleshooting / Repairs done as:
45th Fl Tamper S/W 2-147 Transponder - Reset O.K.
45 Fl Tamper S/W 1-139 Transponder - Reset O.K. ..
34th Fl W/Flow S/W. 2-099. Transponder - Reset O.K -
20th Fl Tamper S/W 1-143 Transponder - Reset OK -
All Units Located in 'B' Riser Stair Standpipe -
Also Replaced (5) Lamps/Bulbs at F.C. Station Bypass Panel's / Floor's -
NOTE: Live Test / Solomon Floors 42+43rd A.C. Shutdowns - Postponed for New Date

WORK REMAINING After Hours as per Mr. J. Marzano / Mr Campbell - Solomon Smith Barney
+ Perlman Wakefield. - Firefly will be notified. -

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED 90404

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
SILVERSTEIN PROPERTIES -
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
R.T.		S/C 10 818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		8-1-00	AM			J. TORRES. F. ROSAZIO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
15			7387 Lamps Display F.C.S.	N/C		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8 AM	4:30						

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8-1-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED SERVICE CONTRACT. —

SERVICE PERFORMED As per contract checked/repairs on 36th Fl. page. - Tracing wiring found open wires (broken) by speaker/strobe (North west wall). - Also checked for intermittent 7232 P.O. at F.C. station 9th Fl. page / Repairing I.C. 4512 Replaced - Back to operation. - Fire Command Station Display Lamps (Burned out) Replaced 7387 Type - (11) Circuits replaced) under trouble status. - (4) 7387 Clear Alarm status - Replaced back to operation. -
NOTE: As per conversation with Mr. Jerry Manzano Customer Walkfield - Schedule with B. Sprinkle TEST / Live Shutdowns for 42 & 43 Fl. as requested by D. Trevino Fireguard. - By Tomorrow 8-2-00 / 9:00 AM. -

WORK REMAINING Continue S/C. —

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ________ X ________ Date

FIRE SERVICE INCORPORATED 90403

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
Silverstein Properties
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
L.T.	S/C 00 818				T.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-31-00	AM	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			(12 VLT) Batteries Strobe Pnl AFC100	6995		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8AM	9AM	3:30 PM						

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 7-31-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/Contract - Repairs -

SERVICE PERFORMED As per Contract / Repairs done on 45th Fl Strobe panel (3) panel AFC-100 Intermittent. - Signal Trouble - Panel Removed - Changes done/updated - Installed wiring back to operation, also Batteries (2) units 12 VLTS. Replaced). - Also as per Status Check Repair on 22nd Fl. AFC 101 panel (2) - Trouble Condition Both Side - Panel - - Output Voltage Check Adjusted. - Low. - Back to operation. - North Side Unit Found Loose Connection on Unit Ceiling Type. - (East Side.) Area - Repairing back to operation. -
System Ock / Restored back to operation

WORK REMAINING Continue S/C.

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED 22347

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			Cable	Addr			
45	D/DETECTOR		4 -	125	= WIRES PULL OUT		
					NOT LONGER · TTB		
45	D/DETECTOR		4 -	126	= WIRES PULL OUT · TTB		
					NOT LONGER		
44	S/SYS		4 -	228	WIRES PULL OUT TTB		
					NOT LONGER -		
45	FAN SHUTDOWN/		4 -	345	WIRES PULL OUT		
	STATUS TF45·2				NOT LONGER · TTB		
45	FAN SHUTDOWN		4 -	350	WIRES PULL OUT TTB		
	STATUS				NOT LONGER		
45	STAGE PULL/TRANS		4 -	359	E.O.L. DEVICE WRONG.		
	(PAD-2)				VALVE CONNECTED -		
					(UNIT REWIRED) PAD-2		
43	TAMPER SW		4 -	459	WIRES PULL OUT · TTB		
					NOT LONGER		

INVOICE TO: 7W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES H. ROSARIO Zingera	F.S.I
	DATE SCHEDULED 7-26-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	930 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) P. Keller (For J Corp)
CUSTOMER SIGNATURE (For J Corp)
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

DATE TIME NAME

SERVICE PERFORMED & REMAINING: AS PER CONTRACT - CHECK / TROUBLESHOOTING / CORRECTING ABOUT CIRCUITS / TTB'S CHECK FOR WIRING / PULL OUT UNITS NOT LONGER ON FIELD DELETED. - ALSO CORRECTED WIRING ON PAD-2 STAGE PANEL ADDED ON 45 FL. WRONG END OF LINE RESISTOR (1.8) FOUND ON RELAY INTERFACE TERMINAL) - PLACED 3.9K EOL. & UNIT REWIRED. - CHECK BACK TO NORMAL. - ALSO AS PER MR. R. WALL FIRECOM FOREMAN REEVALUATED FIRE COMMAND STATION BLUE PRINT (WITH EXISTING LABELING / WIRING ROBERT'S / FUNCTIONS

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

- COPY RETURNED TO SHOP / FIRECOM -

FIRE SE⌐VICE INCORPOR⁄ ED
80966

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C. N.Y.C. -

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T.	S/C 00818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-25-00	A.M.	C. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

SERVICE DATE: 7-25-00

CUSTOMER SIGNATURE: P. Kell (F. J. Lewis)

WILL RETURN ON:

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/Contract - Repairs Strobe Lights / Panel's - CKT'S - 32 Fl. Ground Fault Condition. - 47 Fl. S/Detector Area. -

SERVICE PERFORMED Contract Repairs 32nd Fl. Strobe Lights CKT #1 - Trace Located Negative Wire / Grounded on Existing Ceiling Speaker / Strobe 'White' unit. - Which were Removed to Install New Ceiling tiles. - Corrected / Restored CKT back to Normal / Tested O.K. - Also Check 47 Fl. 'B' Communication Closet S/Detector Not Operating. - N/G. - Unable to Reach Unit due to Ceiling Pipes 'on way'. - Access Must be Provided By Bld. - to Cut Hole on Wall near S/D. top Portion in order to Remove Unit Check Base Wiring. -

WORK REMAINING Contract S/C.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service, Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FCI 155

FIRE SE⌐VICE INCORPOR/ ED 76790

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
PV.		S/C 00 818				
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		7-19-00	OJ			J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8N	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-19-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [illegible]

SERVICEMAN SIGNATURE: [illegible]

PROBLEM—AS DESCRIBED Service Contract -

SERVICE PERFORMED As per Contract performed Check / Troubleshooting Repairs on Strobe panel Unit on 32nd Fl. Check for CKT #1 Ground Fault. - E.O.L. placed at terminal. - (Further Troubleshooting needed on CKT #1 in order to locate Unit/Units grounded. -) Flow Rehabilitation / Renov. - Also assisting Tech Robert Dalosky checking activation outputs 'DRY' - on Floor's 40 thru 43 At Lugates Shop / R.W. - Firecom - See Print Out - Submitted by Tech. - Smoke Det. Activating Varing CKTS. / Areas on Floors -

WORK REMAINING Continue Contract -

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______

FCI 155
REV 6/86

FIRE SE[illegible]VICE INCORPOR[illegible] ED   76789

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
T[illegible].		SC 00 818				F.S.?
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		7-18-00				J. Torr[illegible] / F. Rosa[illegible]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800	900	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-18-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [illegible] (F. J. Carp)

SERVICEMAN SIGNATURE: [illegible]

PROBLEM—AS DESCRIBED Service Contract. / Strobes lights [illegible] trouble —

SERVICE PERFORMED As per contract performed check's repair on 15th Fl. strobe panel trouble activation. — AFC 150 unit upgraded / P.C. and batteries replaced voltage increased to 28.99 VDC. — Backup. — Normalized also strobe light CKT #1 on 12th Fl. panel — found that wiring loose. — Corrected. — Units back to operation. — AFC 101 #1 system [illegible] back in operation. —

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name X

Date

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22345

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		TST CLEAN	DEVICES: TTB'S		STROBE
6	'B' COMM.		✓	TTB	(1)	AFC 101 (1)
	CORE HER		✓	TTB	(1) D3 C3	
	'B' STAIR			TTB	(1) D1 C1	
5	W. HER (SCHMN)		✓	TTB (1) D3 C3		
	W. HER (SCHMN)		✓	TTB (1) C3		
	'B' STAIR		✓	TTB (1) D1 C1		
4	'B' COMM		✓	—		AFC 100 (1)
3	'B' STAIR		✓	TTB (1) D1 C1		
	'B' COMM.		✓			AFC 100 (1)
2	FREIGHT AREA		✓			AFC 100 (1)
1	Lbby / GROUND		—			
	PUMP RM		✓	TTB (1) D1 C1		
	PUMP RM		✓			AFC 100 (1)

———→

3 F.C. STA. BYPASS PNL. RELAMP. — Replaced (4) LIGHTS —

INVOICE TO: W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D
F. ROSARIO	DATE SCHEDULED: 7-12-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
3	LAMPS 387 / BYPASS PNL.	N/C

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): P. KINNEY (for J. Gonzalez)
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature] [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT.
PREV MAINTENANCE ON TTB'S RISER & STROBE PANEL'S AS LISTED
VOLTAGES / SIGNAL / RELAYS CHECKED. WIRING SECURED. BATTERIES CHECK.
ACK / RESETTING BACK TO OPERATION —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22346

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREAS	TTB'S		STROBS PNL	TST CLEAN
11	'B' COMM			AFC 101 (2)	✓
				(D) BATTERIES Replaced).	
10	N/A	UNAVAILABLE —			
9	N/A	UNAVAILABLE —			
8	'B' COMM			AFC 101 (1)	✓
7	'B' COMM			AFC 101 (1)	✓
7	CORE HER	TTB (1)	D1C1		✓
6	'B' COMM			AFC 100 (1)	
6	'B' STAIR	TTB (1)	D1C1		✓
6	ENG. HEA RM	TTB (1)	D3C3		✓
5	'B' COMM			(D) AFC 100 (1) Disable Batt	
5	'B' STAIR	TTB (1)	D1C1		✓
5	W. HER.	TTB (2)	D3C3		✓
4	'B' COMM			AFC 100 (1)	✓
3	'B' COMM			AFC 100 (1)	✓
3	'B' STAIR	TTB (1)	D1C1		✓
2	FREIGHT AREA			AFC 100 (1)	✓
1	PUMP RM	TTB (1)	D1C1		✓
1	PUMP RM.			AFC 100 (1)	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED 7-11.00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VOLT 7AH BATTERIES	$69.75

PREVENTIVE MAINTENANCE CONTRACT

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

CUSTOMER NAME (PRINT) PAT KINSELLA (For J. Cooryn)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING S/CONTRACT -
PREVENTIVE MAINTENANCE ON TTB'S Units / Strobe Pnl's Risers
Voltage / Signal's Check - Batteries Back Up (Replaced) (2)
(11th Fl Listed) - System Restored Back to operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22344

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS FLOOR			DEVICES TTB'S		STRB PNL	TEST CLEAN
20	CORE HER			(1)	AFC 100	✓
19	CORE HER			(1)	AFC 100	✓
18	CORE HER	(4)	TTB D1C1	(2)	AFC 100	✓
		(1)	TTB D3C3			
17	CORE HER			(1)	AFC 100	✓
16	CORE HER			(1)	AFC 100	✓
15	CORE HER	(2)	TTB D1C1	(2)	AFC 100	✓
		(1)	TTB D3C3			
14	CORE HER			(1)	PA92	✓
13	'B' COMM			(1)	AFC 100	✓
	'C' ELECT			(1)	AFC 101	✓
12	CORE HER	(2)	TTB D1C1			
		(1)	TTB D3C3			
12	'B' COMM.			(2)	AFC 101	✓
(*) 22	STROBE PNL "SOUTH"	(2) BATT. REPLACED -				12 VOLT 7 AMP

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TOLLE	F.S.I
C. TABAREZ	DATE SCHEDULED 7-5-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLT/7 AMP. (STROBE PNL).	@ 69.95

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT) SILVERST [illegible]
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature] [signature]

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE - AS PER CONTRACT CHECK TEST VOLTAGES / SIGNAL'S ON TTB'S RISERS & STROBES PANEL'S ON FLOORS ABOVE LISTED. - SYSTEM ACK/RESET - IN OPERATION
* 22ND FL. (2) BATTERIES REPLACED. - OK. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22343

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR				TTB'S		STROB/PUL	TST CLEAN
26	CORE HER				(1) PYRO'S		✓
25	CORE HER				(1) AFC100		✓
24	CORE HER.		(2) TTB'S D1C1 (1) TTB D3C3		(1) AFC100		✓
23	N/A AT THIS TIME (MAYOR'S OFFICE) -						
22	'B' COMM				(2) AFC101 (B) BATT. NEEDED (1) SET.		✓
21	CORE HER		(1) TTB D1C1 (1) TTB D3C3		(1) AFC100		✓

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres E. Tabares	F.S.I.
	DATE SCHEDULED 7-3-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature] [signature]

SERVICE PERFORMED & REMAINING S/CONTRACT - PREV. MAINTENANCE CHECK ON TTB'S RISERS PANEL'S UNITS. - / STROBES LIGHTS PANEL'S ON FLOOR'S ABOVE LISTED. - VOLTAGE / SIGNAL'S READING TAKEN - / WIRING CHECK - BATTERIES CHECK.
AS: 22nd Fl. STROBE PNL 'SOUTH' AFC101 NEEDS (2) BATTERIES 12 VLTS. 7 AMP. - TO REPLACE. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22341

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES			
	'B' COMM. (CLOSET)		TTB'S		STROBE	TST CLEAN
31	'B' COMM		(1) TTB 22 A/B D3C3	AFC 100 (1)		✓
			(2) Battery Replaced Disabled			
30	'B' COMM			(1) AFC 100		✓
			(2) Batteries Replaced OK			
30	CORE HEL		(1) TTB D1C1 #13 A/B - Key Calling Repaired			
29	'B' COMM.			AFC 100 (1) OK.		✓
28	'B' COMM.		(1) TTB D3C3 #21 A/B	AFC 100 (1)		✓
27	CORE HEL		(1) TTB #12 A/B	Ryco 3'SPH OK.		✓
32	Floor Page / Back to Normal (Required) (Floor Renovated)					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres, C. Tabares	F.S.D.
	DATE SCHEDULED: 6-28-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8V
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	BATTERIES 12VLTS.	69.95
—	STROBE PANEL (AFC 100)	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature] / [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT

Check/Repair on TTB'S / Strobe panel's on Prev. Maintenance on floors listed above also Batteries Replaced as needed (Low Voltage) 2 units on 30th Fl Strobe panel & 31st Fl.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

NOTE: 31st Fl. Panel Disabled due to Shorted CKT 'A'/B on Strobe Loop's —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22342

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				TTB'S		Strobe PUL
35	'B'	Comm				Strobe PUL. ✓
						(2) Batteries Replaced
33	B	Comm				(2) Batt. Replaced Strobe PUL
33	Core	Het	(1) TTB D C2			✓
			# Key Cylinder Needed.			
32	'B'	Comm	(1) TTB D3C3			(1) Strobe PUL
			# 23A/B			AFC 100 ✓
31	'B'	Comm.				(1) Strobe PUL ✓
						(2) Batt. Used. AFC 100
37	'B'	Comm				(1) AFC 100 Strobe ✓
						(2) Batt. Replaced OK
36	'B'	Comm				(1) Strobe PUL ✓
						(2) Batteries Replaced

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / C. Tabares	FSI
	DATE SCHEDULED: 6-27-00
CONTRACT #: SKC00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	Batt. 12 Volts.	69.95
1	Strobe PUL (AFC 100)	

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING S/C.
Prev. Maintenance Check / Repairs on TTB'S & Strobe PUL'S on Item Above Listed. — Batteries Replaced Also. — (Low Voltage) —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22340

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES		STROBES	TST MAINT
			TTB'S			
38	FREIGHT AREA		TTB 26A/B (1)		AFC 100 (1)	✓
	'B' COMM.		D3-4		* BATT.	NEED
37	FREIGHT AREA		TTB 25 A/B		AFC 100 (1)	✓
	'B' COMM		D3-4 (1)		* BATT.	NEED
36	FREIGHT AREA				AFC 100 (1)	✓
	'B' COMM				* BATT.	NEEDED
36	SOUTH SIDE		TTB/OPP. SOUTH (1)			✓
	(WALL CLOSET)		D1-2 # 15 A-B			
35	FREIGHT AREA				AFC 100 (1)	✓
	'B' COMM				* BATT.	NEEDED
34	COPY PHOTO RM		TTB D3-4		AFC (100)	✓
	'B' COMM.		24 A/B		AFC (102)	✓
	CONF/RM EAST				AFC (10)	✓
33	FREIGHT AREA				AFC 100	✓
	'B' COMM.				* BATT.	NEEDED
33	CORE	HER	* TTB (N/A) PENDING.			

INVOICE TO: WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED 6-21-00
CONTRACT # S/C 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING S/CONTRACT.
PREV. MAINTENANCE CHECK OF TTB'S [illegible] RISER'S & STROBE PNL'S
ON FLOOR'S 38/33 AS LISTED LOCATIONS. –
NOTE: BATTERIES (LOW VOLTAGE) NEEDED ON 38/37/36/35/33 FLOOR'S (SEE ABOVE)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

to be Continued. —

FIRE SERVICE INCORPORATED

22335

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR				TTB'S		STRPAN	TST MAINT
44	FREIGHT ELEV.						
	'B' COMM				(1)	AFC 100	✓
43	FREIGHT AREA			TTB	(1)	PAD2.	(1) ✓
	'B' COMM			29A/B		(SPRE)	✓
				D3/4			
42,	OPPSITE RECEPTN.			TTB	(1)		✓
	CLOSET/WALL			D1/2			
	FREIGHT AREA			TTB	(1)		✓
	'B' COMM.			D3/4	(1)	PAD2	✓
				28A/B		(SPRE)	
41	FREIGHT AREA						
	'B' COMM.				(1)	PAD2	✓
						(SPRE)	
40	FREIGHT AREA			TTB	(1) D3/4	PAD2	(1) ✓
	'B' COMM.			27A/B		(SPRE)	
						AFC 100	
39	FREIGHT AREA			[illegible]		PAD2	(1) ✓
	'B' COMM.					(100)	
39	OPP. AUDTM ENT.			TTB	(1) D1/2		✓
	(WALL CLOSET)						

INVOICE TO: 2W.T.C.
N.Y.C.
J. CARRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	FS-2
	DATE SCHEDULED 6-20-00
CONTRACT # 5/C00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	810 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ________ DATE ________ TIME ________

SERVICE PERFORMED & REMAINING 5/CONTRACT.
(A) PREVENTIVE MAINTENANCE CHECK FOR OPERATING VOLTAGE LEVELS/WIRING ON TTB'S RISER & STROBES PANEL'S AS LISTED (ABOVE). – UNITS ALSO WERE DUSTED OFF/CLEANED. – OLD WIRE (DEVOTED) PULLOUT CABINETS. –
TO BE CONTINUED. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22339

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR							
48	Plant Mgr		Strobe Panel Check. O.K.				
			(Key cylinder needed)				
			— 0 —				
47	W. Mgr.		TTB Data 3-4				
			#31A - 31B	((Freight)			
47	A Tenant 'C' Steps		TTB Data 1-2	— Strobe Pnl			
			#19A - 19-B	{ AFC 100			
			— 0 —				
46	'B' Comm. (Freight)		Strobe Pnl AFC 100 (*)				
			(1) Out out to Repair —				
			Key cylinder broken.				
			— 0 —				
45	B Comm (Freight)		TTB D 3+4	Strobe Pnl			
			# 30A - 30B	P/D 2(1)			
			TTB D 1+2	AFC 100 (1)			
			(Wall closet)	AFC 100 (1)			
			# 18A - 18B				
45	Freight Area Lobby		S/D Replaced Installed				
	(Previously Removed) Const.						
	Back in operation —						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO:
7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F. J.
	DATE SCHEDULED: 6-14-00
CONTRACT #: SFC00818	TYPE OF SYSTEM: 3500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM) PM	430 AM (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME _____ DATE _____ TIME _____

SERVICE PERFORMED & REMAINING: S/Contract. —

As per contract started preventive maint on TTB's with risers from 48 Fl. to 45 (see list) above — Also check strobes pnl's on floors as listed. — System ock / restored back to operation /

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22338

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS **DEVICES**

FLOOR							
39	STROBE PNL TABLE - REPAIRS -						
	(2) 12VOLT BATTERIES REPLACED. -						
	AFC 100 CKTS CHK O.K. -						
31	STROBE PANEL TABLE - REPAIRS						
	(2) CKTS A-B - DISABLED DUE TO						
	RENOVATION. - TO RESTORE. -						
22	STROBE PNL TABLE - SIGNAL TROUBLE						
	REPAIRS - O.K.						
47	(3) STROBE'S LIGHTS S.W. CORNER CORRIDOR						
	WIRING CORRECTED & ALSO REPAIRED						
	BROKEN P.C. TERMINAL ON STROBE UNIT.						
	CHECK/TEST O.K. -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED 6-13-00
CONTRACT # S/C N 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12VLT.	

CUSTOMER NAME (PRINT) SILVERSTEIN

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING: [illegible] CHECK/TEST REPAIRS ON STROBES UNITS/PANELS AS LISTED ABOVE. - 39 FL. (2) BATTERIES REPLACED ALSO [illegible] UNIT. - ASSISTED F.S.D. AS REQUESTED TEST CHECK DOOR RELEASES ON 24 FL. - - SYSTEM OK/RESETED BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED 76788

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
RT.	S/C00 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		6-7-00	AM	J. TORRES / F. ROSARIO / D. MARCUS

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
1			MANUAL pull STATION HIRTANE	$40.00		
			— CAT # 47092-0260 —			

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 6-7-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED: S/CONTRACT / PREV MAINTENANCE — Moroni Clanding

SERVICE PERFORMED: As per Contract check / any Repairs done on 37th Fl. Warden's Station — Call s/w Replaced - Audio O.K. — 36th Fl. Manual pull station 058 - 'A' Stair Replaced Installed new one (old defective). — Check O.K. — 47th Fl Roof Plant Replaced Exchanged AFC 100 Panel Strobe pnl (defective old one) Install wiring Tested O.K. - Back in operation. — Strobe panel modification update performed by Firecom Eng. Dept. — 31st Fl Page / Speaker Trouble Condition due to open CKT / Found Electrician Forest Elect working on it. — Floor Under Construction — Spliced / O.K. / Reset Back to operation

WORK REMAINING —

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name X

Date

FIRE SERVICE INCORPORATED

76794

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
R.T.		S/C 00 818				F.S.D.
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		6-6-00	A.M. —			J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 6-6-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature] [signature]

PROBLEM—AS DESCRIBED S/CONTRACT. — MAINTENANCE.

SERVICE PERFORMED (1) As per F.S.D. requested check door release on 24th Fl. Found freight door entrance North (wood) — not wiring existing for class 'E' fire alarm release for interconnection. — As well South pass elev. lobby entrance South door (wood). — 'A' stair exit (solenoid) defective / strike to be replaced. — (BLD operating). —
(2) Also as per contract check strobe pull's on 41st Fl. — 40th Fl. 39th Fl. for proper operation — Found O.K. — as well 16th Fl and 14th Floor. —
(3) Repair line on warden's phone station 41st Fl. — (call s/w replaced) communication check OK

WORK REMAINING (*) 45th Fl. elev. S/D 012 on alarm due to 'cutting' machine (tiles installing by elev. freight lobby) causing S/D activation / unit removed BLD. notified / F.S.D. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date:

Name: X

FIRE SERVICE INCORPORATED

26065

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				SPK/Page	W/STA	STROBE
32	Soloan Area			✓22	2	22
31	Soloan Area			✓25	2	25
30	Soloan Area			✓27	2	27
29	Soloan Area			✓22	2	22
28	Soloan Area			✓27	2	27
27	Soloan Area			✓29	2	29
26	Soloan Area			✓27	2	27
5	"		"	✓	5	
* 4	"		"	✓20	1	19*
* 3	Soloan Area			✓	–	-(2) 9*
2	"		"	✓	–	4
1	"		"	✓	–	1
48	Roof/Plant			✓	✓	✓
* 47	Soloan Area			✓	✓	✓-(3)*

Strobes Light to be replaced N/G

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.A
	DATE SCHEDULED: 6-3-00
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #: -	PO #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8 AM	4:30 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): [illegible]
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Per Contract / Prev. Maintenance Test for proper operation activation of speakers audio/page - Communications W/station phone + strobes lights on floors listed above (Soloan Area). — Also retested 48 + 47 floor's page speaker's / W/stations due to previous malfunction. - NOTE: 4th fl. strobe's 1/2 CKT active need's to be troubleshooted - 3rd fl. (2) lights

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 76786

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
C.I.	S/C00818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5-31-00	AM.	J. Torres / T. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			-

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5-31-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED SERVICE CONTRACT / PREV. MAINTENANCE / REPAIRS. —

SERVICE PERFORMED 14th Fl. STROBE PANEL Trouble 'A' CKT. - TRACED FOUND UNIT STROBE LIGHT OPEN WIRING NORTH CORRIDOR. - REPAIRED/TESTED BACK TO NORMAL. - 16th Fl. STROBE PANEL (HER) REPAIRED. - P.C. MODIFIED UPDATED — due to False Trouble Intermittent. - 'A' & 'B' CKT'S RESTORED BACK to normal. — TEST O.K. - 41st Fl. strobe panel PAD-2 Trouble due to Battery discharged / to be Replaced For [illegible]. Also As per F.S.I. Requested Check For DOOL [illegible] ACTIVATION on Several locations as 3rd / 14th / 27th / 29 O.K. —

WORK REMAINING 41st STROBE PANEL Replace Batteries. —

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____ Date ____

FIRE SERVICE INCORPORATED

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

76787

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.V.		S/C00 818				F.J.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		5-30-00	AM			J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	4:30						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5-30-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED S/Contract Repairs. – Prev. Maintenance. –

SERVICE PERFORMED 45 Fl. Strobe Pnl ~~[illegible]~~ AFC 100 Fdr B Loop - Shorted to be traced. Strobe lights / zone bypassed E.O.L. - Temporarily. – I[illegible] N/[illegible]. –
41st Fl. Replaced installed (2) new 12 volts. Batteries PAD 2 Panel (old [illegible] dry out). – Trouble [illegible] back to normal. –
47th Fl. Check TTB's & Data 2 – For W/Stations & Floor Page inoperable. – Replaced Mother Board / 792 P.C. – For outputs voltages. – Warden's station repaired check O.K. – Floor page check O.K. –
48th Fl. Roof Plant Repaired W/Stations / P.A. Page. Check/Test O.K. –

WORK REMAINING Continue S/C. Repairs. –

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______ X

FIRE SERVICE INCORPORATED

22337

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	'B' Riser		TAMPR		RESET	CHK
47			155		OK	✓
46			154		OK	✓
45			147		closed	✓
44	'B'	Riser	146		OK	✓
44			146		OK	✓
44			142		OK	✓
43			140		closed	✓
42	'B'	Riser	139		closed	✓
41			138		OK	✓
40			137		OK	✓
39			136		OK	✓
38			135		OK	✓
37			134		OK	✓
36			133		OK	✓
35	'B'	Riser	132		OK	✓
34			131		OK	✓
33			130		OK	✓
32			129		closed	✓
31			128		closed	✓
30			127		closed	✓
29	B	Riser	126		OK	✓
28			125		OK	✓
27			124		OK	✓
26			123		OK	✓
7			130		OK	✓
6			129		OK	✓
5			128		OK	✓
3	'B'	Riser	126		OK	✓
3			125		OK	✓
2			123		OK	✓
2			123		OK	✓
1			123		OK	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F-J-7
	DATE SCHEDULED: 5-24-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature] [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING
Q.I. per F-J-7 request / BLD retested. Check resets on tampers S/W on 'B' Riser as listed - (Print out presented). - System ck / inspected as requested. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED   22336

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	'B' Riser		THPR		Reset	CHK
25			122		OK	✓
24			121		OK	✓
23			120		OK	✓
22			150		OK	✓
21	'B' Riser		149		OK	✓
21	(BE/ND)		149		OK	✓
20			146		OK	✓
20			145		OK	✓
20			144		OK	✓
20			143		OK	✓
19			142		OK	✓
			(ADDED)			
18	'B' Riser		141		OK	✓
17			140		O.K	✓
16			139		OK	✓
15			138		OK	✓
14			137		OK	✓
			(ADJD)			
13	'B' Riser		136		OK	✓
12			135		OK	✓
11			134		OK	✓
10			133		OK	✓
9	'B' Riser		132		OK	✓
8			131		O.K	✓
39	Strobe PNL (Updated/Modified) OK					
			AFC 100			
	Back in operation. —					

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / F. Rosario	F.S.D	
	DATE SCHEDULED: 5-23-00	
CONTRACT #: 5/600818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean OKeeffe.

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME   DATE   TIME

SERVICE PERFORMED & REMAINING

(1) As per F.S.D Requested - do Prev. Maintenance Check for Alarm/Alm Reset above Floor's Tamper's S/W on Standpipe 'B' Riser (List/Print out Report).

Also: Repaired Strobe PNL 39 Fl (Modification Update) Check OK —

(A) INACCESSIBLE ~~(B) MISSING~~ (C) DEFECTIVE (D) OTHER

Back in operation —

22334

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				P.A.
FLOOR	Areas		W/STA	SP/STB			P.A.
38	Solomon Bth		2	18			OK
37	Solomon Sml		2	21			OK
36	Solomon Smith		2	22			OK
	'A' B exit Manual p/l stn to Replace - S/W Broken. -						
35	Solomon Smith B		2	14			O.K
34	Solomon Smith B		2	20			OK
33	Solomon Smith B		2	23			OK.
	(1) S/Strobe (light n/g) Front of W.Hse - Unit to Replace —						

to be Continue

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7W.T.C Solomon Smith Barney, N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED 5-20-00
CONTRACT # s/c 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	11:00 AM PM	4:30 AM PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING: As per Contract, Continue Testing Activation of Audio page speaker and Strobes lights on Solomon Smith Barney Floors as listed above. — Communication Warden's phone stations. — Units available for test. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22333

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABK	ADDR	S/D	TST/Clean
3rd	ELECT	A		1	166	BLK	
	ELECT	B		1	166	D13	
	TELEP	B		1	166	BLK	
	COMM	A		1	166	BLK	
	COMM	B		1	166	BLK	
	FIREMEN ELEV			01	002	BLK	
	[illegible]						
	SECURITY CLOSET			3	048	IEL3	
	KITCHEN SUPPLY			3	042	EDWDS	✓
	WEST	MER AREA		3	006	PEC3T	✓
	WEST	MER	AREA	3	006	PEC3T	✓
	WEST	MER	D/D	3	040	EDWDS	✓
	WEST	MER	D/D	3	041	EDWD	✓
	WEST	MER D/D SUPPLY		3	040	EDWDS	✓
	WEST	MER D/D RET.		3	040	EDWDS	✓
3rd	RECEPTION AREA			1	077	D13	✓
	AREA S/D			1	077	D13	✓
	ELEV	S/D LOBBY		3	029	PEC3	✓
2nd	E.H.R.			3	005	PEC3T	✓
2nd	ELEV LOBBY			3	028	PEC3	✓
1st	M.ER	D/D		3	039	EDWD	✓
1	MER	AREA		1	012	PEC3T	✓
1	MER	D/D		3	037	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	I.J.D
	DATE SCHEDULED: 5-17-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/Contract Continued Prev. Maintenance on Smoke Detectors Units Floors 3rd/2nd/1st As Listed Above (Blown with Prong) Only. — System OK / Service Completed Back to Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22332

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA/CLOSET		CABLE	XTNDR	S/D	TST CLEAN
5	ELECT A		1	169	BLK	✓
	ELECT B		1	169	BLK	✓
	ELECT C		1	169	BLK	✓
	ELECT F		1	169	BLK	✓
	TELEPH A		1	169	BLK	✓
	TELEPH B		1	169	BLK	✓
	COMM B		1	169	BLK	✓
	FREIGHT ELEV		1	004	BLK	✓
	MAIN PASS ELEV		1	004	BLK	✓
	ROTO CLONE		3	013	PEC3T	✓
5	ROTO CLONE		3	013	PEC3T	✓
4	ELECT A		1	167	BLK	✓
	ELECT G		3	050	PEC3	✓
	TELEPH B		1	167	BLK	✓
	COMM B		1	167	BLK	✓
	FREIGHT ELEV.		1	003	BLK	✓
	PASS ELEV.		1	003	BLK	✓
	CHEF OFFICE		3	043	[illegible]	✓
	ELECT B		1	167	BLK	✓
4	TELEPH A		1	167	BLK	✓
44	SHUTTLE ELEV		4	018	PEC3	*
	MULTIPLE ALARMS (SENS UNIT) Replaced					
	BACK IN OPERATION. –					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Turner / F. Rosario	FJD
	DATE SCHEDULED: 5/16-00
CONTRACT #: SE 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: 5/[illegible] –
PREVENTIVE MAINTENANCE ON SMOKE DETECTION ON 5th/4th FL. (SEE ABOVE)
AS LISTED. ALSO REPAIR ON 44th SMOKE DETECTOR UNIT (4-018) ELEV. [illegible]
ALARMING UNIT REMOVED (REPLACED) FOR ANOTHER EXISTING UNIT BACK IN
OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

91421
#1

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC NEW YORK
N.Y

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP		U.P.S = 818				F.S.P
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		5-16-00	AM			C. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	9.30	11.30						
	AM	PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 5-16-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keefe

SERVICEMAN SIGNATURE: CARLOS FORERO

PROBLEM—AS DESCRIBED U.P.S MAINTENANCE / SERVICE CONTRACT

SERVICE PERFORMED Checked U.P.S System, Took Reading for inputs - out puts, Battery Voltage, U.P.S System (OK) Also cleaned Filters

BATTERY AMP .2
TOTAL BATTERY VOLTAGE = 140.7 V (#80 Batteries)
OUT-PUT HZ 62.5 HZ
LOAD #1 11.1

WORK REMAINING L #2 11.1

OUTPUT VOLTAGE 246.V A/C

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

X

Name ______ Date ______

FCI 155
REV 6186

FIRE SERVICE INCORPORATED
SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

91680

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York City

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Ricky Trivino	UPS SC 818				FSD

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		05/16/00		Marcos

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00	9:30	11:30						
AM	AM	AM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE

WILL RETURN ON

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Marcos Llaurro (?)

PROBLEM—AS DESCRIBED

UPS Maintenance / Service contract

SERVICE PERFORMED

Cleaned and checked UPS system for connections, input and output voltages readings and Battery voltages. Battery voltage range is 13.5 Vdc (normal range)

Battery Amp : 0.2 Amps
total battery voltage 140 Vdc
out put Hz : 62.5 Hz

WORK REMAINING

Load 1 : 11.0 Amps
Load 2 : 11.0 Amps
out put voltage 246 VAC

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name X Date

FIRE SERVICE INCORPORATED

22330

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR				W/STA	SP/STBES		P.A.
48	Solomon Smith B.			2	6		N/G.
47	"	"		2	17		N/G.
46	"	"		2	23		OK.
45	"	"		1	54		O.K
44	"	"	"	1	16		OK
43	"	"		1	OUT		OUT
					(UNDER CONST)		
42	"	"		2	20		O.K
41	"	"		2	23		O.K.
40	"	"		2	22		OK
39	"	"		2	24		O.K.

To be Continue

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. Solomon Smith Barney N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 5-13-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #:	P.O. #: -
CALL AUHTORIZED BY:	PHONE: / EXT:

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Douglas Mazzone
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

SERVICE PERFORMED & REMAINING: S/CONTRACT - CHECK TESTED AUDIO/VISUAL ACTIVATION ON SPEAKER'S / STROBES LIGHTS BY ALARMING M/STATION ON FLOOR'S 48 TO 39 AS LISTED. ALSO TESTED COMMUNICATION DEVICES - WARDEN'S PHONES. -
NOTE: SPKR'S / PAGE FLOOR'S 48 (PLANT + 47 E) DEFECTIVE N/G - TO BE

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

TROUBLESHOOTED - REPAIR AUDIO PAGE CKTS. -

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21309

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		CABLE	XTNDR	S/D	TST/CLEAN
35	ELECT A-B	(2)	2	196	BLK	✓
	TELEPH A-B	(2)	2	196	BLK	✓
	COMM A-B	(2)	2	196	BLK	✓
	ELECT C-D	(2)	4	049	EDW/BLK.	✓
	ELECT F		4	049	BLK	✓
	ELECT F1		4	049	PEC3	✓
	ELECT G		4	073	PEC3	✓
	SECURITY		4	073	PEC3	✓
	ELEV. PASS		2	012	BLK	✓
	FREIGHT ELEV		2	012	BLK	✓
	ELEV. SHUTTLE		4	001	PEC3	✓
	W. HER Area		4	025	PEC3T	✓
	W. HER D/D.		4	097	EDW45	✓
34	ELECT A-B	(2)	2	194	BLK	✓
	ELECT C-D	(2)	2	193	BLK	✓
	TELEPH A-B	(2)	2	194	BLK	✓
	TELEPH C-D	(2)	2	193	BLK	✓
	COMM A-B	(2)	2	194	BLK	✓
	COMM C		2	193	BLK	✓
	ELECT DW		2	193	BLK	✓
	ELECT F		4	048	PEC3	✓
	ELECT F1 A/C ROOM		4	048	PEC3	✓
	ELECT G		4	072	PEC3	✓
	SECURITY		4	072	PEC3	✓
	FREIGHT ELEV		2	011	BLK	✓
	ELEV. LOBBY		2	011	BLK	✓
	ELEV. SHUTTLE		4	000	PEC3	✓
	CORE HER Area (3)		4	252	PEC3T	✓
	CORE HER D/D.		2	251	HOCHIKI	✓
	CORE HER D/D.		2	251	HOCHIK.	✓
	W. HER Area		4	024	PEC3T	✓
	W. HER D/D		4	096	EDW45	✓
	KITCHEN EXH.		4	121	EDW45	✓

INVOICE TO: WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRE / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 4-19-00
CONTRACT #: S/00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [illegible signature]
SERVICEMAN SIGNATURE: [illegible signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT.
Quarterly Prev. Maintenance Smoke Detection on Floors 35th/34th (Silverstein) - Areas Listed - System ACK/RESET - Lobby ... Checked D.R. / Signals / Page O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21311

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				Cable	Xmod	S/A	Test
33	ELECT	A-B	(2)	2	191	BLK	✓
	TELEPH	A-B	(2)	2	191	BRK	✓
	COMM	A-B	(2)	2	191	BLK	✓
	ELECT	C-D	(2)	2	192	BLK	✓
	TELEPH	C-D	(2)	2	192	BRK	✓
	COMM	C		2	192	BLK	✓
	ELECT	D.W.		2	192	BLK	✓
	ELECT	F		2	018	PEC3	✓
	ELEC 'G' CLOSET			3	011	PEC3	✓
	SECURITY CLOSET			3	011	PEC3	✓
	ELEV LOBBY PASS			2	010	BLK	✓
	FREIGHT LOBBY ELEV			2	010	BLK	✓
	SHUTTLE ELEV.			3	027	PEC3	✓
	CORE MEV	AREA	(3)	2	250	PEC3T	✓
	CORE MEV D/D		(2)	2	249	Hochiki	✓
	W. MER.	AREA	(2)	3	004	PEC3T	✓
	W. MER	D/D	(2)	3	036	EDWDS	✓
32	PASS ELEV.			2	009	BLK	✓
	FREIGHT ELEV.			2	009	BRK	✓
	ELECT	A-B	(2)	2	190	BLK	✓
	TELEPH	A-B	(2)	2	190	BRK	✓
	COMM	A-B	(2)	2	190	BRK	✓
	ELECT	C-D	(2)	2	189	BLK	✓
	TELEPH	C-D	(2)	2	189	BLK	✓
	COMM	C		2	189	BLK	✓
	ELECT	D.W.		2	189	BLK	✓
	ELECT	F		3	017	PEC3	✓
	ELECT	G/SEC	(2)	3	010	PEC3	✓
	SHUTTLE ELEV			3	026	PEC3	✓
	CORE MEV	AREA	(3)	2	248	PEC3T	✓
	CORE MEV	D/D	(2)	2	247	Hochiki	✓
	W. MER	AREA	(2)	3	003	PEC3T	✓
	W. MER	D/D	(2)	3	035	EDWDS	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 4-25-00
CONTRACT #: S/00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/C.
Prev. Maintenance Contract testing S/detectors on Several Floors as schedule - All Area tested listed / Closets. MER's - as listed.
System OK / Reset to Normal operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21310

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	PLANT			CABLE	XNDL	S/D	TEST
48	ROOF						
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	096	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
48	DUCT	S/D		4	070	EDWDS	✓
48	DUCT	S/D		4	116	EDWDS	✓
48	DUCT	S/D		4	118	EDWDS	✓
48	DUCT	S/D		4	117	EDWDS	✓
48	DUCT	S/D		4	118	EDWDS	✓
48	DUCT	S/D		4	118	~~EDWDS~~ D138	✓

PREVENTIVE MAINTENANCE CONTRACT

41st TEST & DEVICES OUTPUTS FUNCTIONS. ALARM'S – SPK/PAGE – STROBES / SHUTDOWN FANS.
(FOREST ELECTRIC – 41st Fl (SOFTWARE / INSTALLATION)! –

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 4-26-00
CONTRACT #: SK00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: S/CONTRACT
As per contract check / test & smoke devices detectors – beams ducts on roof M.E.R. Plant. – as listed – (Advised Bother [illegible] Ed Sensing EDWD [illegible] / contractor Forest / G.C. / Scheduled to test / shutdowns / SPK / strobes

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

on 41st Floor —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21312

REPORT OF FIELD SERVICE

LOCATIONS — DEVICES

FLOOR				CABLE	VTNDR	S/D	TEST
31	ELECT	A-B	(2)	2	187	BRK	✓
	TELEPH	A-B	(2)	2	187	BRK	✓
	COMM	A-B	(2)	2	187	BRK.	✓
	ELECT	C-D	(COAT) 2	2	186	BRK.	✓
	COMM	C-D	(COAT) 2	2	186	BRK	✓
	ELECT	D.W.	(2)	2	186	BRK	✓
	ELECT	F		3	016	PEC 3	✓
	ELECT	G		3	009	PEC 3	✓
	FREIGHT ELEV.			2	008	BRK	✓
	PASS ELEV.			2	008	BRK	✓
	SHUTTLE ELEV.			3	025	PEC 3	✓
	SECURITY CLOSET			3	009	PEC3	✓
	CORE HER AREA (3)			2	244	PEC3T	✓
	CORE HER D/D (2)			2	245	HOCHIKI	✓
	W. HER AREA (2)			3	002	PEC3T	✓
	W. HER D/D (2)			3	034	EDWS	✓
30th	PASS ELEV.			2	007	BRK	✓
	FREIGHT ELEV			2	007	BRK	✓
	ELECT	A-B	(2)	2	184	BRK	✓
	TELEPH	A-B	(2)	2	184	BRK	✓
	COMM	A-B	(2)	2	184	BRK	✓
	ELECT	C-D	(2)	2	183	BRK	✓
	ELECT	D.W.		2	193	BRK	✓
	ELECT	F		3	015	PEC 3	✓
	ELECT	G/SEC.	(2)	3	008	PEC 3	✓
	TELEPH	C/COAT		2	183	BRK	✓
	COMM	C/COAT		2	183	BRK	✓
	SHUTTLE ELEV.			3	024	PEC 3	✓
	CORE HER CEILING (3)			2	242	PEC3T	✓
	CORE HER D/D (2)			2	243	HOCHIKI	✓
	W. HER AREA (2)			3	001	PEC3T	✓
	W. HER D/D (2)			3	033	EDWS	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 5-2-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTON

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING

Continue S/C Prev. Maintenance on Smoke Detection Floor's 31/30 (Solomon Area). - System Ok/Reset. -
To be Continue -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during this period of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

21313

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		CABLE	XMNDR	S/D	TST
29	ELECT A-B	(2)	2	182	BAK.	✓
	TELEPH A-B	(2)	2	182	BAK	✓
	COMM A-B	(2)	2	182	BAK	✓
	ELECT C-D	(2)	2	181	BAK	✓
	ELECT D.W.		2	181	BAK	✓
	ELECT G		3	007	PEC3	✓
	SECURITY		3	007	PEC3	✓
	ELECT F		3	014	PEC3	✓
	TELEPH C		2	181	BAK	✓
	COMM C		2	181	BAK	✓
	TELEPH D/CORT		2	181	BAK	✓
	FREIGHT ELEV. Lby		2	006	BAK	✓
	MAIN ELEV. Lby		2	006	BAK	✓
	SHUTTLE ELEV		3	030	PEC3	✓
	CORE HER Ceiling		2	240	PEC3T	✓
	CORE HER Ceiling		2	240	PEC3T	✓
29	CORE HER Ceiling		2	240	PEC3T	✓
	CORE HER D/D		2	241	HOCHIKI	✓
	CORE HER D/D.		2	241	HOCHIKI	✓
	WEST HER AREA		3	032	PEC3T	✓
	WEST HER AREA		3	032	PEC3T	✓
	WEST HER D/D.		3	000	EDWDS	✓
	WEST HER D/D		3	000	EDWDS	✓

6th Power Rack Test / Repair (Status)

6th Fl Amplifier Rack Trouble / Repair Status

15 Warden Station (312-2) Light ckt Repair (grounded) - Unit disable - out Radio.

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 5-3-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance / Service Contract Checked / Test Units on 29th Fl. (All Areas) Listed. Also Repairs on 6th Fl / 15th Fl. System Ack / Restored Back to operation. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21314

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		Cable	XTNDR	S/D	TST
27	ELECT A		2	178	BRK	✓
	ELECT B		2	178	BRK	✓
	ELECT C		2	177	BRK	✓
	ELECT D		2	177	BRK	✓
	TELEPH A		2	178	BRK	✓
	TELEPH B		2	178	BRK	✓
	TELEPH C		2	177	BRK	✓
	TELEPH D		2	177	BRK	✓
	COMM A		2	178	BRK	✓
	COMM B		2	178	BRK	✓
	COMM C		2	177	BRK	✓
	COMM D		2	177	BRK	✓
	FREIGHT ELEV.		2	004	BRK	✓
	PASS ELEV.		2	004	BRK	✓
	CORE MER D X/DT.		2	237	Hochiki	✓
	CORE MER DX DUCT		2	237	Hochiki	✓
	LADIES D/D RET.		2	236	Hochiki	✓
	RETURN South.		2	236	Hochiki	✓
	RETURN NORTH		2	236	Hochiki	✓
26	ELECT A-B (x2)		2	176	BRK	✓
	TELEPH A-B (x2)		2	176	BRK	✓
	COMM A-B (x2)		2	176	BRK	✓
	ELECT C-D (x2)		2	175	BRK	✓
	TELEPH C-D (x2)		2	175	BRK	✓
	COMM C-D (x2)		2	175	BRK	✓
	FREIGHT ELEV.		2	003	BRK	✓
	PASS ELEV Lbby		2	003	BRK	✓
	CORE MER D/D		2	235	Hochiki	✓
	CORE MER D/D		2	235	Hochiki	✓
	LADIES Rm D/D RET		2	234	Hochiki	✓
	RETURN South D/D		2	234	Hochiki	✓
	RETURN North D/D		2	234	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I
	DATE SCHEDULED: 5-9-00
CONTRACT #: SFC 00818	TYPE OF SYSTEM: 8700
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): [signature]
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

SERVICE PERFORMED & REMAINING: Continue Silverstein - Prev. Maintenance on Smoke Detection (Solomon Floors) areas listed above. - System Ck/Tested, as per operation & also Repaired/Installed (1) Epson LX 810 Printer Replaced at 44 Fl. Security office Solomon Brothers. - (Cold not work printing.) P.C. Active. - Back in operation -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21315

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Areas		Cable	XTNDR	S/D	TST
28	Elect A		2	180	BRK	✓
"	Elect B		2	180	BRK	✓
"	Elect C		2	179	BRK	✓
"	Elect D		2	179	BRK	✓
"	Elect DW		2	179	Dec 3	✓
"	Elect F		3	179	Dec 3	✓
"	Elect G		3	180	Dec 3	✓
"	Tel A		2	180	BRK	✓
"	Tel B		2	180	BRK	✓
"	Tel C		2	179	BRK	✓
"	Comm A		2	180	BRK	✓
"	Comm B		2	180	BRK	✓
"	Comm C		2	179	BRK	✓
"	Comm D		2	179	BRK	✓
"	Freight Elev		2	005	Edwards	✓
"	Pass Elev		2	005	Edwards	✓
"	Shuttle Elev		3	005	Dec 3	✓
"	Core MER		2	239	Hochiki	✓
"	Core MER		2	239	Hochiki	✓
"	West MER Ceiling		3	057	Dec 3T	✓
"	West MER Ceiling		3	057	Dec 3T	✓
"	West MER Ceiling		3	057	Dec 3T	✓
"	West MER D/D		3	047	DI 3D	✓

(D) No Detector in Security Closet.

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 5-10-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Routine S/Contract - Prev. Maintenance
On Smoke Detectors Sprinkler Floors Area Listed above -
System OK Re-Tested - As Per Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

12047

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	Area			Cable	XTUN	S/D	TST
40	Elect	A			207	BEK	✓
"	Elect	B			207	BEK	✓
"	Elect	C			"	Apollo	✓
"	Elect	D			"	Apollo	✓
"	Elect	F	(B)			—	—
"	Elect	G			078	PEC3	✓
40	Tel	A			207	BEK	✓
	Tel	B			207	BEK	✓
"	Storage Closet					Apollo	✓
"	Coat Closet					Apollo	✓
"	Comm	A			207	BEK	✓
"	Comm	B			207	BEK	✓
"	Storage					Apollo	✓
"	Storage					Apollo	✓
40	Freight Elev	(D)			017	BEK	✓
"	Pass Elev				017	BEK	✓
"	Shuttle Elev				006	DI3	✓
"	Security Closet				078	PEC3	✓
"	Core	MER	Ceiling		208	Apollo	✓
"	Core	MER	Ceiling		208	Apollo	✓
"	Core	MER	D/D		271	Apollo	✓
"	Core	MER	D/D		271	Apollo	✓

(B) Head Missing
(D) Head Inside the Ceiling

INVOICE TO: 7 WTC
NYC

SERVICEMAN ASSIGNED	SEE AT JOB SITE
V. Torres / F. Kisano	F.S.D.
	DATE SCHEDULED: 5-10-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Conducted [illegible] Prev. Maintenance On Smoke Detectors [illegible] Floor area listed above. System OK Restored to Normal Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SE[illegible]ICE INCORPORAT[illegible] 91762

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T Shop		SC# 0818				F.S.D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		4/26/00	AM			C. Tabara

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM	4:30 PM		8:00				

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE:

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED

Preventive Maintenance

SERVICE PERFORMED

I Assisted To Jimmy Torres Cleaned & Tested of Smoke detectors (Duct and Areas) Located on 48th floor M.E.R. All Smoke detector Tested Work properly.
Also Assisted Techs. to Test 47th floor Devices Solorzon floor

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

26061

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	AREA / CLOSET			CABLE	ZONE	S/D	TESTED
36	ELEV. LOBBY			2	013	BLK	✓
	FREIGHT ELEV			2	013	BLK	✓
	ELEV SHUTE			4	002	PEC 3	✓
	6' ELECTRIC			4	074	PEC 3	✓
	SECURITY CLOSET			4	074	PEC 3	✓
	CORE HER CEILING			2	256	PEC 3T	✓
	CORE HER "			2	256	PEC 3T	✓
	CORE HER "			2	256	PEC 3T	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	ELECT. A			2	198	BLK	✓
	COMM A			2	198	BLK	✓
	TELEPH A			2	198	BLK	✓
	TELEPH B			2	198	BLK	✓
	ELECT B			2	198	BLK	✓
	COMM B			2	198	BLK	✓
	ELECT C			2	197	BLK	✓
	COMM C			2	197	BLK	✓
	TELEPH C			2	197	BLK	✓
	ELECT D			2	197	BLK	✓
	TELEPH D			2	197	BLK	✓
	ELECT D1			2	197	BLK	✓
	ELECT F			4	050	PEC 3	✓
36	WEST	HER	AREA	4	026	PEC 3T	✓
	WEST	HER	AREA	4	026	PEC 3T	✓
	WEST	HER	D/D	4	098	EDWD	✓
	WEST	HER	D/D	4	098	EDWD	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 4-18-00
CONTRACT #: 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): NEUERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Continue S/Contract.
Prev. Maintenance on Smoke Detection Units on Various Floors
Areas / Closets - Elev Lobbies - HER's / Duct's Units as listed above. -
System OK / Restored Back to Operation. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

,26063

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			CABLE	XTNDR	S/D	TST
38	ELECT	A-B	(2)	2	202	BRK	✓
	TELEPH	A-B	(2)	2	202	BRK	✓
	COMM	A-B	(2)	2	202	BRK	✓
	ELECT	C		2	203	BRK	✓
	ELECT	D		2	203	BRK	✓
	ELECT	D1		2	203	EDWDS	✓
	ELECT	'G'		4	076	PEC3	✓
	SECURITY			4	076	PEC3	✓
	ELECT	'F'		4	052	PEC3	✓
	FREIGHT ELEV			2	015	BRK	✓
	PASS ELEV.			2	015	BRK	✓
	ELEV SHUTTLE			4	004	PEC3	✓
	CORE HER AREA (3)			2	260	PEC3/T	✓
	CORE HER D/D (2)			2	261	HOCHIKI	✓
	W. HER AREA			4	028	PEC3T	✓
	W. HER D/D			4	100	EDWDS	✓
38	W. HER AREA AUDTH			4	046	PEC3T	✓
38	W. HER D/D AUDTH			4	127	EDWDS	✓
37th	PASS/FREIGHT (2)			2	014	BRK	✓
	TELEPH	A-B	(2)	2	200	BRK	✓
	ELECT	A-B	(2)	2	200	BRK	✓
	COMM	A-B	(2)	2	200	BRK	✓
	TELEPH	C-D	(2)	2	199	BRK	✓
	ELECT	C-D	(2)	2	199	BRK	✓
	COMM	C		2	199	BRK	✓
	ELECT	D1		2	199	BRK	✓
	ELECT	F		4	051	PEC3	✓
	ELECT	G		4	075	PEC3	✓
	SECURITY			4	075	PEC3	✓
	ELEV. SHUTTLE			4	003	PEC3	✓
	CORE HER AREA (3)			2	258	PEC3T	✓
	CORE HER D/D (2)			2	257	HOCHIKI	✓
	W. HER AREA (2)			4	027	PEC3T	✓
	W. HER D/D (2)			4	099	EDWDS	✓

INVOICE TO: 2 W.T.C. (Salomon Brothers) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres, F. Rosario	F.S.D.
	DATE SCHEDULED: 4-12-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	1800 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continue S/Contract — Preventive Maintenance of Smoke Detection on Floors 38/37 - Areas Listed. — Units Cleaned/Tested/Recorded — Each Unit Ok/Reacted Properly — To Contract S/C

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

X

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21920

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABLE	XTNDR	S/D	TST CLEAN
39	ELECT	A		2	205	BRK	✓
	TELEPH	A		2	205	BRK	✓
	COMM	A		2	205	BRK	✓
	ELECT	B		2	205	BRK	✓
	COMM	B		2	205	BRK	✓
	TELEPH	B		2	205	BRK	✓
	ELECT	C		2	204	BRK	✓
	ELECT	D		2	204	BRK	✓
	ELECT	DW-1		2	205	BRK	✓
	ELECT	F		4	053	PEC 3	✓
	ELECT	G		4	077	PEC3	✓
	SECURITY			4	077	PEC 3	✓
	ELEV. PASS			2	016	BRK	✓
	FREIGHT ELEV.			2	016	BRK	✓
	ELEV. SHUTTLE			4	005	PEC3	✓
	CORE	HER AREA		2	262	PEC3	✓
	CORE	HER AREA		2	262	PEC 3	✓
	CORE	HER AREA		2	262	PEC3T	✓
	CORE	HER D/D		2	263	Hochiki	✓
	CORE	HER D/D		2	263	Hochiki	✓
39	WEST	HER D/D		4	101	EDWDS	✓
	W. HER AREA			4	029	PEC3T	✓
	D/D	Ceiling	Recpt.	2	254	S-5022 Apollo	✓
	D/D	"	"	2	254	"	✓
	D/D	"	"	2	254	"	✓
	D/D	"	"	2	254	"	N/A
	D/D	"	"	2	254	"	N/A

INVOICE TO:
7 W.T.C.
(Solomon Brothers)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres F. Rosario	F.S.D	
	DATE SCHEDULED: 4-11-00	
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	800 AM	330 PM	330 PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE:

SERVICEMAN SIGNATURE:

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING
S/CONTRACT –
PREV. MAINTENANCE SMOKE DETECTION CLASS E EQUIPMENT – ON 39TH FLOOR – (AREAS LISTED). – SYSTEM TESTED/RESET. As per operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(39)

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11784

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				S/D	CHAN	STNDR	TST
23	MECH- RM	D/D	Apollo		2	264	✓
23	MECH RM	D/D	Apollo		2	264	✓
23	MECH RM. AREA HEAT Apollo				2	268	✓
23	MECH RM AREA HEAT Apollo				2	268	✓
23	BUNK RM AREA		Apollo		2	269	✓
23	BUNK RM AREA		Apollo		2	269	✓
23	CONF. RM/CLASS RM			(4)	2	265	✓
	(S. WEST CORNER)		UNDER FLOOR				
23	CONF RM/CLASS RM			(4)	2	265	✓
	(S. W CORNER) U/F.						
23	QUATER'S MASTER			(3)	2	266	✓
	UNDER/FLOOR -						
23	MOTORO/A RM			(4)	2	266	✓
	U/FLOOR						
23	WATCH COMMAND CENTER			(9)	2	266	✓
	UNDER/FLOOR. -						
7	TANK RM AREA COMBO			(2)	1	110	✓
7	GENERATOR RM			(5)	1	110	✓
47	RADIO COMM. ROOM.			(2) Apollo	2-	270	✓
	(ROOF)		AREA/COMBO				
23	MANUAL PULL STATIONS			(3)	-2-	032	✓

INVOICE TO: 7 W.T.C
N.Y.C MAYOR'S OFFICE
23rd Fl.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 4-7-00
CONTRACT #	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Ray Lynch [signature]

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Contract S/contract Prev. Maintenance / Located / Search of Smoke Detectors U/Floor's Areas. - (As Listed) on 23rd 47th & 07th Floors - (As Listed). -
Also Tested (3) Manual pull stations - (2-032). - Check/Stose Panel Alarm/Trouble Voltage O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

26064

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

(SHAFT'S)

LOCATIONS				DEVICES			
FLOOR				CABLE	XTNDR	S/D	TST
47	SHUTTLE ELEV WEST			4	037	PEC3T	✓
47	SHUTTLE ELEV. EAST			4	037	PEC3T	✓
43	E.H.R. PE1.2 (BATH RM ENT.)			4	064	PEC3	✓
16	E.H.R AREA EAST			1	195	BRK	✓
16	E.H.R AREA EAST			1	195	BRK	✓
16	E.H.R D/D EAST			1	254	EDWDS	✓
16	EHR AREA WEST			1	195	BRK	✓
16	E.H.R D/D WEST			1	254	EDWDS	✓
15	E.H.R AREA WEST			1	192	BRK	✓
15	E.H.R AREA EAST			1	192	BRK	✓
15	E.HR AREA EAST			1	192	BRK	✓
3RD	SHUTTLE ELEV. SHAFT			3	049	PEC3T	✓
2	E.H.R HE 3+2			3	005	PEC3T	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. ROSARIO	F.J.J	
	DATE SCHEDULED: 4-7-00	
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
4:00 PM	4:30 PM	8:30 PM	AM PM	

P.M.

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): PAT. Kinsella (For J. Corrigan)
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

SERVICE PERFORMED & REMAINING
Prev. Maintenance Elevators Shaft's - S/Detection (as listed) assisted by OTIS Mechanic - and E.H.R's Areas. - System All Reset Back to operation. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(16)

FIRE SERVICE INCORPORATED 26059

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	PRESS	RM	XTNDR	S/D	SERIAL	TEST

FLOOR	PRESS	RM	XTNDR	S/D	SERIAL	TEST
23	U/Floor		2-266	DIA-3	E6112A3	✓
	U/F		2-266	"	E9412A3	✓
	U/F		2-266	"	E6112A3	✓
	U/F		2-266	"	E8112A3	✓
*	U/F		N/A - LOCATION NEEDED			—
23	E.O. CENTR					
	PODIUM U/F		2-267	DIA-3	E94304	✓
	PODIUM U/F		2-267	DIA-3	E94384	✓
	PODIUM U/F		2-267	DIA-3	E94384	✓
23	E.O.C MONTRS					
	# 1-4 TWR		2-267	DIA 3		✓
	# 5-8 TWR		2-267	DIA 3		✓
	# 9-12 TWR		2-267	DIA 3		✓
	# 13-16 TWR		2-267	DIA-3		✓
	# 17-20 TWR		2-267	DIA-3		✓
	# 21-24 TWR		2-267	DIA-3		✓
	# 25-28 TWR		2-267	DIA 3		✓
	# 29-32 TWR		2-267	DIA 3		✓

NON REMOVABLE

to be continued

INVOICE TO: 7 W.T.C.
O.E.M. - 23rd Fl.
N.Y.C.
MAYOR'S OFFICE

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / F. Rosario 4-6-00	F.S.D. / Ray Lynch	
	DATE SCHEDULED: 4-6-00	
CONTRACT #: 5/L 00	TYPE OF SYSTEM: 8100	
FEE SERVICE #: -	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Ray Lynch D.I.S.

SERVICEMAN SIGNATURE: [signature] [signature]

SERVICE PERFORMED & REMAINING: Prev. Maintenance on Smoke Detector Units — Located on 23rd Fl. — Areas / Underfloor — (As listed above) Units / Terminated Directly to Class 'E' System.
NOTE: Units under Raised Floor - Tiles / Rugs needed to be lifted. — & Units search/located. — Escort needed.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

26060

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS	DEVICES						
FLOOR							
47	Elev SHAFT Car 44/47 SHUTTLE						
		CABLE 4	XTNDR	037	S/D PEC 3T		
46	KITCHEN SHUTTLE # 38 CAR						
		CABLE 4	036		PEC 3T		
46	FREIGHT SHUTTLE HKEY ROOM						
		4 - 036			PEC 3T		
47	EHR	CAR 21-28					
		CABLE 2 - 220			BAK		
47	EHR	CAR 21-28					
		CABLE 2 - 220			BAK.		
47	EHR	CAR 21-28					
		CABLE 4 067			PEC 3		
46	EHR	HKE 2-3					
		CABLE 4 065			PEC 3		
46	EHR	HKEY					
		CABLE 4 - 066			PEC 3		
31	EHR	AREA					
		CABLE 2 - 188 (2) BAK.					
31	EHR	DID ECR					
		CABLE 2	246 (1)		Hochiki SIF24		
31	EHR	AREA - CABLE 1 - 188 (1) BAK.					
	EHR	DID ECR CABLE - 2 - 246 Hochiki (1)					

Left margin annotations: SOLOMON; SILV.; SOLOMON; SILV.

INVOICE TO: 7 W.T.C
N.Y.C.
(OTIS)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	FJD / OTIS
	DATE SCHEDULED: 4-6-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	430 PM	830 PM	AM PM	4 P.H.

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): PAT KINSELLA (For J. Cornyer)

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING
CHECK TEST OF ELEVATOR SHAFT / EHR'S AREA S/DETECTORS
LISTED ABOVE AS PER CONTRACT.
SYSTEM OCR [illegible]. TO BE CONTINUED.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11756

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES: CABLE	XTNDR	S/D	TST CLEAN
45	SHUTTLE E/EV			4	011	PEC 3	✓
	PASS E/EV.			2	022	BRK	✓
	FREIGHT E/EV			2	022	BRK	✓
	SHUTTLE KITCHEN			4	012	PEC 3T	✓
	COMM 'B'			2	217	BRK	✓
	TELEPH B			2	217	BRK	✓
	ELECT B			2	217	BRK	✓
	'G' ELECT. CLOSET			4	013	PEC 3	✓
	SECURITY CLOSET			4	083	PEC 3	✓
	ELECT A			2	217	BRK	✓
	COMM A			2	217	BRK	✓
	AREA 'D' STAIR			4	063	PEC 3T	✓
	'F' ELECTRIC			4	059	PEC 3T	✓
	EAST A/V PROJECT			4	091	PEC 3T	✓
	SHAFT/PROJ. ROOM			4	089	PEC 3	✓
	D/D AHU 45-1			4	123	EDWDS	✓
	D/D TF 45-3			4	094	EDWDS	✓
45	E/EV SHUTTLE			4	019	PEC 3	✓
	D/D TF 45-1			4	092	EDWDS	✓
	D/D AHU 45-2			4	124	EDWDS	✓
	AREA STAIR			4	003	PEC 3	✓
44	ELECT A-B	(2)		2	215	BRK	✓
	COMM A-B	(2)		2	215	BRK	✓
	TELEPH A-B	(2)		2	215	BRK	✓
	E/EV PASS.			4	021	BRK	✓
	FREIGHT E/EV			4	021	BRK	✓
	E/EV. SHUTTLE			4	010	PEC 3	✓
	E/EV. SHUTTLE			4	010	PEC 3	✓
	ELECT. 'F'			4	058	PEC 3	✓
	ELECT 'G'			4	082	PEC 3	✓
	SEC. CLOSET			4	082	PEC 3	✓
	WEST-HER CEILING			4	834	PEC 3T	✓
	WEST HER D/D			4	112	EDWDS	✓

INVOICE TO: 2 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D. 4-5-00
	DATE SCHEDULED: 4-5-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8100
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Preventive Maintenance on Smoke Detection Units (Station Floor (Listed Above). – Floors 45 & 44th Units Tested OCK/Reset at Fire Console – To Continue –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is installed and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11770

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR		CABLE	XMDR	S/D	TST CLEAN
47	W. HER D/D	4	069	EDWDS	✓
	W. HER D/D	4	115	EDWDS	✓
	W. HER D/D	4	113	EDWDS	✓
	ELECT G.	4	085	PEC3T	✓
	SECURITY	4	085	PEC3T	✓
	VERTICAL SHAFT	4	068	PEC3T	✓
	ELEV. SHUTTLE LOBBY	4	016	PEC3T	✓
	ELECT 'F'	4	061	PEC3T	✓
	ELECT A-B (2)	2	223	BRK	✓
	COMM A-B (2)	2	223	BRK	✓
	ELECT 'C' CLOSET	2	223	BRK	✓
	COMM 'D' CLOSET	2	223	BRK	✓
	STAIR 'B' LANDING	2	221	EDWDS	✓
	CORE HER D/D	2	279	EDWDS	✓
	CORE HER AREA (3)	2	278	PEC3T	✓
46th	FREIGHT LBBY	2	023	BRK	✓
	ELECT G	4	084	PEC3	✓
	SEC. CLOSET	4	084	PEC3	✓
	ELECT B	2	218	BRK	✓
	COMM B	2	218	BRK	X DEFECT.
	ELECT A	2	218	BRK	✓
	COMM A	2	218	BRK	✓
	TELEPH A	2	218	BRK	✓
	TELEPH D	2	219	BRK	✓
	ELECT D	2	219	BRK	✓
	COMM D	2	219	BRK	✓
	ELEV. SHUTTLE 'H'	4	015	PEC3T	✓
	ELEV. SHUTTLE F.	4	014	PEC3	✓
	CORE HER. D/D (2)	2	277	HOCHIKI	✓
	CORE AREA. (3)	2	276	PEC3T	✓
	ELECT F	4	060	PEC3	✓
	ELECT C	2	219	PEC3	✓
	KITCHEN SHUTTLE ELEV.	4	013	PEC3	✓

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 4-4-00
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	400 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [illegible]
SERVICEMAN SIGNATURE: [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance as per Service Contract - Cleaned Tested Smoke Detectors Units on areas listed Floors 47 & 46th (Solomon S.B. Floors). - System O.K. Reset as per operation. -
(*) 'B COMM. = S/D. DEFECTIVE / CHECK replace pending. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15753

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREA'S		S/D	CABLE	XTNDR	
6	SWITCHGEAR		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
6	H.V. VAULT	(x4)	BRK	1	171	
	H.V. VAULT	(x4)	BRK	1	171	
	H.V. VAULT	(x4)	BRK	1	171	
	H.V. VAULT	(1)	BRK	1	171	
5	SWITCH GEAR	Area	BRK	1	170	North
	"	"	BRK	1	170	North
	"	"	BRK	1	170	North
	"	"	BRK	1	170	North
	SWITCH GEAR		BRK	1	170	South
	"	"	BRK	1	170	South
	"	"	BRK	1	170	South
	"	"	BRK	1	170	South
	H.V. VAULT	Area	(x6)	1	170	
	H.V. VAULT	Area	(x6)	1	170	
46	STROBE PANEL		AFL 100	Repairing (BATTERIES)		

Silverstein [illegible]

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 3-29-00
CONTRACT #: SIC00790	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8 AM	9 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	Batteries 12 Volts	

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [illegible]
SERVICEMAN SIGNATURE: [illegible]

SERVICE PERFORMED & REMAINING: Continuing SI Contract - Prev. Maintenance on Smoke Detection Floor's 6th / 5th Fl (Silverstein) High Voltage Room's / Vault - * Repairs on 46th Fl. Strobe Panel AFL100 * Replaced (2) Batteries 12 Volt. Also Back in Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15751

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S.		CABLE	XTNDR	S/D.	TST CLEAN
9	ELECT A		1	179	BRK	✓
	COMM B		1	179	BRK	✓
	COMM ~~B~~		1	179	BRK	✓
	ELECT B		1	179	BRK	✓
	TELEPH A		1	179	BRK	✓
	TELEPH B		1	179	BRK	✓
	PASS ELECT		1	008	BRK	✓
	FREIGHT ELECT.		1	008	BRK.	✓
	COMM C		1	178	BRK	✓
	ELECT C		1	178	BRK	✓
	TELEPH C		1	178	BRK	✓
	ELECT D		1	178	BRK	✓
	COMM D		1	178	BRK	✓
	TELEPH D		1	178	BRK	✓
	RETURN D/D	NORTH	1	238	Hochiki	✓
	RETURN D/D	EAST	1	238	Hochiki	✓
	RETURN D/D	SOUTH	1	238	Hochiki	✓
	CORE HEL D/D.		1	239	Hochiki	✓
	CORE HEL. D/D.		1	239	Hochiki	✓
6	PASS/FREIGHT ELEV (2)		1	005	BRK	✓
	COMM. 'A'		1	172	BRK	✓
	ELECT 'A'		1	172	BRK	✓
	TELEPH 'A'		1	172	BRK	✓
	ELECT 'B'		1	172	BRK	✓
	COMM 'B'		1	172	BRK	✓
	TELEPH 'B'		1	172	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	DUCT S/D. FAN RM		1	231	Hochiki	✓
	DUCT S/D. FAN RM		1	229	Hochiki	✓
	DUCT S/D FAN RM		1	232	Hochiki	✓
	DUCT S/D FAN RM		1	233	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F.S.D.
	DATE SCHEDULED: 3.22.00
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is imposed and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [illegible]
SERVICEMAN SIGNATURE [illegible]

SERVICE PERFORMED & REMAINING: Preventive Maintenance on Smoke Detection Devices of Class E System on floors 9 & 6th all areas above (Listed). — System ACK Restored —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15750

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREA'S		CABLE	XTUDE	S/D	TEST CLEAN
8	ELEV. PASS		1	007	BRK	✓
	FREIGHT ELEV		1	007	BLK	✓
	ELECT 'A'		1	177	BLK	✓
	COMM A		1	177	BLK	✓
	TELEPH A.		1	177	BLK	✓
	COMM B		1	177	BLK	✓
	ELECT B		1	177	BLK	✓
	TELEPH B		1	177	BLK	✓
	RETURN D/D	North	1	236	Hochiki	✓
*	RETURN D/D	South	N/A	—	—	—
	RETURN D/D	EAST (Elev)	1	236	Hochiki	✓
	CORE MER D/D		1	237	Hochiki	✓
	CORE MER D/D		1	237	Hochiki	✓
	COMM C-D (2)		1	176	Hochiki	✓
	ELECT C-D (2)		1	176	Hochiki	✓
	TELEPH C-D (2)		1	176	Hochiki	✓
7	COMM A		1	175	BLK	✓
	ELECT A		1	175	BLK	✓
	TELEPH A.		1	175	BLK	✓
	PASS/FREIGHT ELEV		1	006	BLK	✓
	COMM B		1	175	BLK	✓
	ELECT B		1	175	BLK	✓
	TELEPH B		1	175	BLK	✓
	COMM C		1	174	BLK	✓
	ELECT C		1	174	BLK	✓
	TELEPH C		1	174	BLK	✓
	TELEPH D		1	174	BLK	✓
	ELECT D		1	174	BLK	✓
	COMM D		1	174	BLK	✓
	CORE MER D/D		1	235	Hochiki	✓
	CORE MER D/D		1	235	Hochiki	✓
	RETURN D/D	North	1	234	Hochiki	✓
	RETURN D/D	South	1	234	Hochiki	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED: J. [illegible] / F. Rosario	SEE AT JOB SITE: F.S.D.
	DATE SCHEDULED: 3-21-00
CONTRACT #: 5/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.
NAME / DATE / TIME

SERVICE PERFORMED & REMAINING
Monthly Contract Preventive Maintenance on Smoke Area Detectors Floors 7 + 8 (Listed Areas). - System Ack/Reseted Properly. -
* NOTE: 8th FL Return Unit South Side Unavailable / No Location. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

By Drawing [?] Reviewed[?]. —

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15749

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: AREAS		CABLE	XTNDR	S/D	TST CLEAN
11th	COMM 'A'		1	182	BLK	✓
	ELECT A		1	182	BLK	✓
	TELEPH A		1	182	BLK	✓
	PASS ELEV		1	010	BRK	✓
	COMM 'B'		1	182	BLK	✓
	ELECT 'B'		1	182	BLK	✓
	TELEPH 'B'		1	182	BLK	✓
	FREIGHT ELEV		1	010	BLK	✓
	RETURN PLENUM South		1	244	HOCHIKI	✓
	RETURN D/D North		1	241	HOCHIKI	✓
	CORE HER D/D		1	243	HOCHIKI	✓
	CORE HER D/D		1	243	HOCHIKI	✓
	ELECT RM C		1	183	BLK	✓
	COMM 'C'		1	183	BLK	✓
	TELEPH 'C'		1	183	BLK	✓
	TELEPH 'D'		1	183	BLK	✓
	ELECT 'D'		1	183	BLK	✓
	COMM 'D'		1	183	BLK	✓
10	PASS/FREIGHT (2)		1	009	BLK	✓
	ELECT A-B (2)		1	181	BLK	✓
	TELEPH A-B (2)		1	181	BLK	✓
	COMM A-B (2)		1	181	BLK	✓
	CORE HER D/D		1	241	HOCHIKI	✓
	CORE HER D/D		1	241	HOCHIKI	✓
	RETURN D/D North		1	240	HOCHIKI	✓
	RETURN D/D South		1	240	HOCHIKI	✓
	RETURN D/D EAST		1	240	HOCHIKI	✓
	ELECT C-D (2)		1	180	HOCHIKI	✓
	COMM C-D (2)		1	180	HOCHIKI	✓
	TELEPH C-D (2)		1	180	HOCHIKI	✓

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.I.
	DATE SCHEDULED: 3-15-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Routine Prev. Maintenance as per Contract — Test (Manual) Smoke Detectors (Duct) in Areas (Listed) Floors 11th + 10th. System Cor/Reset Back to Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15748

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CABLE	VNDR	S/D	TST CLEAN
13	COMM A-B	(2)	1	186	BLK	✓
	ELECT A-B	(2)	1	186	BLK	✓
	TELEPH A-B	(2)	1	186	BLK	✓
	PASS FREIGHT	(2)	1 (012)	012	BLK	✓
	CORE HER D/D		1	247	Hochiki	✓
	CORE HER D/D		1	247	Hochiki	✓
	ELECT C		1	187	BLK	✓
	COMM C		1	187	BLK	✓
	TELEPH C.		1	187	BLK	✓
	RETURN D/D	North	1	246	Hochiki	✓
	RETURN D/D	South	1	246	Hochiki	✓
	COMM D		1	187	BLK	✓
	TELEPH D		1	187	BLK	✓
	ELECTRIC D		1	187	BLK	✓
12	PASS LBBY		1	011	BLK	✓
*	COMM A	(Cover n/g)	1	184	BLK	✓
	ELECT A		1	184	BLK	✓
	TELEPH A		1	184	BLK.	✓
	FREIGHT ELEV		1	011	BLK.	✓
	COMM B		1	184	BLK	✓
	ELECT B		1	184	BLK	✓
	TELEPH B		1	184	BLK	✓
*	CORE HER D/D LED		1	245	Hochiki	✓
*	CORE HER D/D LED		1	245	Hochiki	✓
	RETURN PLENUM D/D N		1	244	Hochiki	✓
	RETURN PLENUM D/D S		1	244	Hochiki	✓
	COMM 'C'		1	185	BLK	✓
	ELECT 'C		1	185	BLK	✓
	TELEPH 'C'		1	185	BLK	✓
	COMM 'D'		1	185	BLK	✓
	ELECT 'D'		1	185	BLK	✓
	TELEPH 'D'		1	185	BLK	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.J.D.
	DATE SCHEDULED: 3-14-00
CONTRACT #: SFC 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #: 3-14-00
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:20 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING

Courtesy S/Contract Prev. Maintenance on class E System - Smoke Detectors Tested/Cleaned on Floor's 13/12 Above Listed. -

(*) NOTE: Core HER D/D 'LED's - N/G Need to Replace. 'A' Comm Closet - Unit Cover N/G to Replace -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15746

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		CABLE	XTNDR	S/D	TST CLEAN
15	COMM A		1	190	BLK	✓
	ELECT A		1	190	BLK	✓
	TELEPH A		1	190	BLK	✓
	COMM B		1	190	BLK	✓
	ELECT B		1	190	BLK	✓
	TELEPH B		1	190	BLK	✓
	PASS FREIGHT (2)		1	014	BLK	✓
(*)	CORE HER D/D		1	251	Hochi	✓ LED
	CORE HER D/D		1	251	Hochi	✓
	RETURN PLENUM D/D		1	250	Hochi	✓
(*)	RETURN South	NO ACCESS			U/N	*
(*)	COMM C-D	(2)	1	191	BLK	✓
	ELECT C-D	(2)	1	191	BLK	✓
	TELEPH C-D	(2)	1	191	BLK	✓
(*)	D COMM. CLOSET NO ACCESS/FURNITURE					
14	PASS FREIGHT (2)		1	013	BLK	✓
	COMM A		1	188	BLK	✓
	ELECT A		1	188	BLK	✓
	TELEPH A		1	188	BLK	✓
	TELEPH B		1	188	BLK	✓
	COMM B		1	188	BLK	✓
	ELECT B		1	188	BLK	✓
	CORE HER D/D		1	249	Hochi	✓
	CORE HER D/D		1	249	Hochi	✓
	RETURN D/D		1	248	Hochi	✓
(*)	RETURN D/D North	NO ACCESS				*
	COMM C		1	189	BLK	✓
	ELECT C		1	189	BLK	✓
	TELEPH C		1	189	BLK	✓
	ELECT D		1	189	BLK	✓
	TELEPH D		1	189	BLK	✓
	COMM D		1	189	BLK	✓
18	TELCOM Rm		1	198	FDUS	✓
18	TELCOM/D/D FAN		1	108	D18-3	✓

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F Rosario	F.S.D.
	DATE SCHEDULED 3-8-00
CONTRACT # 5/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING CONTINUE S/CONTRACT - PREV. MAINTENANCE SMOKE DETECTION 15/14 FLOOR'S (SEE ABOVE). —

* NOTE: 15 Fl. 'D' COMM. CLOSET = NO ACCESS DOOR BLOCKED FURNITURE ON WAY.
* CORE HER D/D. L.E.D. TO BE REPLACE / DAMAGE, — 15 Fl.
* RETURN DUCTS/DETECTOR (AS PREVIOUS REPORT) NO ACCESS - (SOLID CEILING) 15 Fl

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

* 14 Fl. RETURN DUCT'S/DETECTOR (AS PREVIOUS REPORT) NO ACCESS (SOLID CEILING) North Side

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15747

REPORT OF FIELD SERVICE

LOCATIONS FLOOR	DEVICES						
	AREAS		CABLE	XTNDM	S/D	TST/CLEAN
17	COMM	A-B	(2)	/	197	BLK	✓✓
	ELECT	A-B	(2)	/	197	BLK	✓✓
	TELEPH	A-B	(2)	/	197	BLK	✓✓
	PASS	ELEV		/	016	BLK	✓✓
	FREIGHT ELEV			/	016	BLK	✓✓
	CORE	HER D/D		/	256	Hochik	✓
	CORE	HEL D/D		/	256	Hochik	✓
(*)	RETURN PLENUM D/D		NO ACCESS			CLOSE	
	ELECT	C-D	(2)	/	196	BLK	✓✓
	COMM	C-D	(2)	/	196	BLK	✓✓
	TELEPH	C-D	(2)	/	196	BLK	✓✓
16	COMM	A-B	(2)	/	193	BLK	✓✓
	ELECT	A-B	(2)	/	193	BLK	✓✓
	TELEPH	A-B	(2)	/	193	BLK	✓✓
	TELEPH	C-D	(2)	/	194	BLK	✓✓
	ELECT	C-D	(2)	/	194	BLK	✓✓
	COMM	C-D	(2)	/	194	BLK	✓✓
	PASS LBBY			/	015	BLK	✓
	FREIGHT LBBY			/	015	BLK	✓
	CORE	HER D/D		/	253	Hochik	✓
	CORE	HER D/D		/	253	Hochik	✓
	PLENUM	RETURN D/D		/	252	Hochiki	✓
(*)	"	RETURN SOUTH	NO ACCESS			UNAVAILABLE	

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: WTC
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	7-1-D
	DATE SCHEDULED 3-7-00
CONTRACT # 5/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) SILVERSTEIN

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING

CONTINUE S/CONTRACT PREV. MAINTENANCE ON FLOORS 17 & 16 (AS LISTED)

(*) NOTE: (17 FL. RETURN DUCT DET. UNAVAILABLE / NO ACCESS. CEILING
16 RETURN D/D SOUTH SIDE NO ACCESS / PROVIDED AS PREVIOUSLY REPORTED

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15722

REPORT OF FIELD SERVICE

FLOOR	AREAS/ELEV			CABLE	XTNDR	S/D	TST/CLEAN
19	ELECT	B		1	201	BLK	✓
	COMM	B		1	201	BLK	✓
	TELEPH	B		1	201	BLK	✓
	PASS/FREIGHT ELEV.			1	018	BLK	✓
	ELECT	A		1	201	BLK	✓
	COMM	A		1	201	BLK	✓
	TELEPH	A		1	201	BLK	✓
	RETURN D/D NORTH			1	259	HOCHIKI	✓
	RETURN D/D SOUTH			1	259	HOCHIKI	✓
	CORE HER SUPPLY			1	260	HOCHIKI	✓
	CORE HER SUPPLY			1	260	HOCHIKI	✓
	ELECT	C-D	(2)	1	200	BLK	✓
	COMM	C-D	(2)	1	200	BLK	✓
	TELEPH	C-D	(2)	1	200	BLK	✓
18	COMM	A-B	(2)	1	197	BLK	✓
	ELECT	A-B	(2)	1	197	BLK	✓
	TELEPH	A-B	(2)	1	197	BLK	✓
(*)	PASS/FREIGHT ELEV.		(2)	1	016	BLK	✓
	COMM	C-D	(2)	1	196	BLK	✓
	ELECT	C-D	(2)	1	196	BLK	✓
	TELEPH	C-D	(2)	1	196	BLK	✓

(*) FREIGHT 18 Fl. ELEV. 16by S/D UNIT (DEFECTIVE BASE Replaced)

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / L. ROSARIO	T.J.
	DATE SCHEDULED: 3-1-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING
Continue S/C. Preventive maintenance on Floors 19 & 18 (as listed) Units TEST/CLEAN - Alarms ACK/RESET - Function outputs O.K. - System RESET - Back to operation. —
(*) NOTE: 18 Fl FREIGHT 16by S/D Base Replaced. — To follow up. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

88032

SUBSIDIARY OF FIF. .M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
Silverstein.
7 WTC
Emergency Service.
Saturday

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Service.					S/o Lawrence

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		15 January 2000		Newell

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			TROUBLE CALL			
			Construction BILLABLE	CONTRACT TROUBLE CALL		

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
200	245	330		1.50				

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 15 January 2000

CUSTOMER SIGNATURE: Leslie Lawrence

WILL RETURN ON:

SERVICEMAN SIGNATURE: B. C. Newell

PROBLEM—AS DESCRIBED

Emergency Service.

SERVICE PERFORMED 200 recd beep. Contact service and customer. Customer report 43rd FL speaker going in and out of trouble. Floor under construction. 2:45 arrived at jobsite. Met with Security. Check F.C.S. 43rd FL speaker in trouble, then trouble reset. Met with Engineer. Access 38th FL and 42nd FL. Construction floors gutted. Speaker open and grounded circuit disconnected grounded [illegible] wires 41st FL and 43rd FL. to stabilized F.C.S. Checked F.C.S. -ok speaker in trouble 40-43. Call completed.

WORK REMAINING

* Must clear grounded speakers 41st and 43rd FL

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

88043

SUBSIDIARY OF F... OM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED

7 WORLD TRADE CENTER
NEW YORK, N.Y

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC-00818				
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		1-17-00				T. TRONCOSO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			12VDC/7AH BATTS	69.95		

TROUBLE CALL

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
12:30	1:30	2:00		1.5				
PM	PM	PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☑

SERVICE DATE: 1-17-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keef

SERVICEMAN SIGNATURE: T. Troncoso

PROBLEM—AS DESCRIBED

TROUBLE CALL

SERVICE PERFORMED

REPLACE TWO 12VDC/7AH BATTS. IN AFC-100
STROBE PANEL 20TH FL. MER. ROOM.
PANEL BACK ON LINE.

WORK REMAINING

JOB DONE.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED   21937

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS / DEVICES
6	STROBE PANEL ACTIVATION
	(1) AFC 100 - 'B' COMM. -
	(1) STROBE - 5 SPKRS.
3rd	STROBE PNL ACTIVATION (1) AFC 100
	'B' COMM. -
	STROBES = 10 UNITS
2nd	STROBE PANEL ACTIVATION (1) AFC 100
	FREIGHT/ENTRANCE AREA -
	STROBES = 6 UNITS.
1st	STROBE PANEL ACTIVATION (1) AFC 100
	PUMP ROOM. -
	STROBES = 2 UNITS. -
* 26	STROBE PANEL PYRO SYSTEM 3 CORE HER
	TROUBLE / NEED (2) BATTERY 6 VOLTS
	(LOW OUTPUT)
* 12	REPAIRED (1) AFC 101 PANEL - REPLACED
	(1) BATTERY 12 VOLTS. - (LOW OUTPUT) -
	'B' COMM. CLOSET
* 11	REPAIRED (1) AFC 101 PANEL (1) BATTERY
	REPLACED LEAKING UNIT / DEFECTIVE. -
	'B' COMM. CLOSET -
16	REPAIRED (1) AFC 100 PANEL - 'A' CKT OUT
	CHECK / RESISTANCE - O.K. - BACK TO
	OPERATIONS -

INVOICE TO: 7 WTC.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	DATE SCHEDULED 1-12 00
CONTRACT # S/C 00 313	TYPE OF SYSTEM 3500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLTS	69.95 each

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): [illegible]STEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM SERVICE WORK — The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby consents to the interruption... regarding interruption of the system, but service during the ... of the equipment.

NAME ____ DATE ____ TIME ____

SERVICE PERFORMED & REMAINING
(A) PER CONTRACT CHECK TESTED STROBE PANELS (LIGHTS) ON FLOORS AREAS (ABOVE LISTED). - ALSO REPAIRED REPLACED (1) BATTERY UNIT ON 12 FLOOR AND (1) UNIT BATTERIES ON 11 FL (LOW OUTPUT) LEAKING UNIT. -
(A) 26 FL PANEL PYRO TROUBLE NEEDED (2) UNITS — PENDING —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SE VICE INCORPORA ED 70080 2/1/99

SUBSIDIARY OF F... .OM INC

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R. Trivino		Scitt OE18				F. S. D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		10/13/99	AM			C. Tabor

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2.			BATERIES 12 VOL	69.95		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

☐ O C ☐ EMERGENCY CALL
☐ I & T ☒ CONTRACT CALL
☐ FEE CALL ☐ PICK UP
☐ DELIVERY ☐ DEMO OWNER
☐ DEMO ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM	4:30 PM		8:00				

☐ MAT. REQD ☐ PARTIAL
☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 10/13/99

WILL RETURN ON

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of protection service during their service of the equipment.

Date

Name X

PROBLEM—AS DESCRIBED

Preventive Maintenance

SERVICE PERFORMED

Cleaned and Tested Sensitivity of Smoke detector on 2nd and 3rd floor Areas Closets Elevator Lobbys All detector Tested Work OK. Also. Repairs on The 45th floor Strobe Panel

Not delivery To WTC. four Batteries for Replacement on Strobe panel

WORK REMAINING

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

89235

SUBSIDIARY OF FIR. JM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
New York . N.Y

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP		U.P.S= 818				FSP
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		2-23-00	300 AM			C. FORERO C TABARES

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	12.30 PM	300 AM	430 PM					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☒

SERVICE DATE: 2-23-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: C. FORERO

PROBLEM—AS DESCRIBED: PREVENTIVE MAINTENANCE / U.P.S System (10K)

SERVICE PERFORMED: Cleaned And Checked U.P.S System Took Readings Cleaned Cabinet, checked 24V mini fans all Runing on Cleaned Filters And Batteries, (U.P.S it's operational)

Battery Amps = 2A
Total Battery Voltage 140.9 V. A/C
Output Voltage 6.2 HZ
(LOAD) L-1 = 11.4
L-2 = 11.1

WORK REMAINING: Output Voltage 250V
Input Volts 208V A/C

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding the interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

21928

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				S/D	CABLE	XTNDR	TEST CLEAN
24	CORE	HER D/D		HOCHIKI	2	231	✓
	CORE	HER D/D.		HOCHIKI	2	231	✓
	ELEV.	ELEV.		BRK	2	001	✓
	FREIGHT ELEV.			BRK	2	001	✓
	COMM	A		BRK	2	172	✓
	ELECT	A		BRK	2	172	✓
	TELEPH	A		BRK	2	172	✓
	COMM	B		BRK	2	172	✓
	ELECT	B		BRK	2	172	✓
	TELEPH	B		BRK	2	172	✓
	RETURN	D/D	SOUTH	HOCHIKI	2	230	✓
	RETURN	D/D	NORTH.	HOCHIKI	2	230	✓
	COMM	C		BRK	2	171	✓
	ELECT	C		BRK	2	171	✓
	TELEPH	C		BRK	2	171	✓
	TELEPH	D		BRK	2	171	✓
	ELECT	D		BRK	2	171	✓
	COMM	D		BRK.	2	171	✓
22	PASS ELEV.			BRK	1	021	✓
	FREIGHT ELEV.			BRK.	1	021	✓
	TELEPH.	A		BRK	1	207	✓
	ELECT	A		BRK	1	207	✓
	COMM	A		BRK	1	207	✓
	ELECT	B		BRK	1	207	✓
	COMM	B		BRK	1	207	✓
	TELEPH	B		BRK	1	207	✓
	COMM	C		BRK	1	206	✓
	ELECT	C		BRK	1	206	✓
	TELEPH	C		BRK	1	206	✓
	TELEPH	D		BRK	1	206	✓
	ELECT	D		BRK.	1	206	✓
	COMM	D		BRK	1	206	✓
	CORE	HER D/D	(2)	HOCHIKI	1	264	✓
	RETURN	D/D	(2)	HOCHIKI	1	265	✓

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-23-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME _____ DATE _____ TIME _____

SERVICE PERFORMED & REMAINING: Cont'd S/CONTRACT - TEST CLEANING OF AREA'S SMOKE DETECTOR (CLOSET'S) + H-E-R DUCT S/D. + ELEVATOR'S LOBBIES ON FLOOR (LISTED ABOVE). - SYSTEM ACK/RESTORED PROPERLY. - TO CONTINUE. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21927

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		S/D	CABLE	XTNDR	TST CLEAN
25	COMM A		BRK	2	174	✓
	ELECT A		BRK	2	174	✓
	TELEPH A		BRK	2	174	✓
	ELECT B		BRK	2	174	✓
	COMM B		BRK	2	174	✓
	TELEPH B		BRK	2	174	✓
	PASS ELEV.		BRK	2	002	✓
	FREIGHT ELEV		EDWARDS	2	002	✓
	COMM C		BRK	2	174	✓
	ELECT C		BRK	2	174	✓
	TELEPH C		BRK	2	174	✓
	ELECT D		BRK	2	174	✓
	COMM D		BRK	2	174	✓
	TELEPH D		BRK	2	174	✓
	RETURN D/D NORTH		HOCHIKI	2	232	✓
	RETURN D/D SOUTH		HOCHIKI	2	232	✓
	CORE MER D/D		HOCHIKI	2	233	✓
25	CORE MER D/D		HOCHIKI	2	233	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. ROSARIO	F.S.D.	
	DATE SCHEDULED: 2-22-00	
CONTRACT #: 5/C00818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUTHORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING: STARTED YEAR 2000 / FIRST FLOOR CLEANING TESTING OF SMOKE DETECTOR'S WITH IN AREAS CLOSET'S / ELEV LOBBIES TANDEMS - MER'S - DUCTS. - AS LISTED. - CHECK SUMMATION (ALL'S RESET) BYPASS FUNCTIONS O.K. - BACK TO NORMAL.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21926

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES W/STA	Cable	XTNDR	SPK Page
14	HALLWAY		✓	1	325	✓
	CORE HER		✓	1	325	✓
13						
12	HALLWAY		✓	1	323	✓
	CORE HER		✓	1	323	✓
11	HALWAY		✓	1	322	✓
	CORE HER		✓	1	322	✓
10	HALWAY		✓	1	321	✓
	CORE HER		✓	1	321	✓
9	HALLWAY		✓	1	320	✓
	CORE HER		✓	1	320	✓
8	HALLWAY		✓	1	319	✓
	CORE HER		✓	1	319	✓
7	HALLWAY		✓	1	318	✓
	CORE HER		✓	1	318	✓
6	HALLWAY		✓	1	317	✓
6	HER (FAN RM)		✓✓	1	338	✓
6	ENGNR'S - RAN II		✓	1	335	●
5	HALLWAY/SERV. ELEV.		✓	1	336	✓
5	SW GEAR	H.V.	✓	1	336	✓
5	HER	NORTH	✓	1	337	✓
5	"	SOUTH	✓	1	337	✓
5	HER	N.W	✓	1	316	
4	'B' EXIT / AREA		✓	1	315	✓
3	F.D. OFF RAN I		✓	1	314	●
2	'A' EXIT (AREA)		✓	1	313	✓
2	HER WEST		✓	1	334	✓
2	T/FRAME AREA		✓	1	334	✓
1	PUMP RM		✓	1	341	✓
1	GROUND ENTRANCE		X	OUT/SERV.		—

INVOICE TO: WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Lokker / F. Rosario	F.D.
	DATE SCHEDULED: 2.18.00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: As per contract check/tested for operation Warden's phones stations + spkr page on floors 14 to 1st Fl. as listed above. — ④ Ground floor entrance unit (disabled due to grounded wiring. — (as previous informed)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE UNIT - OUT — (D) OTHER

FIRE SERVICE INCORPORATED

21925

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES		
FLOOR		W/STA	SPKRS Page	XFMR
25	Hallway	✓	✓	282
	Core Her	✓		282
24	Hallway	✓	✓	281
	Core Her	✓		281
23	N/A	NO ACCESS		–
22	Hallway	✓	✓	333
	Core Her	✓		333
21	Hallway	✓	✓	332
	Core Her	✓		332
* 20	Hallway	✓	✓	331
	Core Her. *	✓		331
*	Low audibility phone. –			
19	Hallway	✓	✓	330
	Core Her	✓		330
18	Hallway	✓	✓	329
	Core Her	✓		329
17	Hallway	✓	✓	328
	Core Her	✓		328
* 16	Hallway	✓	✓	327
	Core Her *	✓		327
	Low audibility phone. –			
15	Hallway	✓	✓	326
	Core Her	✓		326

To be continued.

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.D.
	DATE SCHEDULED: 2-17-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	1200 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): [illegible] WERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

DATE | TIME | NAME

SERVICE PERFORMED & REMAINING: As per contract – check test for operations on warden's stations and P.A/Page on floors 25 to 15 as listed above. Floors 20/16 low audibility on phones to be check (increased).
(+) Also as per Firecom – started replacing T.C.'s prov's at F.C.STA – to delete points on (Solonoid riser points). – to be continue. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21921

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	EXITS		CABLE	M/STA	TST		
25	A		2	036	✓		
	B		2	037	✓		
24	A		2	034	✓		
	B		2	035	✓		
23	A	ACCESS NEEDED					
	B		4	-	MAYOR'S OFFICE		
22	A		2	070	✓		
	B		2	071	✓		
21	A		-	068	✓		
	B			069	✓		
20	A			066	✓		
	B			067	✓		
19	A			064	✓		
	B			065	✓		
18	A			062	✓		
	B			063	✓		
17	A			060	✓		
	B			061	✓		
16	A			058	✓		
	B			059	✓		
15	A			056	✓		
	B			057	✓		
14	A			054	✓		
	B			055	✓		
13	A			052	✓		
	B			053	✓		
12	A			050	✓		
	B			051	✓		
11	A			048	✓		
	B			049	✓		
10	A			046	✓		
	B			047	✓		

INVOICE TO: WTC.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 2-10-00
CONTRACT #: S/C 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Contract S/C. Check/Tested for proper operation manual pull stations (as listed) floors 25 to 10th. —
Alarms acknowledged / reset / output functions O.K. —
To be continued. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15721

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S -			S/D	CABLE	XTNDR	TST/CLEAN
21	PASS ELEV			BRK	1	020	✓
	FREIGHT ELEV			EDWDS	1	020	✓
	COMM	A		BRK	1	204	✓
	ELECT	A		BRK	1	204	✓
	TELEPH	A		BRK	1	204	✓
	ELECT	B		BRK	1	204	✓
	COMM	B		BRK	1	204	✓
	TELEPH	B		BRK	1	204	✓
	ELECT	C		BRK	1	205	✓
	COMM	C		BRK	1	205	✓
	TELEPH	C		BRK	1	205	✓
	COMM	D		BRK	1	205	✓
	ELECT	D		BRK	1	205	✓
	TELEPH	D		BRK	1	205	✓
	CORE	HEF D/D (2)		HOCHIKI	1	264	✓
	RETURN	D/D NORTH		HOCHIKI	1	263	✓
(✱)	RETURN	D/D SOUTH		HOCHIKI	1	263	LED
20	COMM	A-B	(2)	BRK	1	203	
	ELECT	A-B	(2)	BRK	1	203	
	TELEPH	A-B	(2)	BRK	1	203	
	TELEPH	C-D	(2)	BRK	1	202	
	COMM	C-D	(2)	BRK	1	202	
	ELECT	C-D	(2)	BRK	1	202	
	PASS	ELEV.		BRK	1	019	✓
	FREIGHT	ELEV.		EDWDS	1	019	
	PLENUM	RETURN NORTH		HOCHIKI	1	261	
	PLENUM	D/D RET	SOUTH	HOCHIKI	1	261	
	PLENUM	D/D RET	EAST	HOCHIKI	3	045	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 2-29-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

SERVICE PERFORMED & REMAINING: Contract S/Contract on smoke detection units on floors 21 + 20 (above listed locations) — cleaned & tested. —
(✱) NOTE: Return duct detector south side on 21st Fl. (need LED - broken). —
(✱) Also check / bypass function on duct S/D return unit 20th Fl (cable 3 - code 045) east side. — System ack/reset back to operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21919

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS					DEVICES		
FLOOR	A	B	C		MANUAL STA.	CABLE	XTNDR TST
35	056	057	195		✓✓	2	✓
34	054	055			✓✓	2	✓
33	053	052			✓✓	2	✓
32	051	050			✓✓	2	✓
31	048	049			✓✓	2	✓
30	046	047			✓✓	2	✓
29	044	045			✓✓	2	✓
28	042	043			✓✓	2	✓
27	040	041			✓✓	2	✓
27	040 → EAST Corridor				✓	2	✓
26	038	039			✓✓	2	✓
26	038 → EAST Corridor				✓	2	✓

41st 'B' EXIT M/STATION 069 N/G - FIELD WIRING OPEN. - FOREST ELEC. NOTIFIED TO RUN WIRING / TO TTB ON 42nd FL. - (Floor under Construction). —

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres, F. Rosario	F.S.D.
	DATE SCHEDULED: 2-2-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #: -
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Conducting Semiannual Check / Testing Manual pull stations Alarm's / Activation on floors (above Listed). —
NOTE: 41st FL 'B' EXIT UNIT Removed / Wiring cut / Floor Under Construction. - Forest Electric Notified unit to be Restored / Devices on Location. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21918

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS					DEVICES		
FLOOR	EXIT A	EXIT B	EXIT C		CABLE	XTNDR	M/STA
48	147				2	147	✓✓
47	080	081	082		2		✓✓✓
47	FITNESS AREA				2	084	✓✓
46	079	078	—		2		✓✓
45	076	077	—		2		✓✓
44	074	075	—		2		✓✓
43	072	073			2		✓✓
42	071	070	199-4		2		✓✓✓
41	068	069	198-4		2		✗✓✓
40	067	066	197-4		2		✓✓✓
39	065	064	193-4		2		✓✓✓
39	AUDITORIUM EXIT				4	194	✓✓
38	062	063	192-4		2		✓✓✓
37	060	061	145-4		2		✓✓✓
36	058	059	144-4		2		✓✓✓

(*) → 058 A EXIT - N/G - BROKEN S/W.

— 0 —

		TAMPER'S	TEST	O.K.
46	PUMP RM	153 - 152	✓	
46	"	151 - 150	✓	
46	"	149 - 148	✓	

41st M/STA 069 'B' EXIT WIRING CUT / OPEN
FIELD WIRING OPEN / UNIT ZEROED. —

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	7-S-1
	DATE SCHEDULED: 2-1-00
CONTRACT #: 5K00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	450 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	-

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: AS PER CONTRACT CHECK TESTED FOR PROPER ALARM / RESET OPERATING MANUAL PULL STATIONS ON FLOORS 48 TO 36th AT LISTED LOCATION / CABLE · XTNDR'S — CODES · AMOUNT —
NOTE: 36th FL. 'A' EXIT UNIT #058 NOT OPERATING - BROKEN S/W — MUST BE REPAIRED. — SYSTEM O.K. TESTED. —
ALSO TESTED TAMPER'S ON 46th FL PUMP ROOM — —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

124-S



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT EP = EXPLOSION PROOF
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(J)	JUNCTION BOX
LPC	LOW PRESSURE COMPRESSURE
LP	LOW PRESSURE SWITCH
H	HORN EP = EXPLOSION PROOF

REV	DATE	BY	DESCRIPTION
3	11/10/98	C.S.	ADDED (1) INTERGIN FIRE SYS. CONTROL PANEL ON 1ST FL. FOR 'MAYORS OFFICE' PER FJ-64637-02.
2	9/29/98	C.S.	ADDED (1) HORN, (1) STROBE & (1) HEAT DET. ON 1ST FL. PER FJ-64637.
1	8/25/98	C.S.	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR: | ENGINEER:

PARTIAL RISER DIAGRAM
1ST FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-01
REV	3

OOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT EP = EXPLOSION PROOF
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
⊣	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(J)	JUNCTION BOX
LPC	LOW PRESSURE COMPRESSURE
LP	LOW PRESSURE SWITCH
▷H	HORN EP = EXPLOSION PROOF

REV	DATE	BY	DESCRIPTION
2	05/04/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 1ST FL. PER LJ-80208.
1	8/25/98	CS	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
1ST FLOOR

DRWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	2
OF	2
REV	2

CONTRACTOR | ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-01

1ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR F = FLUSH
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
1	05/01/00	JM	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
2ND FLOOR

DWN L.H. | APPD | ENGR J.M. | CKD | DATE 05/01/00 | SCALE N.T.S. | SHEET 1 OF 2 | REV 1

CONTRACTOR | ENGINEER

FIRECOM, INC. CASE/ACME — WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-02

2ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT EP = EXPLOSION PROOF
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(J)	JUNCTION BOX
(ER)	ELEVATOR RECALL JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
2	05/04/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 2ND FL. PER LJ-80208.
1	05/02/00	JM	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
2ND FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APP'D	
ENGR	J.M.
CKD	
DATE	05/02/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-02

2ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
4	10/10/00	JM	ADDED (5) SPKR/STRBS. FOR 'STANDARD CHARTER' PER LJ-80452.
3	8/30/99	CS	ADDED (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN & (1) AREA SMK. DET. ON 13TH FL. FOR 'STANDARD CHARTER' PER FJ-65220-01.
2	7/9/99	CS	ADDED (6) SPEAKERS, (5) STROBES & (1) RELAY FOR DOOR RELEASE ON 13TH FL. FOR 'STANDARD CHARTER' PER FJ-65220.
1	7/9/99	CS	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
13TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	4
JOB	FJ-26840
DWG	B-504111-13

CONTRACTOR | ENGINEER

FIRECOM, INC. CASE/ACME
39-27 59TH STREET WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
2	9/13/99	C.S.	ADDED (1) SPKR./STRB. & (1) RELAY FOR DOOR RELEASE ON 7TH FL. FOR "AMEX" PER FJ-65298.
1	9/13/99	C.S.	EXT. TTB#22A (D-506284-A) & ASSOCIATED DEVICES TRANFERRED FROM DWG. B-504111-07 SH. #1 TO THIS DWG.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

~~PARTIAL RISER DIAGRAM~~
7TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-07
REV	2

7TH FLOOR



7TH FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
6	11/15/99	C.S.	ADDED (4) SPKR./STRBS., (1) PHOTO HEAT/SMK. DET., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN & (2) RELAYS FOR DAMPER CONTROL ON 7TH FL. FOR "AMEX" PER FJ-65418.
5	9/15/99	C.S.	EXT. TTB #22A (D-506284-A) & ASSOCIATED DEVICES TRANSFERRED FROM THIS DWG. TO DWG #B-504111-07 SH#2.
4	1/20/99	C.S.	ADDED (5) SPKR./STRBS. (5) STRBS.,(1) MANUAL-PULL STATION (1) RELAY FOR DOOR RELEASE & (1) AREA SMK. DET. ON 7TH FL. FOR "MAYORS OFFICE" PER FJ-64918.
3	11/23/98	C.S.	REPLACED (2) HEAT DETECTORS WITH (7) PHOTO HEAT/SMK DETS. & ADDED (1) SPKR. STROBE ON 7TH FL. PER FJ-64637.
2	9/9/98	C.S.	ADDED (2) HEAT DETS. & (3) SPKR./STRBS ON 7TH FL PER FJ-64637.
1	8/25/98	C.S.	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
7TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	1
OF	2
REV	6
JOB#	FJ-26840
DWG#	B-504111-07

CONTRACTOR / ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
1	7/7/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR ENGINEER

PARTIAL RISER DIAGRAM
13TH FLOOR

DRN	L.H.
APPVD	
CHCK	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	1
JOB#	FJ-26840
DWG#	B-504111-13

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

13TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH /
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
1	03/02/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR:
ENGINEER:

PARTIAL RISER DIAGRAM
20TH FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	03/02/01
SCALE	N.T.S.
SHEET	2
OF	2
REV	
JOB#	FJ-26840
DWG#	B-504111-20

20TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
2	03/02/01	JM	ADDED (2) SPEAKER/STROBES PER LJ-80656.
1	03/02/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
20TH FLOOR

DRN	L.H.
APP'D	
ENGR	J.M.
CKD	
DATE	03/02/01
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-20

CONTRACTOR
ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

20TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
⊣	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
1	04/11/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
22ND FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/11/01
SCALE	N.T.S.
SHEET	1
JOB#	FJ-26840
OF	2
DWG#	B-504111-22
REV	1

22ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
Ⓙ	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
2	04/11/01	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SHUTDOWN FOR 'FEDERAL HOME LOAN' PER LJ-80739.
1	04/11/01	JM	RISER REDRAWN. SEE DWG# E-504111-5 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
22ND FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/11/01
SCALE	N.T.S.
SHEET	2
OF	2
REV	7
JOB#	FJ-26840
DWG#	B-504111-22

22ND FLOOR



REV	DATE	BY	DESCRIPTION
8	10/6/99	C.S.	REPLACED (1) RELAY FOR DOOR RELEASE ON 23RD FL. FOR "OEM" PER FJ-64914-01.
7	1/20/99	C.S.	ADDED (1) RELAY FOR DOOR RELEASE ON 23RD FL. FOR "OEM" PER FJ-64914.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
UF	UNDER FLOOR DETECTOR
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE
	REMOTE INDICATING LAMP

REV	DATE	BY	DESCRIPTION
6	12/28/98	C.S.	ADDED (2) MANUAL PULL STATIONS ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64899.
5	12/11/98	C.S.	REPLACED (3) DUCT DETS WITH (3) HIGH VELOCITY AREA DETS. PER FJ-64637
4	11/20/98	C.S.	DELETED (1) PRESSURE SWITCH, (2) TAMPER SWITCH & (2) WATER FLOW SWITCH. REPLACED (7) PHOTO HEAT/SMK DETS. WITH (2) HEAT DETS. ADDED (2) ELEV. LOB. DETS. & (1) AREA SMK. DET. ADDED PRESSURE SWITCH (TROUBLE) CONN TO PRE-ACTION SYSTEMS ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64637
3	11/10/98	C.S	ADDED (1) PRE-ACTION SYSTEM ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64637-02.
2	9/29/98	C.S.	ADDED (1) PAD-2 STRB PNL., (28) SPKR./STROBES., (7) STRBS., (6) DUCT SMK. DETS., (6) RELAYS FOR AC SHUTDOWN, (1) RELAY FOR DOOR RELEASE, (1) PRESSURE SWITCH, (2) TAMPER SWITCH, (2) WATER FLOW, SWITCH, (42) UNDER FLOOR DETS., (1) PRE-ACTION SYSTEM, (2) AREA SMK. DETS., (7) PHOTO HEAT/SMK. DETS. & (42) INDICATING LAMPS ON 23RD FLOOR PER FJ-64637.
1	8/26/98	C.S.	RISER REDRAWN. SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
23RD FLOOR

DWN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	8/26/98
SCALE	N.T.S.
SHEET	1
OF	1
JOB	FJ-26840
DWG#	B-504111-23
REV	8

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
[strobe symbol]	STROBE LIGHT
[speaker/strobe symbol]	COMB. SPKR/STROBE
[speaker symbol]	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
[fan shutdown symbol]	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
[resistor symbol]	END OF LINE RESISTOR
[stair speaker symbol]	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
[bi-directional speaker symbol]	BI-DIRECTIONAL SPEAKER

REV	DATE	BY	DESCRIPTION
2	09/20/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 24TH FL PER LJ-80431
1	09/20/00	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
24TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	09/20/00
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-24

24TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR

24TH FLOOR

REV	DATE	BY	DESCRIPTION
1	09/20/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
24TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APP'D	
DSGN	J.M.
CKD	
DATE	09/20/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	1
JOB#	FJ-26840
DWG#	B-504111-24



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(ER)	ELEVATOR RECALL JUNCTION BOX
(EA)	ELEVATOR ADVANCE

MAY 1 8 2000

REV	DATE	BY	DESCRIPTION
1	05/16/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DRWN L.H.
APPV'D
ENGR J.M.
CHKD
CONTRACTOR
ENGINEER

PARTIAL RISER DIAGRAM
30TH FLOOR
'SILVERSTEIN'

DATE 05/16/00
SCALE N.T.S.
SHEET 1
OF 2

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-30
REV 1

30TH FLOOR



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

MAY 1 8 2000

REV	DATE	BY	DESCRIPTION
2	05/16/00	JM	ADDED (1) RELAY DAMPER CONTROL & (6) STROBES. REPLACED (1) EXIST. STRB. WITH (1) NEW STRB. FOR 'SALOMON SMITH BARNEY' PER LJ-80228.
1	05/16/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS.

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
30TH FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	05/16/00
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-30
REV	2

30TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(ER)	ELEVATOR RECALL JUNCTION BOX
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN: L.H.
APPVD:
ENGR: J.M.
CKD:
DATE: 04/26/00
SCALE: N.T.S.
SHEET: 1
OF: 2
REV: 1

CONTRACTOR: | ENGINEER:

PARTIAL RISER DIAGRAM
31ST FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-31

31ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
SS	SUB-SYSTEM
CD	COMBINATION SMOKE & HEAT DETECTOR
J	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 31ST FL. PER LJ-80208.
2	04/26/00	JM	ADDED (6) STROBES & (1) RELAY FOR DAMPER CONTROL FOR 'SALOMON SMITH BARNEY' PER LJ-80205.
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
31ST FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/26/00
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-31
REV	3

31ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(ER)	ELEVATOR RECALL JUNCTION BOX
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/27/00
SCALE	N.T.S.
SHEET	1
OF	2
REV	1

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
32ND FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-32

32ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 32ND FL. PER LJ-80208.
2	04/26/00	JM	ADDED (6) STROBES & (1) RELAY FOR DAMPER CONTROL FOR 'SALOMON SMITH BARNEY' PER LJ-80204.
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
32ND FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/27/00
SCALE	N.T.S.
SHEET	2
OF	2
JOB	FJ-26840
DWG	B-504111-32
REV	3

32ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

33RD FLOOR

REV	DATE	BY	DESCRIPTION
1	9/13/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

~~PARTIAL RISER DIAGRAM~~
33RD FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	1
JOB	FJ-26840
DWG#	B-504111-33



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
4	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 33RD FL. PER LJ-80208.
3	12/2/99	J.M.	ADDED (1) SPKR./STRB. ON 33RD FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65307-01.
2	9/13/99	C.S.	ADDED (3) SPKR./STRBS. & (2) STROBES FOR 'SOLOMON SMITH BARNEY' PER FJ-65307.
1	9/13/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
33RD FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-33
REV	4

33RD FLOOR



36TH FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
6	06/08/00	JM	TRANFERRED (4) SPKR./STRBS. FROM SH.1 TO SH. 2 PER FIELD CONDITIONS
5	9/23/99	CS	DELETED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB #15 D-504319 & TRANSFERRED TO TTB #25B D-505652. DELETED (1) MANUAL STATION FROM TTB #15 D-504319 & TRANSFERRED TO TTB #25A D-504948-11 PER FJ-65149.
4	9/23/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
3	6/25/99	CS	ADDED (4) SPKR./STRBS. ON 36TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65150.
2	6/24/99	CS	ADDED (2) AREA SMK. DETS., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN, (1) MANUAL PULL STATION, (1) PRE-ACTION PNL. & (1) STRB. ON 36TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65149.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
36TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APP'D	
ENGR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-36
REV	6



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

JUN 0 9 2000

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
5	06/08/00	JM	ADDED (5) STRBS. FOR "SALOMON SMITH BARNEY" PER LJ-80277.
4	06/08/00	JM	TRANSFERRED (4) SPKR/STRBS. FROM SH. 1 TO SH. 2 PER FIELD CONDITIONS.
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 36TH FL. PER LJ-80208.
2	9/23/99	CS	TRANSFERRED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB#15 D-504319 TO TTB #25B D-505652. TRANSFERRED (1) MANUAL STATION FROM TTB#15 D-504319 TO TTB #25A D-504948-11 PER FJ-65149.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
36TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRWN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DRWG#	B-504111-36
REV	5

36TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(ER)	ELEVATOR RECALL JUNCTION BOX
SS	SUB-SYSTEM
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	6/24/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
37TH FLOOR

DWN: L.H.
APP'D:
ENGR: C.S.
CKD:
DATE: 6/24/99
SCALE: N.T.S.
SHEET: 1
OF: 2
REV: 1
JOB#: FJ-26840
DWG#: B-504111-37

CONTRACTOR
ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

37TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
6	09/11/00	JM	ADDED (2) SPKR/STRBS., (1) STROBE FOR 'SALOMON SMITH BARNEY' PER LJ-80417.
5	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 37TH FL. PER LJ-80208.
4	7/2/99	CS	ADDED (2) STROBES ON 37TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65204.
3	7/2/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
2	6/24/99	CS	ADDED (1) STROBE ON 37TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65147.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
37TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	6
JOB#	FJ-26840
DWG#	B-504111-37

CONTRACTOR | ENGINEER

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

37TH FLOOR



38TH FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
}	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 38TH FL. PER LJ-80208.
2	7/2/99	CS	ADDED (2) STROBES ON 38TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65204.
1	7/2/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
38TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-38
REV	3



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
5	11/14/00	JM	ADDED (3) SPKR./STRBS. & REPLACED (14) EXIST. SPKR./STRBS. FOR 'SALOMON SMITH BARNEY' PER LJ-80504.
4	9/23/99	C.S.	DELETED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB #16 D-504320 & TRANSFERRED TO TTB #26B D-504948-14. DELETED (1) MANUAL STATION FROM TTB#16 D-504320 & TRANSFERRED TO TTB #26A 504948-13 PER FJ-65149.
3	6/25/99	C.S.	ADDED (1) STROBE, (2) AREA SMK. DETS., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN, (1) MANUAL PULL STATION & (1) PRE-ACTION PNL. ON 39TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65149.
2	6/16/99	C.S.	ADDED (3) SPEAKER/STROBES, (2) STROBES, (6) DUCT SMK. DETS., (6) RELAYS FOR FAN SHUTDOWN & (2) RELAYS FOR DAMPER CONTROL ON 39TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65162.
1	6/16/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
39TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/16/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	5
JOB#	FJ-26840
DWG#	B-504111-39

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

39TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
SS	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
4	11/22/00	JM	ADDED (1) SPKR./STRB., (1) STRB., (3) DUCT SMK. DETS., (3) RELAYS FOR FAN SHUTDOWN & (3) RELAYS FOR DAMPER CONTROL FOR "SALOMON SMITH BARNEY" PER LJ-80504-01.
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 39TH FL. PER LJ-80208.
2	9/23/99	CS	TRANSFERRED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB#16 D-504320 TO TTB #26B D-504948-14. TRANSFERRED (1) MANUAL STATION FROM TTB#16 D-504320 TO TTB #26A D-504948-13 PER FJ-65149.
1	6/16/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/16/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	4

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
39TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-39

39TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL FLOOR SPEAKERS
FS	FAN STATUS

40TH FLOOR

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/2/99	JM	RISER REDRAWN. SEE DWG# B-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN: L.H.
APPVD:
ENGR: C.S.
CKD:
DATE: 7/2/99
SCALE: N.T.S.
SHEET: 1
OF: 2
REV: 2

CONTRACTOR:
ENGINEER:

PARTIAL RISER DIAGRAM
40TH FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB#: FJ-26840
DWG#: B-504111-40



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
11	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE PER LJ-80208.
10	04/24/00	JM	ADDED (2) PRE-ACTION PNLS. FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
9	03/13/00	JM	MODIFIED AS PER FJ-65296.
8	03/09/00	JM	DELETED FIRE ALARM CONTROL PNL. WITH UNDER FLOOR DETS. & GRAPHIC ANN. PNL. FOR UNDER FLOOR DET. PER LJ-80061.
7	02/02/00	JM	ADDED (3) SPKR/STRB ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80045-01.
6	01/31/00	JM	DELETED SUB-SYSTEM, FAN STATUS & FAN SHUTDOWN FROM 40TH FL. PER LJ-80061.
5	01/07/00	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SHUTDOWN ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80049.
4	01/06/00	CS	ADDED (18) SPKR/STRBS., (1) AREA SMK. DET., (5) RELAYS FOR DAMPER CONTROL & (1) RELAY FOR DOOR RELEASE ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80045.
3	9/18/99	CS	ADDED (1) PAD-2 STRB. PNL., (4) SPKR/STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/2/99	CS	ADDED (2) STROBES ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/2/99	CS	RISER REDRAWN. SEE DWG# E-50410-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
40TH FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-40
REV	11

CONTRACTOR | ENGINEER



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
41ST FLOOR
"SILVERSTEIN"

FIRECOM, INC. CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-41

41ST FLOOR



41ST FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(CD)	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
9	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 41ST FL. PER LJ-80208.
8	04/24/00	J.M.	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON BARNEY' PER LJ-80202.
7	03/13/00	J.M.	MODIFIED AS PER FJ-65296.
6	03/09/00	J.M.	DELETED PRE-ACTION PNL. & ANSUE SYSTEM ON 41ST FL. PER LJ-80061.
5	01/31/00	J.M.	DELETED SUB-SYSTEM, DUCT DETS., FAN SHUT-DOWN & COMBINATION SMK. & HEAT DETS. FROM 41ST FL. PER LJ-80061.
4	01/06/00	J.M.	ADDED (21) SPKR./STRBS., (1) AREA SMK. DETS. & (5) RELAYS FOR DAMPER CONTROL ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80046
3	9/18/99	C.S.	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/6/99	C.S.	ADDED (2) STROBES ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/6/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN: L.H.
APPVD:
ENGR: C.S.
CKD:
CONTRACTOR:
ENGINEER:

PARTIAL RISER DIAGRAM
41ST FLOOR
'SALOMON SMITH BARNEY'

DATE: 7/6/99
SCALE: N.T.S.
SHEET: 2 OF 2

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-41
REV 9



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
Ⓓ	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
42ND FLOOR
'SILVERSTEIN'

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-42

FIRECOM, INC.
CASE/ACME
WOODSIDE, NEW YORK 11377

42ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
10	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 42ND FL. PER LJ-80208.
9	04/24/00	JM	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
8	03/13/00	JM	MODIFIED AS PER FJ-65296.
7	02/02/00	JM	ADDED (2) RELAYS FOR DAMPER CONTROL, DELETED (2) AREA SMK. DETS. & (3) SPKR./STROBES FROM 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80048-01.
6	01/31/00	JM	DELETED SUB-SYSTEM, FAN STOP STATUS & FAN SHUTDOWN FROM 42ND FL. PER LJ-80061.
5	01/10/00	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SUTDOWN ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80049.
4	01/07/00	JM	ADDED (21) SPKR./STRBS., (3) AREA SMK. DETS., (4) RELAYS FOR DAMPER CONTROL, (19) DAMPERS,(1) RELAY FOR DOOR RELEASE & (1) EXT. TTB ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80048.
3	9/18/99	CS	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/6/99	CS	ADDED (2) STROBES ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
42ND FLOOR
'SALOMON SMITH BARNEY'

DRN	L.H.
APPD	
CHKR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	10
JOB#	FJ-26840
DWG#	B-504111-42

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

REV	DATE	BY	DESCRIPTION
3	03/23/00	JM	ADDED (2) MANUAL PULL STATIONS PER LJ-80143
2	03/1[illegible]/00	JM	MODIFIED AS PER FJ-65296.
1	07/09/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR		ENGINEER	

PARTIAL RISER DIAGRAM
43RD FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	3
JOB#	FJ-26840
DWG#	B-504111-43

43RD FLOOR

124-5



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□⊗	COMB. SPKR/STROBE
▷□	SPEAKER
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
Ⓓ	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
⊣	END OF LINE RESISTOR
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
CD	COMBINATION SMOKE & HEAT DETECTOR
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
9	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 43RD FL. PER LJ-80208.
8	04/24/00	J.M.	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
7	03/22/00	J.M.	ADDED (1) PAD-2 STRB. PNL., (24) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (5) AREA SMK. DETS. & (1) TAMPER SWITH, (1) WATERFLOW SWITCH, (1) RELAY FOR DOOR RELEASE & (5) RELAYS FOR DAMPER-CONTROL FOR SALOMON SMITH BARNEY' PER LJ-80143.
6	03/13/00	J.M.	MODIFIED AS PER FJ-65296.
5	03/09/00	C.S.	DELETED PRE-ACTION PNL. (SUB-SYSTEM) FROM THE 43RD FL. PER LLLJ-80061.
4	01/31/00	C.S.	DELETED FAN SHUTDOWN, DUCT SMK. DETS., SUB-SYSTEM & COMBINATION SMK. & HEAT DETS. FROM 43RD FL. PER LJ-80061.
3	9/18/99	C.S.	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 43RD FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/9/99	C.S.	ADDED (2) STROBES ON 43RD FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/9/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
43RD FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB	FJ-26840
DWG	B-504111-43
REV	9



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
J	JUNCTION BOX
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
3	8/23/99	C.S.	TRANSFERRED ALL EQUIPMENT ADDED IN REV. #2 FROM TTB D-504304 TO TTB D-504948-21 ON 45TH FL. PER FIELD CONDITIONS OF FJ-65133.
2	5/25/99	C.S.	ADDED (1) PAD-2 STROBE PNL W/ASSOC. (18) SPKR/STROBES & (19) STROBES, (6) RELAYS FOR DOOR RELEASE & (1) AREA SMOKE DET. ON 45TH FL. PER FJ-65133.
1	5/25/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR / ENGINEER

PARTIAL RISER DIAGRAM
45TH FLOOR

DRN	A.S.
APPD	
CHKR	C.S.
CKD	
DATE	5/25/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-45
REV	3

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

45TH FLOOR

124-5



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
7	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 45TH FL. PER LJ-80208.
6	12/20/99	JM	ADDED (1) SPKR./STRB., (1) AREA SMK. DET. & (1) RELAY FOR DAMPER CONTROL ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER LJ-80021.
5	9/17/99	CS	ADDED (2) SPKR./STRBS. ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65320.
4	9/17/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
3	8/23/99	CS	ADDED (1) STROBE ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65133-01.
2	8/23/99	CS	TRANFERRED (1) PAD-2 STB. PNL. W/ASSOC. CONN. (18) SPKR./STRBS., (19) STRBS. (6) RELAYS FOR DOOR RELEASE & (1) AREA SMK. DET. FROM TTB D-504304 TO TTB D-504948-21 ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FIELD CONDITIONS OF FJ-65133.
1	8/23/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN	L.H.
APP'D	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	7

CONTRACTOR ENGINEER

PARTIAL RISER DIAGRAM
45TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-45

124-S



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

47TH FLOOR

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
J	JUNCTION BOX
EA	ELEVATOR ADVANCE

SEP 09 2000

REV	DATE	BY	DESCRIPTION
4	09/08/00	JM	ADDED (4) AREA SMK. DETS. PER LJ-B0393.
3	9/23/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
2	9/9/98	CS	ADDED (2) AREA SMK. DETS. & (1) SPKR./STROBE ON 47TH FL. PER FJ-64637.
1	9/9/98	CS	RISER REDRAWN. SEE DWG# E-504111-5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
47TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/9/98
SCALE	N.T.S.
SHEET	1
OF	2
JOB	FJ-26840
DWG#	B-504111-47
REV	4

CONTRACTOR / ENGINEER

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

124-S



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR F = FLUSH
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
Ⓓ	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
⊣	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
Ⓙ	JUNCTION BOX
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
2	05/05/00	JM	ADDED (RELAY FOR DOOR RELEASE ON 47TH FL. PER LJ-80208.
1	9/9/98	JM	RISER REDRAWN. SEE DWG# E-504111-5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
47TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/9/98
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-47

47TH FLOOR



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A / B (speaker)	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR # 16 TW
	A / B (stair speaker)	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1PR # 20TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR # 20 TW/SH 1 PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20TW, 1PR # 20 TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1PR # 20 TW
	TS	TAMPER SWITCH			1PR # 20TW
	SS	SUB-SYSTEM	F.B.O.		1PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RANI	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1 PR # 20 TW 1PR # 20 TW/SH
	RANII	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR # 20 TW/SH, 1PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
	⊠	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1PR # 16
	F/C	FUSE CUTOUT BOX			
	⊗	STROBE LIGHTS			
	D	DAMPER CONTROL	F.B.O		1PR#16
	(resistor)	END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT. WIRING OF SPKRS & STROBES CONNECTION REFER TO DWG. C-103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-01, 07, 02,

REV.	DATE	BY	DESCRIPTION
23	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS: 3RD THRU 5TH PER LJ-80208.
22	11/19/98	CS	ADDED (1) AREA SMK. DET. & (1) RELAY FOR FAN SHUTDOWN ON 3RD FL. FOR "SPI" PER FJ-64746.
21	1/20/98	C.S.	ADDED (1) RELAY FOR DOOR RELEASE ON THE 3RD FL. FOR "SPI" PER FJ-64217.
20	7/17/96	L.G	ADDED (2) SMOKE DET. ON 3RD FL PER FJ-63094
19	6/14/96	L.G	ADDED (4) SPKR/STROBES TO EXISTING CKTS ON 3RD FL PER FJ-63044
18	4/18/96	LE	ADDED (5) SPKRS./STROBES TO EXIST. CKTS., (2) DUCT SMK. DETECTORS, (2) FAN SHUTDOWN & (1) AREA SMK. DETECTOR ON 3RD FL. PER FJ-62932.
17	3/9/95	TT	ADDED (6) STROBES ON 10TH FL PER FJ-61990-01
16	10/25/94	TT	ADDED STRB SYST-3 PANEL W/ASSOC. (7) SPEAKER/STRBS, (8) STRBS, (3) DUCT DET., (3) RELAY FOR FAN SHUTDOWN, (3) RELAY FOR DOOR RELEASE & (1) RELAY FOR DAMPER RELEASE ON 9TH FL., & (6) SPKR/STRB, (6) STRBS, (1) DUCT DET. (1) RELAY FOR FAN SHUTDOWN, (3) RELAYS FOR DOOR RELEASE & (1) RELAY FOR DAMP. RELEASE ON 10TH FL. PER FJ-61990
15	4/25/94	T.T.	ADDED (3) SPEAKERS AND (3) STROBES ON 8TH FLOOR AS PER FJ-61453
14	1/28/94	L.E	ADDED RELAYS TO DOOR RELEASE RISER ON 7TH & 8TH FLOORS AS PER FJ-61536
13	12/22/93	TT	REVISED PER AS BUILT
12	12/21/93	TT	ADDED AFC101 W/ASSOC 9 STROBES 5 SPKRS, 1 HEAT DET, 1 DUCT DETECTOR & 1 RELAY FOR FAN SHUTDOWN ON 8th FL. ADDED AFC101 W/ASSOC 14 STROBES, 9 SPKRS, SUB SYSTEM, MANUAL STATION, DUCT DET. FAN SHUTDOWN PER FJ 61453
11	1/4/93	BD	ADDED POWER SUPPLY & TTB RISER AS PER FJ-60844.
10	9/15/92	TS	ADDED DOOR RELEASE ON 3RD FL PER FJ-60710 (SALOMON BROTHERS INC.)
9	5/19/92	BD	ADDED DOOR RELEASE RELAY ON 5TH FL. PER FJ-60447-01
8	4/27/92	BD	ADDED WATERFLOW & TAMPER SWITCH NEW ZONE ON 5TH FL. PER FJ-60447.
7	6/10/91	BD	ADDED AFC-100, F/C, 6" T-BELL ON 6TH FL. AS PER FJ-29874.
6	01/16/91	BD	ADDED TTB, RELAY ON 5TH FL., ANSUL SYSTEM, PREACTION SYSTEM, RELAY (PURGE) ON 4TH FL. RELAY (PURGE) RELAY (PRESS) ON 3RD FL. RELAY (PURGE) ON THE 2ND FLOOR PER FJ-28829-16.
5	10 10 90	BD	ADDED 2 DET 1ST FL, 2 MS & 2 SPKR/STROBE 2ND FL, 1 MS & 19 SPKR/STROBE 36TH FL, 1 MS & 19 SPKR/STROBE 37TH FL. FJ 29247
4	6-21-90	BD	ADDED MANUAL STA, SMOKE DET ON NEW ZONE & SPKRS/STROBE TO EXISTING PANEL ON 4th FL PER FJ 29099
3	6-21-90	BD	ADDED DOOR RELEASE ON 3RD FL PER FJ 29353
~~2~~	~~4-4-90~~	~~JP~~	~~REVISED PER RETURN SUBMISSION~~
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER

NEW YORK, NEW YORK

1ST FL. — 10TH FL.

FIRE ALARM SYSTEM RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. JP
CKD.
DATE 9-6-89
SCALE

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-26840
DWG. E-504111-1
SHEET 1 OF 5
REV 23

WTCI-124-S



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A, B	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR # 16 TW
	A, B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1 PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DHI	840-76-SA	1 PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1 PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1 PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1 PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1 PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR # 20 TW/SH 1 PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20 TW, 1PR # 20 TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1 PR # 20 TW
	TS	TAMPER SWITCH			1 PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1 PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1 PR # 20 TW 1 PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR # 20 TW/SH, 1 PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
		FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1 PR # 16
	F/C	FUSE CUTOUT BOX			
		STROBE LIGHTS			
		REMOTE LAMP			
	AFC	AFC-100 PNL. TYPICAL 14TH FL THRU 18TH FL REFER DWG. C-505456			
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			
		COMB. SPKR./STROBE			

NOTE: FOR TENANT WIRING SPKRS & STROBES CONNECTION REFER TO DWG C-103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-13, 20,

REV.	DATE	BY	DESCRIPTION
18	11/5/97	CS	ADDED (1) DUCT SMOKE DET. & (1) RELAY FOR FAN SHUTDOWN ON 18TH FL. PER FJ-64087
17	12/9/96	T.T.	ADDED (2) SPEAKR-STROBES (1) DUCT SMOKE DETECTOR & (1) FAN SHUTDOWN ON 18TH FLOOR PER FJ-63401
16	6/24/96	L.E	ADDED (2) DUCT DETECTORS (2) RELAYS FOR FAN SHUTDOWN ON 20TH FL PER FJ-62063
15	5/6/96	L.G	ADDED (9) SPKR/STROBES (3) STROBE LIGHTS (1) RELAY FOR FAN SHUTDOWN (1) DUCT DET. (1) RELAY FOR DOOR REL. ON 19TH FL PER FJ-62947
14	8/2/95	L.G	ADDED (3) SPKR/STROBES (1) WATER FLOW ON 20TH FL PER FJ-63449
13	8/02/95	LE	DELETED (1) SPKR. & (1) STROBE ON 13TH FL. ADDED (1) SPKR./STROBE ON 13TH FLOOR PER FJ-62413-01 FOR S.E.C.
12	7/7/95	LE	ADDED (1) SPEAKER AND (1) STROBE TO EXISTING CIRCUIT ON 13TH FLOOR PER FJ-62413.
11	4/25/95	JD	ADDED (1) COMB-SPKR./STROBE AND (1) STROBE TO EXISTING CIRCUITS ON 13TH FLOOR PER FJ-62282.
10	6-14-93	JFR	ADDED DOOR RELEASE RELAY 18th Floor per FJ-60911-01
9	1-11-93	JFR	ADDED AFC-101 STROBE PNL W/ASSOC. (12) STROBE LIGHTS - ADDED (14) SPKRS TO EXISTING CKT ON 18TH FL. PER FJ-60911.
8	1-4-93	BD	ADDED TTB RISER AS PER FJ-60849.
7	9/23/92	BD	REVISED FJ-60656 PER RETURNED SUBMISSION.
6	9/3/92	BD	ADDED (2) AFC-101, 34 SPEAKER/STROBE, AREA DET & RELAY FOR DOOR RELEASE ON 11TH FLOOR. ADDED (2) AFC-101, 36 SPEAKER/STROBE, AREA DETECTOR, RELAY FOR DOOR RELEASE, DUCT DETECTOR, FAN SHUTDOWN & TTB EXTENDER ON 12TH FLOOR. ADDED AFC-101 (9) SPEAKER/STROBE, (2) DUCT DET. (2) FAN SHUTDOWN ON 13TH FLOOR PER FJ-60656.
5	9/30/91	BD	ADDED AREA DET. ON 18TH FL. FJ-60131.
4	8/22/91	BD	ADDED COMBINATION SPEAKER/STROBE (2) ON 19TH FL & (5) ON 20TH FL AS PER FJ-29865-03.
3	4/29/91	BD	ADDED FAN SHUTDOWN, DUCT DET., TTB, STROBE PNLS PER FJ 29865
2	11/09/90	B.D.	ADDED STR PNL, SPKRS/STROBES, FAN SHUTDOWN ON 14th THRU 18th FL, SUB-SYSTEM TO 14th FL PER FJ-29486
1		JP	REDRAWN/GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
11TH-20TH FL.

FIRE ALARM SYSTEM RISER DIAGRAM

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

DWN. SJ
APPVD.
ENGR. JP
CKD.
DATE 9-6-89
SCALE
JOB NO. FJ-26840
SHEET 2 OF 5
DWG E-504111-2
REV. 18



QTY	SYMBOL	DESCRIPTION	CAT. NO	BSA NO	WIRE SIZE
	A, B	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1PR #16 TW
	A, B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1PR #16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR #18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR #18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1PR #18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1PR #20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1PR #20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1PR #18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1PR #20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1PR #20 TW/SH 1PR #20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR #20 TW, 1PR #20 TW/SH 1PR #16 TW
	WF	WATERFLOW SWITCH			1PR #20 TW
	TS	TAMPER SWITCH			1PR #20 TW
	SS	SUB-SYSTEM	F.B.O.		1PR #20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR #16, 1PR #20 TW 1PR #20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1PR #20 TW/SH, 1PR #20 TW 3PR #22 TW/SH, 2PR #12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
		FAN CONTROL (START, STOP, STATUS)	F.B.O.		2PR #14 1PR #18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1PR #20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1PR #16
	F/C	FUSE CUTOUT BOX			
		STROBE LIGHTS			1PR #14
		COMB. SPKR./STROBE			1PR #14
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT WIRING SPKRS & STROBES CONNECTION REFER TO DWG C-103114

NOTE:
FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-23, 30, 24, 22,

REV.	DATE	BY	DESCRIPTION
33	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS 21ST & 26TH THRU 30 PER LJ-80208.
32	4/22/98	CS	ADDED (3) SPKR./STROBES ON THE 22ND FL., PER FJ-64400.
31	8/15/97	CS	ADDED (1) STROBE LIGHT ON 21ST FL. PER FJ-63964
30	7/22/97	CS	ADDED (4) SPEAKERS & (6) STROBES ON 25TH FL PER FJ-63887
29	5/20/97	T.T.	ADDED (1) SPKR/STROBE ON 21ST FL. PER FJ-63762
28	4/6/97	LE	ADDED (4) SPKRS./STROBES ON 21ST FLOOR PER FJ-63685 FOR 'SOLOMON BROS' (FBO).
27	4/7/97	CS	ADDED (1) RELAY FOR DOOR RELEASE ON 21ST FL PER FJ-63677
26	9/19/96	L.G	ADDED (1) SPKR ON 21ST FL PER FJ-63243
25	7/9/96	JD	ADDED (4) SPKR./STROBES, (4) STROBES, (2) SPEAKERS TO EXIST. CKT. ADDED (1) DUCT SMK. DET. (1) FAN SHUTDOWN & DOOR RELEASE ON 21ST FLR. FOR FIRST STATE MNGT. PER FJ-63102.
24	5/17/96	LE	ADDED (2) SPKR./STROBES, (2) STROBES ON 22ND FLOOR PER FJ-62997 FOR FEDERAL HOME.
23	3/27/96	TT	ADDED (2) COMB. SPKR/STRBS, (1) DUCT DET, (1) RELAY FOR FAN SHUTDOWN ON 21ST FLOOR AS PER FJ-62858
22	11/16/95	JD	ADDED PREACTION PANEL TBL. AND ALARM ON 26TH FLOOR PER AS BUILT.
21	11/10/95	JD	ADDED (2) STROBES ON 26TH & 27TH FL. PER FJ-62532-02.
20	11/2/95	JD	CHANGED WF & TS DESIG. TO PREACTION ALARM & TROUBLE RESP. PER FJ-62532-01.
19	10/19/95	JD	ADDED DUCT SMOKE DET. W/ASSOC. FAN START/STOP ON 26TH & 27TH FLOORS PER FJ-62532-01 FOR STD. CHARTERED BANK
18	9/12/95	JD	PER FJ-62532 26TH & 27TH FLOOR: ADDED STROBE PANEL WITH ASSOCIATED STROBE LIGHTS - ADDED SPEAKERS TO EXISTING CIRCUITS - ADDED MANUAL PULL STATION TO EXISTING ZONE - ADDED NEW ZONE FOR FAN SHUTDOWN - ADDED DOOR RELEASE - 27TH FLOOR: ADDED NEW ZONE FOR DUCT DETECTOR, FAN SHUTDOWN, WF & TAMPER SW, PREACT. PNL. ALM & TBL.
17	5/10/94	L.E.	ADDED PRE-ACTION PANEL ON 22ND FLOOR AS PER FJ-61655-01
16	4/24/94	L.E.	ADDED (2) STROBE PNL. W/ASSOC. (33) STROBES, (2) TROUBLE BELLS (2) FUSE CUT-OUT. ALSO ADDED (3) SMK. DUCT DETS., (3) FAN SHUTDOWN AND PRE-ACTION PANEL FOR ALARM & TBL. ON 22ND FL. PER FJ-61655
15	3/24/93	J.D.	ADDED (10) COMBINATION SPEAKERS/STROBES ON 28TH FLR. FOR SALOMON BROTHERS PER FJ-61296-03
14	11/2/93	LE	REPLACED (3) DUCT DETS WITH COMB. SMOKE/HEAT DET. ON 28TH FLR AS PER FJ-61296-04
13	8-31-93	AS	ADDED (6) COMB. SPKR/STROBES TO EXIST. CKTS - ADDED (4) DUCT SMK DET ON NEW ZONES & (1) RELAY FOR FAN START/STATUS/STOP PER FJ-61296 ON 28TH FL
12	1/4/93	BD	ADDED TTB RISER AS PER FJ-60844.
11	1/30/92	AS	ADDED (2) SMOKE DETECTOR ON 28TH FL PER FJ-60288.
10	8/22/91	BD	ADDED AREA DET. ON 21ST FL. AS PER FJ-29865-09
9	7/22/91	BD	ADDED (2) SUB-SYSTEM PRE-ACTION PANEL ON 28TH FL. AS PER FJ-29994.
8	4/26/91	BD	ADDED AFC-100, F/C, 6" T-BELL, 15 COMB. SPKR/STROBES ON 21ST FL. AS PER FJ-29865.
7	4/1/91	BD	ADDED 21 COMB. SPKR/STROBE ON THE 28TH FLOOR PER FJ-29814.
6	11-12-90	BD	ADDED PRE-ACTION SYST. ON 29TH FL THRU 32ND FL 34TH, 35TH FL, 38TH FL, THRU 47TH FL & 4TH FL PER FJ-28829
5	6-21-90	BD	ADDED 17 SPKRS/STROBE ON 30TH FL PER FJ 29099
4	6/21/90	BD	ADDED 17 SPEAKERS/STROBE ON 29TH FL PER FJ 29099
3	6-21-90	B.D	ADDED DOOR RELEASE ON 28TH FL PER FJ 29253
2	4-4-90	JP	REVISED PER RETURN SUBMISSION
1	10-27-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
21ST FL - 30TH FL.

FIRE ALARM SYSTEM
RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. JP
CKD.
DATE 9-6-89
SCALE

FIRECOM INCORPORATED
FIRE CONTROLS DIV.
COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-26840
DWG. E-504111-3
SHEET 3 OF 5
REV. 33

124-5



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A / B	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1PR # 16 TW
	A / B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DHI	840-76-SA	1PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1PR # 20 TW/SH 1PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20 TW, 1PR # 20 TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1PR # 20 TW
	TS	TAMPER SWITCH			1PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1PR # 20 TW 1PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1PR # 20 TW/SH, 1PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
	⊠	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1PR # 16
	F/C	FUSE CUTOUT BOX			
	⊗	STROBE LIGHTS			
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT WIRING OF SPKRS/STROBES CONNECTION REFER TO DWG 6-103114

NOTE:
FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-39, 37, 38, 40, 31, 32, 33, 36,

REV.	DATE	BY	DESCRIPTION
20	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS 34TH & 35TH PER LJ-80208.
19	5/28/97	TT	ADDED NEW AFC-102 STROBE PNL & (16) SPEAKER/STROBES ON 34TH FL. PER FJ-63788.
18	3/13/97	JD	ADDED CONNECTIONS FOR PRESSURIZATION/PURGE ON 39TH FL. PER AS BUILT.
17	12/5/94	JD	ADDED (2) SPKRS./STROBES TO EXIST. CKT. ON 37TH FLOOR PER FJ-62066.
16	8-31-93	AS	ADDED STROBE PANEL & 8-COMB/SPKR STROBES & 1-P.E. DETECTOR ON 34TH FLOOR AS PER FJ-61296 AND FJ-61296-02
15	9-17-90	B.D	ADDED 14 COMB/SPEAKERS/STR ON 38TH FL & 14 COMB/SPKRS/STR ON 39TH FL PER FJ-29485
14	7-9-90	BD	ADDED MANUAL STATION ON 36th, 37th FL PER FJ 29027
13	7-9-90	BD	ADDED 11 SPKS/STR ON 35TH FL PER FJ-29143
12	"	"	ADDED 25 SPKS/STROBE ON 34TH FL PER FJ-29098
11			
10	7-9-90	B.D	ADDED 19 SPKRS STROBES ON 36TH, 37TH FL PER FJ-29247
9	7-9-90	B.D	ADDED 14 SPKRS STROBES ON 40TH FL PER FJ-1247
8			
7	6-21-90	B.D	ADDED 20 SPEAKERS/STROBE ON 33RD FL PER FJ 29099
6	6-21-90	BD	ADDED 19 SPEAKERS/STROBE ON 31ST, 32ND, FLOOR PER FJ 29099
5	6-1-90	BD	CLASS "E" DOOR RELEASE RELAYS (PER DWG ER-7)
4	6-21-90	BD	ADDED DOOR RELEASE ON 32ND & 33RD FL PER FJ 24353
3	4-4-90	JP	REVISED PER RETURN SUBMISSION
2	1-17-90	JP	REVISED PER CONTRACT DWG C-340 ON 40TH FLR. PER FJ-29027
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
31ST FL - 40TH FL.

FIRE ALARM SYSTEM
RISER DIAGRAM

DWN.	SJ
APPVD	
ENGR.	JP
CKD	
DATE	9-6-89
SCALE	
JOB NO.	FJ-26840
SHEET	4 OF 5
DWG.	E-504111-4
REV	20

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

124-5



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A / B	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR #16 TW
	A / B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1PR #16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR #18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR #18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1PR #18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1PR #20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1PR #20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1PR #18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1PR #20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR #20 TW/SH 1 PR #20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR #20 TW, 1PR #20 TW/SH 1PR #16 TW
	WF	WATERFLOW SWITCH			1PR #20 TW
	TS	TAMPER SWITCH			1PR #20 TW
	SS	SUB-SYSTEM	F.B.O.		1PR #20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR #16, 1PR #20 TW 1PR #20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1PR #20 TW/SH, 1PR #20 TW 3PR #22 TW/SH, 2PR #12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
	⊠	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR #14 1 PR #18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR #20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1PR #16
	F/C	FUSE CUTOUT BOX			
	⊗	STROBE LIGHTS			
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT SPKRS, & STROBES CONNECTIONS REFER TO DWG C-103114

NOTE:
FOR CROSSED-OUT FLOORS SEE DWG #B-504111-47, 45, 41, 42, 43

REV.	DATE	BY	DESCRIPTION
18	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS: 44TH & 46TH PER LJ-80208.
17	1-15-98	CS	ADDED (1) MANUAL PULL STATION ON THE 47TH FL. FOR "SOLOMON BROTHERS", PER FJ-64222.
16	6/2/97	TT	ADDED (15) SPEAKER / STROBES & (2) MANUAL PULL STATIONS ON 47TH FLOOR PER FJ-63789.
15	3/13/97	JD	ADDED CONNECTIONS FOR PRESSURIZATION / PURGE ON 42ND FL. SHOWN CONNECTIONS FOR DAMPER CTL. ON 47TH FL. PER AS BUILT
14	02/25/97	C.S.	ADDED (1) SPEAKER STROBE ON 47TH FL. PER FJ-63574
13	7/24/96	JD	REVISED PER AS BUILT.
12	5/19/92	BD	ADDED COMB. SMOKE & HEAT DET. ON 41ST & 43RD FLOORS PER FJ-60493.
11	1-31-92	JFR	ADDED DOOR RELEASE RELAY ON 45TH FL. PER FJ-60271.
10	02/12/91	BD	REVISED A6 PER FJ-28829-20
9	9-10-90	BD	ADDED 18 COMB/SPKRS/STR. ON 46TH, 47TH FL. PER FJ-29483
8	9-10-90	B.D	ADDED AFC-100, COMB/SPKS/STROBES, MANUAL STA, SMK DET, ON 45TH FL PER FJ-29484
7	9-9-90		ADDED WARDEN STATION 41 & 42ND FL PER FJ-29027
6	7-9-90	BD.	ADDED 11 SPKS/STR ON 44TH FL PER FJ-29143
5	7-9-90	BD	ADDED 38 SPKS STR. ON 41ST FL. PER FJ-29027 " 14 " " ON 42ND " PER FJ- "
4	6-21-90	BD	ADDED DOOR RELEASE ON 42ND FL & 43RD FL PER FJ29353
3	4-4-90	JP	REVISED PER RETURN SUBMISSION
2	1-17-89	JP	REVISED PER CONTRACT DWG C-341-C-343 REV.1 ON 41ST & 43RD FL AND 42ND FL PER CONTRACT DWG C-342, PER FJ-29027
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER

NEW YORK, NEW YORK

41ST FL. – ROOF

FIRE ALARM SYSTEM RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. J P
CKD
DATE 9-6-89
SCALE

FIRECOM INCORPORATED
FIRE CONTROLS DIV.

JOB NO. FJ-26840

SHEET 5 OF 5

124-5